

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
3/07/2015	53 Yirrigan Dr Mirrabooka 6061 WA	Contaminated - remediation required	12/11/2018	Chlorinated hydrocarbons (such as from dry cleaning solvents) are present as a vapour in soil beneath the southern portion of the site and extending off-site to the south.
8/07/2015	32 Morgan St Rockingham 6168 WA	Report not substantiated	6/08/2015	No contamination has been identified in soil and groundwater beneath the site.
9/07/2015	303 Great Eastern Hwy Belmont 6104 WA	Remediated for restricted use	27/05/2020	Hydrocarbons (such as from petrol or diesel) are present in soil and groundwater beneath the site that extend off-site to the south-west.
10/07/2015	Lot 214 On Plan 1911 Bassendean 6054 WA	Possibly contaminated - investigation required	29/07/2015	Elevated concentrations of metals are present in industrial waste material used in historical fill at the site.
14/07/2015	28 Division St Welshpool 6106 WA	Possibly contaminated - investigation required	13/10/2015	Chlorinated hydrocarbons such as trichloroethane are present in groundwater beneath the site.
15/07/2015	8 Clayton St (excluding Subject A) Midland 6056 WA	Decontaminated	14/10/2019	Following remediation, no significant contamination remains at the site.
15/07/2015	8 Clayton St (Subject A) Midland 6056 WA	Remediated for restricted use	14/10/2019	Asbestos containing material (ACM), asbestos fines, metals (copper, lead, nickel, zinc) and hydrocarbons (such as from diesel or oil) are present in soils across the site beneath a warning barrier and layer of clean fill capping. An asbestos containment cell (total area 2,280m ²) containing friable asbestos waste, ACM, asbestos fines and metals is present beneath the central portion of the site. Metals (cadmium, chromium, copper, nickel, lead and zinc), pathogens and nutrient contaminated groundwater is present beneath the site.
17/07/2015	289 Patstone Rd Collie 6225 WA	Report not substantiated	13/08/2015	No contamination has been identified.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
20/07/2015	Tom Price Mine, Mining Lease ML45A Mount Sheila 6751 WA	Possibly contaminated - investigation required	2/05/2017	<p>Hydrocarbons (such as from petrol or diesel) are present in soils and groundwater beneath a light-vehicle refuelling facility and a former bulk fuel storage facility at the site. Solvents have also been detected in groundwater beneath the light-vehicle refuelling facility.</p> <p>Groundwater at the site has been impacted by acid and metalliferous drainage, as a result of mine pit excavation and dewatering. Low pH, sulfate and metals (aluminium, arsenic, cadmium, cobalt, copper, iron, manganese, nickel, mercury and zinc) are present in groundwater in areas close to the South-East Prongs, Section Six and Central Pits.</p> <p>Low pH, sulfate and metals (aluminium, copper, iron, manganese, nickel, cobalt, selenium and zinc) are present in surface water in the pit lakes of the South-East Prongs, Section Six Pit and Central Pits.</p>
22/07/2015	Lot 13 St George Ranges 6728 WA	Possibly contaminated - investigation required	1/09/2015	This site has been used for the disposal of liquid wastes including grease and sewage. However, no contamination investigations have been carried out and the quality of soil and groundwater at the site is unknown.
24/07/2015	3134 Marine Tce West End 6530 WA	Not contaminated - unrestricted use	30/11/2017	Investigations found that no contamination is present in soil at the site.
29/07/2015	2351 Albany Hwy Gosnells 6110 WA	Decontaminated	12/12/2022	Following remediation at the adjacent property to the north-west, no known contamination remains at the site.
29/07/2015	104 Chester Pass Rd Yakamia 6330 WA	Remediated for restricted use	17/07/2019	Petroleum hydrocarbons (such as from petrol and diesel) are present in groundwater beneath the former fuel depot located at 107 Chester Pass Road, Milpara, which extends as a plume in a south-easterly direction beneath this site.
5/08/2015	372 Grand Prom Dianella 6059 WA	Possibly contaminated - investigation required	9/09/2015	Hydrocarbons (such as from petrol) are present in groundwater.
5/08/2015	106 Ranford Rd Canning Vale 6155 WA	Contaminated - restricted use	1/02/2017	Hydrocarbons (such as from petrol or diesel) are present in groundwater beneath the site.
5/08/2015	12052 Gladstone Av Swan View 6056 WA	Decontaminated	20/10/2016	Following remediation, no contamination remains at the site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
6/08/2015	274 Erindale Rd Warwick 6024 WA	Decontaminated	23/10/2018	Following remediation, no contamination is present at the site.
12/08/2015	171 Todd St Merredin 6415 WA	Report not substantiated	26/09/2018	No contamination has been identified.
12/08/2015	12797 Columbus Bvd Wandina 6530 WA	Remediated for restricted use	29/09/2015	Hydrocarbons (such as from transformer oil) remain in soil at depths greater than 1.5 metres below the electrical transformer located in the south-western corner of the site.
12/08/2015	169 Railway Pde Boyup Brook 6244 WA	Possibly contaminated - investigation required	10/09/2015	Pathogens (such as E.coli and Enterococci) are present in groundwater onsite and potentially offsite.
17/08/2015	9745 Barlee Way Beechboro 6063 WA	Decontaminated	19/01/2018	Following remediation, no contamination remains at the site.
19/08/2015	595 Robinson St Kingsford 6701 WA	Possibly contaminated - investigation required	2/09/2015	Hydrocarbons (such as from petrol or diesel) have been detected in soil and groundwater at the site.
24/08/2015	Lot 4158 On Plan 137148 Kingston 6256 WA	Report not substantiated	6/10/2015	Limited surface staining by hydrocarbons (such as from petrol, diesel or oil) have been identified at isolated locations across the site.
24/08/2015	588 Simcock Rd Chowerup 6244 WA	Report not substantiated	6/10/2015	Limited surface staining by hydrocarbons (such as from petrol, diesel or oil) has been identified at isolated locations across the site.
31/08/2015	84 Dore St Katanning 6317 WA	Remediated for restricted use	13/04/2017	Hydrocarbons (such as from petrol and diesel) are present in soil beneath the site.
31/08/2015	36 Morgans St Ravensthorpe 6346 WA	Remediated for restricted use	27/03/2017	Hydrocarbons (such as from diesel) are present in soils beneath the central portion of the site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
31/08/2015	1287 Crooks Rd Merredin 6415 WA	Not contaminated - unrestricted use	28/02/2018	Investigations found that no contamination is present at the site.
31/08/2015	2 Gabo Ave Merredin 6415 WA	Not contaminated - unrestricted use	28/02/2018	Investigations found that no contamination is present at the site.
31/08/2015	2 Seymour Ave Shenton Park 6008 WA	Decontaminated	28/03/2019	Following remediation, no contamination remains at the site.
1/09/2015	1 Capital Rd Malaga 6090 WA	Remediated for restricted use	8/03/2021	Hydrocarbon contamination (such as from petrol) is present in groundwater beneath the south-western corner of the site.
9/09/2015	32 Dulwich St Bennett Springs 6063 WA	Report not substantiated	30/09/2015	No contamination has been identified.
10/09/2015	Lot 12 Kwinana Beach Road Kwinana Beach 6167 WA	Contaminated - remediation required	20/10/2015	Petroleum hydrocarbons, i.e. pure diesel, are present in soil and groundwater in the south-western portion of the site.
11/09/2015	Mining Tenement M15/1793 Bullabulling 6429 WA	Possibly contaminated - investigation required	29/09/2015	A breach in the wall of a historic tailings dam has occurred on this site. However, no contamination investigations have been carried out and the quality of soil and groundwater at the site is unknown.
11/09/2015	Mining Tenement M38/236 Laverton 6440 WA	Possibly contaminated - investigation required	13/10/2015	A breach in the wall of a historic tailings dam is reported to have occurred on this site. However, no contamination investigations have been carried out and the quality of soil and groundwater at the site is unknown.
14/09/2015	332 Cockram Rd Lennard Brook 6503 WA	Possibly contaminated - investigation required	30/10/2019	This portion of the abattoir site contains holding pens for livestock and is subject to irrigation with treated wastewater. Nutrients (nitrogen and phosphorus) have been identified in groundwater. Nutrients have also been detected in soil, but it is unclear whether the concentrations detected exceed background conditions.
15/09/2015	Armstrong Rd Wilson 6107 WA	Decontaminated	6/01/2021	No contamination remains at this site.
22/09/2015	26 Davis St Boulder 6432 WA	Possibly contaminated - investigation required	20/10/2015	Hydrocarbons (such as from petrol or diesel) have been identified in soils associated with the underground petroleum storage system.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
23/09/2015	435 Chittleborough Rd Brookton 6306 WA	Possibly contaminated - investigation required	26/10/2016	Screening residue from a municipal (putrescible) waste composting plant has been buried on site. No investigations of potential contamination have been undertaken at the site and the extent of potential contamination is unknown.
9/10/2015	107 Harbour Rd (Lots A, B & C) South Carnarvon 6701 WA	Remediated for restricted use	8/06/2017	Soil beneath Lots A, B, C and E is impacted by metals (copper and zinc) and hydrocarbons (such as from waste oil). Groundwater beneath Lots A, B, C and E is impacted by metals (copper and zinc), hydrocarbons (such as from waste oil) and nutrients (nitrate).
9/10/2015	107 Harbour Rd (Lot E) South Carnarvon 6701 WA	Remediated for restricted use	8/06/2017	Soil beneath Lots A, B, C and E is impacted by metals (copper and zinc) and hydrocarbons (such as from waste oil). Groundwater beneath Lots A, B, C and E is impacted by metals (copper and zinc), hydrocarbons (such as from waste oil) and nutrients (nitrate).
14/10/2015	76 Ashley Rd Tapping 6065 WA	Decontaminated	22/02/2019	Following remediation, no contamination is present at the site.
19/10/2015	Lot 82 Toodyay Rd Parkerville 6081 WA	Possibly contaminated - investigation required	2/12/2015	Groundwater beneath this site has been impacted by landfill leachate and contains elevated concentrations of metals and nutrients.
19/10/2015	Lot 11664 Toodyay Rd Parkerville 6081 WA	Possibly contaminated - investigation required	2/12/2015	Groundwater beneath this site has been impacted by landfill leachate and contains elevated concentrations of metals and nutrients.
20/10/2015	107 Clayton St Bellevue 6056 WA	Possibly contaminated - investigation required	24/11/2015	Hydrocarbon contaminated groundwater (such as from petrol and diesel) is present beneath the adjacent former service station site, including light non-aqueous phase liquid (LNAPL) and the fuel additive methyl tertiary-butyl ether (MTBE), and is likely to extend beneath this site (the road reserve).
20/10/2015	109 Clayton St Bellevue 6056 WA	Possibly contaminated - investigation required	24/11/2015	Hydrocarbon contaminated groundwater (such as from petrol and diesel) is present beneath the adjacent former service station site, including light non-aqueous phase liquid (LNAPL) and the fuel additive methyl tertiary-butyl ether (MTBE), and is likely to extend beneath this site (the road reserve).
22/10/2015	480 Hay St Perth 6000 WA	Remediated for restricted use	10/08/2017	Perfluoroalkyl and polyfluoroalkyl substances (PFAS) (such as from fire-fighting foams) are present in groundwater beneath the site.
22/10/2015	Lot 3501 Falcon Rd Wellington Forest 6236 WA	Possibly contaminated - investigation required	15/12/2015	Hydrocarbons (such as from diesel or oil) remain present in soils beneath the former transformer and spillway and in surface waters of the adjacent settlement dam.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
26/10/2015	20 Heydon Pl Cue 6640 WA	Decontaminated	8/09/2016	Following remediation no contamination remains at the site.
26/10/2015	45 Griffith St Sandstone 6639 WA	Decontaminated	28/06/2016	Following remediation no contamination remains at the site.
27/10/2015	37 Jarvis St South Bunbury 6230 WA	Possibly contaminated - investigation required	26/11/2020	The site has been used as a landfill site for the disposal of municipal wastes and fly-tipping has occurred. The extent of the landfill material requires further characterisation. Asbestos-impacted fill is buried below the site. Soil and groundwater quality at the site has not been investigated.
2/11/2015	14 Wittenberg Dr Canning Vale 6155 WA	Remediated for restricted use	16/11/2015	The site is currently used as a lead assay laboratory and has undergone remediation focused on lead contaminated soil in the base of two drainage soak wells. All lead contaminated soil has been successfully remediated.
2/11/2015	Pia Wadjari Remote Aboriginal Community South Murchison 6635 WA	Possibly contaminated - investigation required	27/01/2016	Hydrocarbons (such as diesel) are present in soils to a depth of 2 metres below ground level, in the vicinity of the diesel generator, in the south eastern portion of the site.
9/11/2015	750 Campbell Rd Gibson 6448 WA	Report not substantiated	17/12/2015	No contamination has been identified.
12/11/2015	Pippingarra Station Pippingarra 6722 WA	Possibly contaminated - investigation required	1/12/2015	Unauthorised disposal of wastes, including asbestos-containing material, has occurred on this site. No contamination investigations have been carried out and the nature of potential contamination at the site is unknown.
12/11/2015	Crown Reserve 25833 Hindmarsh 6462	Not contaminated - unrestricted use	9/06/2016	Investigations found that no contamination is present at the site.
13/11/2015	206 Hampton Rd Northampton 6535 WA	Classification timeframe extended under s.14(1)(b)		
16/11/2015	214 Hampton Rd Northampton 6535 WA	Classification timeframe extended under s.14(1)(b)		
17/11/2015	1 Murray St Perth 6000 WA	Remediated for restricted use	10/08/2017	Perfluoroalkyl and polyfluoroalkyl substances (PFAS) (such as from fire-fighting foams) are present in groundwater beneath the site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
23/11/2015	Lot 143 Munjina-Wittenoom Rd Mulga Downs 6751 WA	Possibly contaminated - investigation required	8/06/2016	Hydrocarbons (such as from diesel or oil) are present in the soils of the site in the area used as a landfill.
25/11/2015	Mining Tenement M38/261 Laverton 6440	Possibly contaminated - investigation required	15/12/2015	Hydrocarbons (such as from petrol/oil/diesel) may be present in the decommissioned bioremediation pad.
26/11/2015	549 Third Avenue Onslow 6710 WA	Contaminated - restricted use	17/05/2016	Hydrocarbons (such as from diesel/oil) are present in soil beneath the north-west portion of the site and are present in groundwater beneath the western portion of the site.
26/11/2015	550 Beadon Creek Rd Onslow 6710 WA	Possibly contaminated - investigation required	29/12/2015	Hydrocarbons (such as from petrol or solvents) are present in groundwater beneath the centre of the site. Hydrocarbons (such as from diesel) are present in groundwater beneath the former power station located to the south of this site and extend beneath the southern portion of the site.
27/11/2015	Crown Reserve 8606 Karlkurla 6430 WA	Remediated for restricted use	22/03/2021	The elevated portion of the site contains historical landfill material beneath a landfill cap with an approximate depth of one-metre. Asbestos containing material (ACM) and landfill gases are present beneath the landfill capping comprising sand and clay layers.
30/11/2015	Merolia Rd Laverton 6440 WA	Possibly contaminated - investigation required	15/12/2015	Hydrocarbons (such as from petrol/oil/diesel) may be present in the decommissioned bioremediation pad.
30/11/2015	Mining Tenement M38/101 Laverton 6440	Possibly contaminated - investigation required	15/12/2015	Hydrocarbons (such as from petrol/oil/diesel) may be present in the decommissioned bioremediation pad.
1/12/2015	Crown Reserve 10009 Merredin 6415 WA	Not contaminated - unrestricted use	5/04/2018	No contamination has been identified or found in soil and groundwater at the site.
2/12/2015	118 Briggs St Welshpool 6106 WA	Not contaminated - unrestricted use	5/04/2017	Following investigation, no contamination has been found.
4/12/2015	210 Hampton Rd Northampton 6535 WA	Classification timeframe extended under s.14(1)(b)		
4/12/2015	1 Archer St Carlisle 6101 WA	Contaminated - remediation required	11/05/2007	A dissolved hydrocarbon plume extends from the source parcel of the Site (166 Rutland Ave, Carlisle) to the northwest. The plume extends beneath Archer St, 3 Archer St, 1 Archer St, Rutland Ave, the Railway Reserve and East Vic Park Primary School.
4/12/2015	30 Beatty Ave Carlisle 6101 WA	Contaminated - remediation required	11/05/2007	A dissolved hydrocarbon plume extends from the source parcel of the Site (166 Rutland Ave, Carlisle) to the northwest. The plume extends beneath Archer St, 3 Archer St, 1 Archer St, Rutland Ave, the Railway Reserve and East Vic Park Primary School.
4/12/2015	166 Rutland Av Carlisle 6101 WA	Contaminated - remediation required	11/05/2007	A dissolved hydrocarbon plume extends from the source parcel of the Site (166 Rutland Ave, Carlisle) to the northwest. The plume extends beneath Archer St, 3 Archer St, 1 Archer St, Rutland Ave, the Railway Reserve and East Vic Park Primary School.
4/12/2015	3 Archer St Carlisle 6101 WA	Contaminated - remediation required	11/05/2007	A dissolved hydrocarbon plume extends from the source parcel of the Site (166 Rutland Ave, Carlisle) to the northwest. The plume extends beneath Archer St, 3 Archer St, 1 Archer St, Rutland Ave, the Railway Reserve and East Vic Park Primary School.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
4/12/2015	Archer St road reserve Carlisle 6101 WA	Contaminated - remediation required	11/05/2007	A dissolved hydrocarbon plume extends from the source parcel of the Site (166 Rutland Ave, Carlisle) to the northwest. The plume extends beneath Archer St, 3 Archer St, 1 Archer St, Rutland Ave, the Railway Reserve and East Vic Park Primary School.
4/12/2015	Railway Reserve Carlisle 6101 WA	Contaminated - remediation required	11/05/2007	A dissolved hydrocarbon plume extends from the source parcel of the Site (166 Rutland Ave, Carlisle) to the northwest. The plume extends beneath Archer St, 3 Archer St, 1 Archer St, Rutland Ave, the Railway Reserve and East Vic Park Primary School.
4/12/2015	Beatty Avenue road reserve Carlisle 6101	Report not substantiated	18/01/2016	No contamination has been identified.
8/12/2015	166 Rutland Av Carlisle 6101 WA	Contaminated - remediation required	11/05/2007	A dissolved hydrocarbon plume extends from the source parcel of the Site (166 Rutland Ave, Carlisle) to the northwest. The plume extends beneath Archer St, 3 Archer St, 1 Archer St, Rutland Ave, the Railway Reserve and East Vic Park Primary School.
10/12/2015	105 Wilson St Port Hedland 6721 WA	Possibly contaminated - investigation required	20/05/2021	Per-and poly-fluoroalkyl substances (PFAS) (such as from fire-fighting foams/ PFAS-containing waste) and hydrocarbons (such as from petrol, diesel and oil) are present in groundwater beneath the site. Further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.
15/12/2015	205 Somers Rd Wagerup 6215 WA	Contaminated - remediation required	12/06/2008	Alkalinity and a heavy metal are present in surface water and groundwater at elevated concentrations extending across the Site. Total dissolved solids are present at in groundwater at elevated concentrations extending across the Site. Metals are present in surface water at elevated concentrations towards the south-west, and the centre of the Site. A non-metallic halogen is present in surface water at elevated concentrations towards the south-west of the Site.
15/12/2015	275 Baldivis Rd Baldivis 6171 WA	Decontaminated	7/07/2017	Following remediation, no contamination remains at the site.
17/12/2015	299 Victoria Rd Malaga 6090 WA	Possibly contaminated - investigation required	20/01/2016	Hydrocarbons (such as from petrol/oil/diesel) may be present in soil and groundwater.
17/12/2015	105 Wilson St Port Hedland 6721 WA	Possibly contaminated - investigation required	20/05/2021	Per-and poly-fluoroalkyl substances (PFAS) (such as from fire-fighting foams/ PFAS-containing waste) and hydrocarbons (such as from petrol, diesel and oil) are present in groundwater beneath the site. Further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
21/12/2015	Peel Terrace Northam 6401 WA	Contaminated - restricted use	20/10/2022	Hydrocarbons (such as from petrol or diesel) are present in groundwater beneath adjacent land which extends to the north to beneath this the site.
23/12/2015	744 Burnside Rd Burnside 6285 WA	Report not substantiated	27/04/2016	No contamination has been identified.
29/12/2015	208 Hampton Rd Northampton 6535 WA	Classification timeframe extended under s.14(1)(b)		
29/12/2015	84 Serpentine Rd Albany 6330 WA	Possibly contaminated - investigation required	9/09/2020	Chlorinated organic compounds (such as chlorinated solvents and their degradation products) are present in groundwater and as vapour in soil beneath the site.
29/12/2015	Forrest Location 88 Pippingarra 6722 WA	Report not substantiated	27/01/2016	No contamination has been identified.
30/12/2015	Yannery Tank Site Maitland 6714 WA	Possibly contaminated - investigation required	9/02/2016	Fragments of potential asbestos containing materials are present in soils at the site.
7/01/2016	564 Village Rd Burrup 6714 WA	Possibly contaminated - investigation required	17/02/2016	Following remediation, residual contamination remains in soil beneath infrastructure at the site. All potential contaminants at the site have not been investigated and the nature and extent of contamination in soil and groundwater is unknown. Metals impacts are present in groundwater beneath the site.
14/01/2016	174A Claisebrook Rd Perth 6000 WA	Contaminated - remediation required	27/01/2016	Chlorinated hydrocarbons (such as from drycleaning solvents) are present in soil and as a vapour within a stormwater drain at the site and a connected drain sump in the adjacent road reserve.
14/01/2016	174A Claisebrook Rd Perth 6000 WA	Contaminated - remediation required	27/01/2016	Chlorinated hydrocarbons (such as from drycleaning solvents) are present in soil and as a vapour within a stormwater drain at the site and a connected drain sump in the adjacent road reserve.
29/01/2016	5 Margerison St Manjimup 6258 WA	Possibly contaminated - investigation required	16/08/2016	Hydrocarbons (such as from diesel and/or petrol) are present in near surface soils adjacent to the fuel gantry and to the southern side of fuel bowzers which extend to the water table at approximately 16 metres below ground level. Hydrocarbons (such as from petrol) are present in groundwater beneath the site and are likely to extend to the west beneath the road reserve.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
2/02/2016	18 Price St Denmark 6333 WA	Report not substantiated	15/03/2016	No contamination has been identified.
3/02/2016	Lot 533 On Plan 73704 Roebuck 6725 WA	Possibly contaminated - investigation required	24/02/2016	Unauthorised disposal of wastes has occurred at the south-east portion of the site. However, no contamination investigations have been carried out and the quality of soil and groundwater at the site is unknown.
3/02/2016	35 Dairy Link Mardella 6125 WA	Not contaminated - unrestricted use	2/08/2016	Investigations found that no contamination is present in soil at the site.
4/02/2016	1 Brearley Av Redcliffe 6104 WA	Possibly contaminated - investigation required	13/07/2016	Polyfluorinated compounds (such as from fire-fighting foams) have been detected in groundwater beneath the site.
9/02/2016	Heydon Pl Cue 6640 WA	Not contaminated - unrestricted use	8/09/2016	Investigations found that no contamination is present in soil or groundwater at the site.
9/02/2016	Reserve 21629 Dunsborough 6281 WA	Remediated for restricted use	20/04/2021	Buried waste from historical landfilling, likely including asbestos-containing material (ACM), is present beneath a capping layer of revegetated clean fill and mulch at the site.
12/02/2016	2 Ward Rd East Rockingham 6168 WA	Not contaminated - unrestricted use	19/07/2016	Investigations found that no contamination is present in soil or groundwater at the site relating to site operations.
12/02/2016	2 Hamersley St Djugun 6725 WA	Remediated for restricted use	16/12/2019	Hydrocarbons (such as from petrol or diesel) are present in groundwater beneath the site.
12/02/2016	1391 Great Northern Hwy Upper Swan 6069 WA	Possibly contaminated - investigation required	13/07/2016	The fuel additive methyl tertiary-butyl ether is present in groundwater beneath the adjacent service station and extends to the north beneath this site.
22/02/2016	Reserve 30188 Marine Reserve 5 WA	Report not substantiated	4/08/2016	No contamination has been identified.
25/02/2016	51 Healy Rd Hamilton Hill 6163 WA	Decontaminated	7/08/2017	Following remediation, no contamination remains at the site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
29/02/2016	92 Gardiner St Moora 6510 WA	Remediated for restricted use	21/01/2020	Hydrocarbon contaminated groundwater (such as from petrol) is present beneath the adjacent service station (the source site) and extends beneath this site. Chlorinated hydrocarbons were identified in groundwater beneath an access road (an affected site) located immediately south of the service station. Chlorinated hydrocarbons were not detected beneath other parcels of land at concentrations above non-potable groundwater use criteria.
29/02/2016	Findlater St road reserve Moora 6510 WA	Remediated for restricted use	21/01/2020	Hydrocarbon contaminated groundwater (such as from petrol) is present beneath the adjacent service station (the source site) and extends beneath this site. Chlorinated hydrocarbons were identified in groundwater beneath an access road (an affected site) located immediately south of the service station. Chlorinated hydrocarbons were not detected beneath other parcels of land at concentrations above non-potable groundwater use criteria.
29/02/2016	88 Gardiner St Moora 6510 WA	Remediated for restricted use	18/12/2019	Hydrocarbon contaminated groundwater (such as from petrol) is present beneath the adjacent service station (the source site), and extends beneath this site. Chlorinated hydrocarbons were identified in groundwater beneath an access road immediately south of the service station and is not likely to be present beneath this site at concentrations above non-potable groundwater use criteria.
29/02/2016	Kintail Rd Applecross 6153 WA	Contaminated - remediation required	18/09/2017	Hydrocarbon contaminated groundwater (such as from petrol and diesel) is present beneath the adjacent service station (the source site), and is likely to extend beneath the adjacent road reserve to the north (this parcel).
3/03/2016	213 Smith Rd Beverley 6304 WA	Not contaminated - unrestricted use	18/01/2017	A test pit investigation found that no contamination is present in soil at the site.
9/03/2016	401 Waterview Pde Ascot 6104 WA	Possibly contaminated - investigation required	24/03/2016	Perfluorinated substances (such as from fire-fighting foams) have been detected in surface water at the site.
11/03/2016	Crown Reserve 5275 Bunbury 6230 WA	Remediated for restricted use	21/01/2021	Mineral sands tailings containing elevated levels of radionuclides were historically deposited at the site. On the northern portion of the site, mineral sands tailings remain present beneath a layer of uncontaminated soil of 0.5 metres thickness. On the southern portion of the site, mineral sands tailings remain present beneath a layer of uncontaminated soil of variable thickness.
15/03/2016	92 Gardiner St Moora 6510 WA	Remediated for restricted use	21/01/2020	Hydrocarbon contaminated groundwater (such as from petrol) is present beneath the adjacent service station (the source site) and extends beneath this site. Chlorinated hydrocarbons were identified in groundwater beneath an access road (an affected site) located immediately south of the service station. Chlorinated hydrocarbons were not detected beneath other parcels of land at concentrations above non-potable groundwater use criteria.
16/03/2016	Reserve State Forest 32, Baudin 6284 WA	Contaminated - restricted use	2/02/2018	Hydrocarbons and metals (arsenic, barium, total chromium, copper, lead, nickel and zinc) are present in soils at the site.
17/03/2016	43 Astley St Gosnells 6110 WA	Classification timeframe extended under s.14(1)(b)		

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
23/03/2016	528 Abernethy Rd Kewdale Kewdale WA	Remediated for restricted use	21/01/2015	Asbestos-containing materials (ACM) are present in soils at the site. Metals and hydrocarbons (such as from diesel or oil) are present in soils at the site. Groundwater beneath the site is impacted with hydrocarbons (such as from diesel).
23/03/2016	Lot 800 on DP 67654, Bayswater 6053 WA	Classification timeframe extended under s.14(1)(b)		
29/03/2016	16 Coulson Way Canning Vale 6155 WA	Remediated for restricted use	15/02/2017	Hydrocarbons (such as from petrol) and phthalates (such as from resins) remain present in groundwater beneath the site.
31/03/2016	Solomon Mine Kings Ore Processing Facility Mount Shelia 6751 WA	Report not substantiated	26/04/2016	No contamination has been identified at levels that pose a risk to human health, the environment or any environmental values under the current landuse.
31/03/2016	Lot 10 Railway Parade, Bayswater 6053 WA	Remediated for restricted use	22/04/2021	Groundwater beneath the site has been contaminated by nearby historical industrial activities, including the burial of cinder waste on off-site land to the north-east. Groundwater contamination is characterised by elevated levels of acidity, metals (such as aluminium and iron), fluoride and nutrients (such as ammonia).
31/03/2016	501 Scarborough Beach Rd Osborne Park 6017 WA	Decontaminated	29/07/2021	Following remediation, no contamination remains at the site.
31/03/2016	Road Reserves Scarborough Beach Rd Osborne Park 6017 WA	Decontaminated	29/07/2021	Following remediation, no contamination remains at the site.
31/03/2016	4 Minilya Cr Dampier 6713 WA	Decontaminated	2/06/2016	Following remediation, no contamination remains at the site.
1/04/2016	Reserve 8231, Mount Palmer 6426 WA	Contaminated - remediation required	19/05/2017	Fibrous asbestos has been identified across the site. Benzo(a)pyrene has been identified in isolated locations across the site
1/04/2016	Reserve 8232, Lot 74 On Plan 215769, Wallaroo 6429 WA	Contaminated - remediation required	25/08/2016	Uncontrolled waste material, including friable and fibrous asbestos material, is present in soils at the site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
1/04/2016	206 Dundas Rd High Wycombe 6057 WA	Classification timeframe extended under s.14(1)(b)		
7/04/2016	41 Austin St Cue 6640 WA	Possibly contaminated - investigation required	11/05/2016	Hydrocarbons (such as from diesel and oil) are present in the soils of the site. Hydrocarbons (such as from diesel) are present in the groundwater at the site.
11/04/2016	Pinjarra Rd Barragup 6210 WA	Remediated for restricted use	29/11/2016	Hydrocarbon contaminated groundwater (such as from petrol and diesel) is present beneath the adjacent former service station (the source site), and extends beneath the road reserve.
11/04/2016	Burslem Dr Maddington 6109 WA	Remediated for restricted use	9/08/2018	Hydrocarbon contaminated groundwater (such as from petrol) from the adjacent service station has historically been identified in groundwater beneath this site. Recent monitoring suggests concentrations are below relevant guideline levels. However, further monitoring is required to confirm concentrations remain below acceptable levels. Per-and poly-fluoroalkyl substances (PFAS) (such as from fire-fighting foams) are present in groundwater beneath the adjacent service station site extending beneath this site. Groundwater monitoring suggests concentrations are below relevant guideline levels however continued monitoring is required to confirm concentrations remain below acceptable levels.
11/04/2016	39 Austin St Cue 6640 WA	Possibly contaminated - investigation required	11/05/2016	Hydrocarbons (such as from Diesel or oil) are found in and on the groundwater.
14/04/2016	34 Davison St Maddington 6109 WA	Possibly contaminated - investigation required	10/05/2016	Impacts to soil were visually identified at the site.
14/04/2016	286 Kalamunda Rd Maida Vale 6057 WA	Decontaminated	25/05/2016	Localised hydrocarbon (such as diesel) impacts are present in soil beneath the site.
19/04/2016	Reserve 20514, Lot 28767 On Plan 215762, Barbalin 6479 WA	Possibly contaminated - investigation required	10/06/2016	Asbestos and hydrocarbons (such as from tar or creosote) are present in soils north of the dam at the site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
26/04/2016	Road Reserves adjacent to Lots 156 & 157, Bibra Lake 6163 WA	Contaminated - restricted use	4/05/2016	Landfill gases including methane, carbon dioxide and hydrogen sulfide are being generated from waste material buried beneath adjacent land and have the potential to migrate beneath this site and accumulate in subsurface voids.
2/05/2016	Crown Reserve 47148, Boodarie 6722 WA	Possibly contaminated - investigation required	30/05/2016	Fragments of potential asbestos containing materials are present in soils at the site.
3/05/2016	12 Claughton Way Glen Iris 6230 WA	Contaminated - restricted use	29/01/2019	Hydrocarbons (such as from petrol) are present in groundwater beneath the eastern portion of the site.
9/05/2016	Johnston St Collie 6225 WA	Not contaminated - unrestricted use	31/05/2018	Investigations found that no significant contamination is present in soil or groundwater at the site.
9/05/2016	Lot 314 Price Street, Reserve 15040, Kellerberrin 6410 WA	Possibly contaminated - investigation required	2/06/2016	Asbestos fragments were visually identified on surface soil surrounding the location of stored asbestos coated pipes at the site.
9/05/2016	Crown Reserve 2804, Nullagie 6758 WA	Possibly contaminated - investigation required	22/06/2016	The site is used as a landfill for the disposal of degradable wastes as well as industrial mining waste. No contamination investigations have been carried out and the quality of soil and groundwater at the site is unknown.
9/05/2016	57 Johnston St Collie 6225 WA	Contaminated - restricted use	18/04/2017	Hydrocarbons (such as petrol or diesel) are present in groundwater beneath the northern portion of the site.
13/05/2016	23 Office Rd Kwinana Beach 6167 WA	Contaminated - restricted use	11/02/2021	Nutrients are present in groundwater beneath the site.
18/05/2016	Lot 883 on Deposited Plan 402083, Onslow 6710 WA	Decontaminated	18/08/2016	Following remediation, no contamination remains at the site.
19/05/2016	29 Felspar St Narrogin 6312 WA	Decontaminated	19/07/2019	Following remediation, no contamination has been identified at that site that poses a risk or potential risk to human health, the environment and/or any environment values.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
19/05/2016	53 Cheltenham St Bennett Springs 6063 WA	Report not substantiated	28/06/2016	No contamination has been identified.
20/05/2016	1 Brearley Av Redcliffe 6104 WA	Possibly contaminated - investigation required	13/07/2016	Polyfluorinated compounds (such as from fire-fighting foams) have been detected in groundwater beneath the site.
20/05/2016	Forrestfield Airport Link, Lot 506 and Lot 75, Bayswater 6053 WA	Possibly contaminated - investigation required	22/06/2016	Perfluorinated alkyl substances (such as from fire-fighting foams) have been detected in surface water at the site.
20/05/2016	76 Guildford Rd Mount Lawley 6050 WA	Possibly contaminated - investigation required	21/09/2016	Hydrocarbon contaminated groundwater (such as from petrol and diesel) is present beneath the adjacent service station (the source site), and extends beneath this site.
20/05/2016	78 Guildford Rd Mount Lawley 6050 WA	Possibly contaminated - investigation required	21/09/2016	Hydrocarbon contaminated groundwater (such as from petrol and diesel) is present beneath the adjacent service station (the source site), and extends beneath this site.
24/05/2016	37 Kitchener Rd Merredin 6415 WA	Contaminated - remediation required	1/07/2016	Asbestos impacted soil is present in the south central portion of the site.
27/05/2016	51 Farrington Rd Leeming 6149 WA	Remediated for restricted use	20/07/2021	Hydrocarbons (such as from petrol or diesel) are present in groundwater as a plume beneath the site, extending from beneath an adjacent service station.
30/05/2016	Lot 501, Crown Reserve 50851, Mount Hardman 6765 WA	Remediated for restricted use	8/11/2016	Following remediation, hydrocarbons (such as from diesel) remain in soils near power station infrastructure at depths between 1 and 2.5 metres below ground level.
3/06/2016	30 Dyson St South Perth 6151 WA	Remediated for restricted use	15/10/2020	Hydrocarbons (such as from petrol and diesel) are present in groundwater beneath the site.
8/06/2016	LOT 11322 ON PLAN 183298 Kalbarri 6536 WA	Not contaminated - unrestricted use	10/06/2021	Investigations found that no contamination is present in soil or groundwater at the site.
8/06/2016	Lot 501 on Deposited Plan 63523, Buillabulling 6429 WA	Possibly contaminated - investigation required	21/06/2016	Hydrocarbons (such as from oil) and fragments of asbestos-containing material were visually observed in surface soils.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
9/06/2016	Lot 8942 Croydon St, Bellevue 6056 WA	Remediated for restricted use	18/09/2018	Asbestos is present in soil below a textile barrier at the 0.5 metre depth.
13/06/2016	42 Ledger Rd Gooseberry Hill 6076 WA	Remediated for restricted use	30/05/2008	Fragments of Asbestos Containing Materials are present in five burial pits within the centre of the Site under 300mm of topsoil and mulch.
13/06/2016	24 Ledger Rd Gooseberry Hill 6076 WA	Remediated for restricted use	29/10/2018	The site has been remediated but ongoing management of unexpected finds of potential asbestos-containing material in near-surface soils is required.
17/06/2016	20 Lemnos St Shenton Park 6008 WA	Contaminated - remediation required	2/11/2016	Fragments of asbestos-containing materials and metals (such as copper, lead, nickel and zinc), associated with the historical disposal of waste, are present in surface soils in the north-east corner of the site.
19/06/2016	78 Guildford Rd Mount Lawley 6050 WA	Possibly contaminated - investigation required	21/09/2016	Hydrocarbon contaminated groundwater (such as from petrol and diesel) is present beneath the adjacent service station (the source site), and extends beneath this site.
21/06/2016	10 Nockolds St Walpole 6398 WA	Remediated for restricted use	29/12/2016	Hydrocarbons (such as petrol or diesel) are present in soil beneath the northern and north eastern portions of the site at a depth of between 3 and 3.5 metres below ground level. Hydrocarbons (such as petrol or diesel) are present in groundwater beneath the northern and north western portions of the site.
21/06/2016	Lot 415 North West Coastal Highway, Inggarda 6701 WA	Report not substantiated	19/07/2016	No contamination has been identified
24/06/2016	62 Roe Rd Capel 6271 WA	Decontaminated	9/05/2017	Following remediation, no contamination remains at the site
27/06/2016	Section of Marble Bar road reserve, Newman 6753 WA	Remediated for restricted use	24/01/2017	Hydrocarbons (such as from oil) are present in shallow soils adjacent to the bitumen road surface on the western side of Marble Bar Road.
27/06/2016	Part Reserve 38991, Fortescue 6716 WA	Possibly contaminated - investigation required	26/07/2016	Fragments of potential asbestos-containing materials are present in soils at the site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
28/06/2016	104 Chester Pass Rd Yakamia 6330 WA	Remediated for restricted use	17/07/2019	Petroleum hydrocarbons (such as from petrol and diesel) are present in groundwater beneath the former fuel depot located at 107 Chester Pass Road, Milpara, which extends as a plume in a south-easterly direction beneath this site.
28/06/2016	4 Hudson Rd Yakamia 6330 WA	Remediated for restricted use	17/07/2019	Petroleum hydrocarbons (such as from petrol and diesel) are present in groundwater beneath the former fuel depot located at 107 Chester Pass Road, Milpara, which extends as a plume in a south-easterly direction beneath this site.
28/06/2016	100 Chester Pass Rd Yakamia 6330 WA	Remediated for restricted use	17/07/2019	Petroleum hydrocarbons (such as from petrol and diesel) are present in groundwater beneath the former fuel depot located at 107 Chester Pass Road, Milpara, which extends as a plume in a south-easterly direction beneath this site.
28/06/2016	3 Leonora Rd Yakamia 6330 WA	Remediated for restricted use	17/07/2019	Petroleum hydrocarbons (such as from petrol and diesel) are present in groundwater beneath the former fuel depot located at 107 Chester Pass Road, Milpara, which extends as a plume in a south-easterly direction beneath this site.
28/06/2016	5 Leonora Rd Yakamia 6330 WA	Remediated for restricted use	17/07/2019	Petroleum hydrocarbons (such as from petrol and diesel) are present in groundwater beneath the former fuel depot located at 107 Chester Pass Road, Milpara, which extends as a plume in a south-easterly direction beneath this site.
30/06/2016	Subject B on DP 402546, 115 Port Rd, Kwinana Beach 6167 WA	Contaminated - remediation required	28/09/2022	Nutrients (such as from fertilisers) are present in soil and groundwater beneath the site which discharges to Cockburn Sound.
1/07/2016	3 Pearse St Wyndham 6740 WA	Decontaminated	7/02/2018	Following remediation, no contamination remains at the site.
1/07/2016	6 Pearse St Wyndham 6740 WA	Decontaminated	20/11/2018	Following remediation, no contamination remains at the site.
1/07/2016	Pearse St road reserve Wyndham 6740	Decontaminated	20/11/2018	Following remediation, no contamination remains at the site.
1/07/2016	18 Bellows St Welshpool 6106 WA	Decontaminated	30/10/2018	Following remediation, no contamination remains at the site.
6/07/2016	9 Broadley Pl Gosnells 6110 WA	Possibly contaminated - investigation required	11/08/2016	Visual evidence of hydrocarbon soil staining at various locations across the site.
7/07/2016	621 Wanneroo Rd, Wanneroo 6065 WA	Remediated for restricted use	26/08/2020	Hydrocarbon impacted groundwater (such as from petrol) is present beneath the adjacent service station site and is likely to be present beneath the northern portion of this site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
11/07/2016	Richards St Manjimup 6228 WA	Possibly contaminated - investigation required	16/08/2016	Hydrocarbons (such as from petrol) are present in groundwater beneath the adjacent fuel depot and are likely to extend to the west beneath the road reserve.
20/07/2016	Lot 1586 on Plan 72986, Exmouth Gulf 6707 WA	Possibly contaminated - investigation required	31/08/2016	Hydrocarbons (such as from oil), are suspected to be present in soils adjacent to oil and gas production infrastructure.
25/07/2016	Hay Street East Perth 6004 WA	Possibly contaminated - investigation required	1/09/2016	Heavy metal impacted soil is present in on-site soils.
25/07/2016	11 Suffolk St Fremantle 6160 WA	Report not substantiated	31/08/2016	No contamination has been identified.
26/07/2016	Subject A on DP 418046, Golf Club Road, Wadderin 6369 WA	Remediated for restricted use	14/12/2021	Asbestos-containing material may be present in soil within the waterfilled reservoir.
26/07/2016	46 Shenton St Menzies 6436 WA	Contaminated - restricted use	25/08/2016	Hydrocarbons (such as from diesel fuel) are present in soils and groundwater at the site.
28/07/2016	22 Wellington St Centennial Park 6330 WA	Remediated for restricted use	18/07/2019	Dissolved-phase hydrocarbons (such as from petrol) are present in groundwater beneath the site.
28/07/2016	229 Albany Hwy Mount Melville 6330 WA	Possibly contaminated - investigation required	8/02/2018	Dissolved-phase hydrocarbons (such as from petrol) are present in groundwater beneath the site.
29/07/2016	100 Skippers Row, Bayswater 6053 WA	Not contaminated - unrestricted use	14/09/2017	Investigations found that no contamination is present in soil and groundwater at the site.
1/08/2016	77 Lakes Rd Hazelmere 6055 WA	Decontaminated	15/11/2019	Following remediation, no contamination is present at the site.
3/08/2016	Mining Tenement P15/4829, Bullabulling 6429 WA	Report not substantiated	30/08/2016	No contamination has been identified.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
3/08/2016	Hepburn St Mount Magnet 6638 WA	Contaminated - remediation required	30/08/2016	Phase separated hydrocarbons (such as pure petrol or diesel) are floating on the surface of the groundwater beneath the site.
4/08/2016	300 Benara Rd Morley 6062 WA	Remediated for restricted use	9/01/2018	Hydrocarbons (such as from petrol and diesel) are present in groundwater beneath the site and are potentially present in soils within the groundwater smear zone at a depth of 2 to 3.5 metres below ground level.
5/08/2016	521 Dundas Rd Forrestfield 6058 WA	Contaminated - remediation required	13/12/2017	Perfluoroalkyl and polyfluoroalkyl substances (PFAS) derived from fire-fighting foams are present in groundwater beneath the site.
9/08/2016	77-81 Prizmic Street, Beeliar 6164 WA	Decontaminated	16/01/2018	Following remediation, no contamination remains at the site.
9/08/2016	23A Redgum Way Morley 6062 WA	Not contaminated - unrestricted use	21/10/2020	Investigations found that no contamination is present in soil or groundwater at the site.
9/08/2016	300 Benara Rd Morley 6062 WA	Remediated for restricted use	9/01/2018	Hydrocarbons (such as from petrol and diesel) are present in groundwater beneath the site and are potentially present in soils within the groundwater smear zone at a depth of 2 to 3.5 metres below ground level.
16/08/2016	77 Uduc Rd Harvey 6220 WA	Possibly contaminated - investigation required	8/09/2016	Hydrocarbons (such as from petrol and diesel) are present in soils beneath the site.
18/08/2016	50 Wallington Rd Balga 6061 WA	Remediated for restricted use	4/08/2021	Asbestos is present at depths greater than 0.3 metres beneath a surface cover (of either turf, mulch, swale or hardstand), clean fill material and a geotextile warning barrier.
18/08/2016	81 Uduc Rd Harvey 6220 WA	Possibly contaminated - investigation required	8/09/2016	Hydrocarbons (such as from petrol and diesel) are present in soils beneath the site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
22/08/2016	Guildford Rd Mount Lawley 6050 WA	Possibly contaminated - investigation required	21/09/2016	Hydrocarbon contaminated groundwater (such as from petrol) is present beneath the adjacent service station site and extends beneath this road reserve.
23/08/2016	Murray St Perth 6000 WA	Not contaminated - unrestricted use	3/10/2017	Investigations found that no contamination is present in soil beneath the site.
25/08/2016	Russell Rd Success 6164 WA	Remediated for restricted use	27/09/2016	Asbestos-impacted soil and asbestos-containing material is buried in a containment cell beneath this site. The containment cell is present immediately below a geotextile warning barrier at approximately at 0.5 metre depth.
29/08/2016	264 Ewen St Woodlands 6018 WA	Remediated for restricted use	7/03/2018	Total petroleum hydrocarbons are present in groundwater beneath the site.
29/08/2016	262 Ewen St Woodlands 6018 WA	Remediated for restricted use	7/03/2018	Total petroleum hydrocarbons are present in groundwater beneath the site.
29/08/2016	260 Ewen St Woodlands 6018 WA	Remediated for restricted use	7/03/2018	Total petroleum hydrocarbons are present in groundwater beneath the site.
5/09/2016	39 Nelson Av East Perth 6004 WA	Classification timeframe extended under s.14(1)(b)		
5/09/2016	521 Dundas Rd Forrestfield 6058 WA	Contaminated - remediation required	13/12/2017	Perfluoroalkyl and polyfluoroalkyl substances (PFAS) derived from fire-fighting foams are present in groundwater beneath the site.
5/09/2016	337 Cambridge St Wembley 6014 WA	Remediated for restricted use	11/12/2017	Hydrocarbons (such as from petrol/diesel) are likely to be present in soils beneath the site across the zone of seasonal groundwater fluctuations and capillary fringe. Hydrocarbons (such as from petrol/diesel) are present in groundwater beneath the site and extend off-site to the south west. Volatile organic compounds (such as from solvents or petrol) are present in soil vapour beneath the site.
5/09/2016	Road Reserve at the junction of Cambridge Street and Jersey Street, Wembley 6014 WA	Remediated for restricted use	11/12/2017	Hydrocarbons (such as from petrol/diesel) are present in groundwater beneath the adjacent service station as a plume that extends to beneath this site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
5/09/2016	339 Cambridge St Wembley 6014 WA	Decontaminated	11/12/2017	No contamination remains at the site.
5/09/2016	341 Cambridge St Wembley 6014 WA	Decontaminated	11/12/2017	No contamination remains at the site.
6/09/2016	3 Hopetoun Pl Welshpool 6106 WA	Decontaminated	2/11/2017	Following remediation, no contamination remains at the site.
6/09/2016	Lots 504 & 505 on Plan 61268, Merredin 6415 WA	Possibly contaminated - investigation required	11/10/2016	Polycyclic aromatic cyclic hydrocarbons and friable asbestos fragments have been identified in soil in the north-west portion of the site. No groundwater investigations have been undertaken.
9/09/2016	20 Ridge Hill Rd Maida Vale 6057 WA	Possibly contaminated - investigation required	4/10/2016	Historic waste materials, including asbestos and elevated levels of nutrients may be present in soil and or groundwater.
11/09/2016	24 Harold St Dianella 6059 WA	Remediated for restricted use	30/04/2018	Asbestos-impacted soils have been remediated to a standard suitable for commercial/industrial landuse.
11/09/2016	25 Cleveland St Dianella 6059 WA	Remediated for restricted use	30/04/2018	Asbestos-impacted soils have been remediated to a standard suitable for commercial/industrial landuse.
12/09/2016	Lot 10 Brand Highway, Eneabba 6518 WA	Possibly contaminated - investigation required	5/05/2022	Radium 226, 228, thorium 228 and sulphate contamination of groundwater at site. Possible residual TPH contamination of soil.
12/09/2016	Road Reserves off Brand Highway, Eneabba 6518 WA	Possibly contaminated - investigation required	5/05/2022	Radium 226, 228, thorium 228 and sulphate contamination of groundwater at site. Possible residual TPH contamination of soil.
13/09/2016	2824 Clementson St Minyirr 6725 WA	Possibly contaminated - investigation required	12/07/2019	Elevated concentrations of nutrients are present in groundwater beneath the site. Suspected asbestos containing material has been visually identified at some locations on the site.
13/09/2016	605 Clementson St Minyirr 6725 WA	Possibly contaminated - investigation required	10/10/2016	Suspected asbestos containing material has been visually identified at some locations on the site.
15/09/2016	125 Radium St Welshpool 6106 WA	Remediated for restricted use	25/08/2022	Elevated concentrations of hydrocarbons (such as from petrol or diesel) are present in groundwater beneath the site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
21/09/2016	Lots 30 & 31 on Plan 174407, Higginsville 6443 WA	Possibly contaminated - investigation required	19/10/2016	Suspected asbestos containing materials (ACM) have been identified in surface soils.
23/09/2016	Lot 8864 Croydon St, Bellevue 6056 WA	Decontaminated	18/09/2018	Following remediation, no contamination is present at the site.
23/09/2016	150 Vivian St South Boulder 6432 WA	Remediated for restricted use	7/06/2017	Following remediation, asbestos-containing material remains present in soils beneath the site.
23/09/2016	150 Vivian St South Boulder 6432 WA	Remediated for restricted use	7/06/2017	Following remediation, asbestos-containing material remains present in soils beneath the site.
27/09/2016	339 Cambridge St Wembley 6014 WA	Decontaminated	11/12/2017	No contamination remains at the site.
28/09/2016	Lot 133 on Plan 18248, Bassendean 6054 WA	Possibly contaminated - investigation required	17/10/2017	Metals (arsenic, aluminium, iron and zinc), ammonia and phosphorous are present in groundwater beneath land to the north of this site and along the northern boundary of the site.
3/10/2016	15 Palmer Cr Davenport 6230 WA	Remediated for restricted use	11/11/2020	Hydrocarbons (such as from petrol or diesel) are present in soil in the eastern portion of the site at a depth of 1.2m metres below ground level. Hydrocarbons (such as from diesel) are present in groundwater beneath the eastern portion of the site.
4/10/2016	5 Hutton St Osborne Park 6017 WA	Remediated for restricted use	19/07/2019	Hydrocarbons (such as from petrol) are present in groundwater beneath a nearby service station at 7 (Lot 152) Hutton Street, Osborne Park and extend to the south-west beneath this site.
10/10/2016	264 Ewen St Woodlands 6018 WA	Remediated for restricted use	7/03/2018	Total petroleum hydrocarbons are present in groundwater beneath the site.
11/10/2016	17 Cayenne St Wattle Grove 6107 WA	Report not substantiated	22/11/2016	No contamination has been identified.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
25/10/2016	12894 Black Point Rd Lake Jasper 6260 WA	Possibly contaminated - investigation required	15/11/2016	The site has been used as a landfill for the disposal of agricultural wastes including animal carcasses and chemical containers which are partially buried. Soil and groundwater quality has not been investigated.
26/10/2016	Lot 1598 Degruessa Road, Gibson 6448 WA	Possibly contaminated - investigation required	22/11/2016	The site has been used as a landfill site for the disposal of waste. The quality of soil and groundwater at the site has not been investigated.
31/10/2016	110 Chapman Rd Geraldton 6530 WA	Remediated for restricted use	25/01/2017	Hydrocarbons (such as oil) are present in soil beneath the site.
4/11/2016	32 Heath Rd Kalamunda 6076 WA	Report not substantiated	13/12/2016	No contamination has been identified.
4/11/2016	24 East Tce Kalamunda 6076 WA	Possibly contaminated - investigation required	13/12/2016	Anecdotal evidence suggests the site has been used for the burial and dumping of waste. However, no contamination investigations have been carried out and the quality of soil and groundwater at the site is unknown.
4/11/2016	Lot 80 on Plan 29203, Kalamunda 6076 WA	Report not substantiated	13/12/2016	No contamination has been identified.
8/11/2016	16 Fewster St Mucchea 6501 WA	Report not substantiated	13/12/2016	No contamination has been identified.
14/11/2016	2131 West Swan Rd Caversham 6055 WA	Possibly contaminated - investigation required	9/12/2016	Hydrocarbons (such as from petrol and diesel) are present in soil and groundwater beneath the site.
17/11/2016	located within Lot 12725 on Deposited Plan 40610, Coolcalalaya 6532 WA	Decontaminated	10/06/2020	Following remediation, no contamination remains at the site.
24/11/2016	Lot 86 Buttweid Rd, Pippingarra 6722 WA	Possibly contaminated - investigation required	29/12/2016	Soils at the site contain petroleum hydrocarbons such as from engine oil. Several areas of potential hydrocarbon contamination were visually identified on surface soil across the site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
28/11/2016	Lot 141 on Deposited Plan 220774, Wallaroo 6429 WA	Possibly contaminated - investigation required	4/01/2017	Unauthorised disposal of wastes has occurred on this site. The quality of soil and groundwater at the site has not been investigated.
28/11/2016	Lot 145 on Deposited Plan 220774, Wallaroo 6429 WA	Possibly contaminated - investigation required	4/01/2017	Unauthorised disposal of wastes has occurred on this site. The quality of soil and groundwater at the site has not been investigated.
29/11/2016	2 Barker St Bedford 6052 WA	Remediated for restricted use	9/10/2018	Petroleum hydrocarbons are present in groundwater beneath the former service station at 168 Walter Road, Bedford and extend to the south and south-west beneath this site.
29/11/2016	Barker St road reserve Bedford 6052 WA	Remediated for restricted use	9/10/2018	Petroleum hydrocarbons are present in groundwater beneath the former service station at 168 Walter Road, Bedford and extend to the south and south-west beneath this site.
30/11/2016	Kintail Rd Applecross 6153 WA	Contaminated - remediation required	18/09/2017	Hydrocarbon contaminated groundwater (such as from petrol and diesel) is present beneath the adjacent service station (the source site), and is likely to extend beneath the adjacent road reserve to the north (this parcel).
30/11/2016	Canning Beach Rd Applecross 6153 WA	Contaminated - remediation required	18/09/2017	Hydrocarbon contaminated groundwater (such as from petrol and diesel) is present beneath the adjacent service station (the source site), and has been found to extend beneath adjacent road reserves to the east and south (these parcels).
30/11/2016	LOT 508 ON PLAN 57802, Geraldton 6530 WA	Remediated for restricted use	29/06/2018	Hydrocarbons (such as from petrol or diesel) are present in groundwater beneath the southern portion of the site.
1/12/2016	16969 Albany Hwy Arthur River 6315 WA	Contaminated - remediation required	12/01/2017	Hydrocarbons (such as from degraded leaded petrol and diesel) and metals (copper and nickel) are present in soil and groundwater beneath the site. Hydrocarbon-contaminated groundwater extends off-site to the west-south-west.
1/12/2016	Lot 2 and road reserve adjacent to 16969 Albany Hwy, Arthur River 6315 WA	Possibly contaminated - investigation required	12/01/2017	Hydrocarbons (such as from degraded leaded petrol and diesel) are present in groundwater beneath a former service station and extend beneath this site.
2/12/2016	36 Surrey St Dianella 6059 WA	Remediated for restricted use	18/04/2017	Asbestos-containing material is present in soil within the south-eastern and south-western embankments on the site and in the north-east corner of this site.
2/12/2016	14 L Pope St Two Rocks 6037 WA	Possibly contaminated - investigation required	3/03/2017	Soils at the site are impacted with hydrocarbons (such as from oils) and asbestos. Marine sediments at the site are impacted with tributyltin

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
5/12/2016	18 Balfour St South Kalgoorlie 6430 WA	Remediated for restricted use	8/08/2019	Volatile organic vapour (such as from drycleaning solvents) was identified in sub-surface soils at the site.
5/12/2016	20 Balfour St South Kalgoorlie 6430 WA	Remediated for restricted use	8/08/2019	Volatile organic vapour (such as from drycleaning solvents) was identified in sub-surface soils at the site.
5/12/2016	6 Miller St Wedgfield 6721 WA	Contaminated - remediation required	4/01/2017	Fragments of asbestos-containing material are present in soils of the site.
5/12/2016	LOT 1182 ON PLAN 221070, Perth 6000 WA	Classification timeframe extended under s.14(1)(b)		
5/12/2016	500 Kookynie-malcolm Rd Leonora 6438 WA	Not contaminated - unrestricted use	15/08/2018	Investigations have found that no contaminants are present at the site.
6/12/2016	Great Eastern Hwy Ghooli 6426 WA	Contaminated - remediation required	31/03/2021	Unauthorised disposal of asbestos-containing material (ACM) has occurred on this site.
6/12/2016	Reserve 24441, Mount Palmer 6426 WA	Classification timeframe extended under s.14(1)(b)		
6/12/2016	Crown Reserve 8229, cnr Great Eastern Highway and Smyth Road Carrabin 6423 WA	Contaminated - remediation required	20/09/2016	Uncontrolled waste material, including friable and fibrous asbestos material, is present in soils at the site.
8/12/2016	Lot 9 Lake Grace-Newdegate Road, Beenong 6353 WA	Decontaminated	9/11/2017	Following remediation no contamination was found to be present in soil at the site
9/12/2016	244 Nanarup Rd Kalgan 6330 WA	Report not substantiated	10/01/2017	No contamination has been identified

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
13/12/2016	Lot 210 on Plan 34336, Widgiemooltha 6443 WA	Possibly contaminated - investigation required	27/02/2020	<p>Based on visual observations, soils at various locations on the site are impacted by hydrocarbons, such as from petrol, diesel or oil.</p> <p>Parts of the site are used for the storage and processing of sulfidic mineral ores, concentrates and tailings, which have the potential to release acidity and/or metals into the environment.</p> <p>Parts of the site have historically been used for landfill and have received wastes of unknown composition.</p>
13/12/2016	Lot 211 on Plan 34336, Widgiemooltha 6443 WA	Possibly contaminated - investigation required	27/02/2020	<p>Based on visual observations, soils at various locations on the site are impacted by hydrocarbons, such as from petrol, diesel or oil.</p> <p>Parts of the site are used for the storage and processing of sulfidic mineral ores, concentrates and tailings, which have the potential to release acidity and/or metals into the environment.</p> <p>Parts of the site have historically been used for landfill and have received wastes of unknown composition.</p>
13/12/2016	Lot 98 on Plan 238373, Widgiemooltha 6443 WA	Possibly contaminated - investigation required	27/02/2020	<p>Based on visual observations, soils at various locations on the site are impacted by hydrocarbons, such as from petrol, diesel or oil.</p> <p>Parts of the site are used for the storage and processing of sulfidic mineral ores, concentrates and tailings, which have the potential to release acidity and/or metals into the environment.</p> <p>Parts of the site have historically been used for landfill and have received wastes of unknown composition.</p>
13/12/2016	Timber Reserve 199/25, Widgiemooltha 6443 WA	Possibly contaminated - investigation required	27/02/2020	<p>Based on visual observations, soils at various locations on the site are impacted by hydrocarbons, such as from petrol, diesel or oil.</p> <p>Parts of the site are used for the storage and processing of sulfidic mineral ores, concentrates and tailings, which have the potential to release acidity and/or metals into the environment.</p> <p>Parts of the site have historically been used for landfill and have received wastes of unknown composition.</p>
13/12/2016	Mining Tenement M15/1516, Widgiemooltha 6443 WA	Decontaminated	27/02/2020	Following remediation, no contamination remains at the site.
13/12/2016	Mining Tenement M15/95 Widgiemooltha 6443 WA	Possibly contaminated - investigation required	27/02/2020	<p>Based on visual observations, soils at various locations on the site are impacted by hydrocarbons, such as from petrol, diesel or oil.</p> <p>Parts of the site are used for the storage and processing of sulfidic mineral ores, concentrates and tailings, which have the potential to release acidity and/or metals into the environment.</p> <p>Parts of the site have historically been used for landfill and have received wastes of unknown composition.</p>

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
14/12/2016	39 Rendezvous Rd Vasse 6280 WA	Contaminated - remediation required	29/07/2020	<p>The site has been used as a landfill site for the disposal of degradable wastes, including domestic and industrial wastes.</p> <p>Metals, aromatic hydrocarbons (benzene), chlorinated hydrocarbons (such as from solvents and their breakdown products) and per-and poly-fluoroalkyl substances (PFAS) (such as from PFAS-containing waste) are present in groundwater beneath the site, and as a plume which extends off-site to the north north-west.</p> <p>Landfill gases including methane, carbon dioxide and hydrogen sulphide (such as from the decomposition of buried wastes) are present beneath the site.</p>
14/12/2016	130 Rendezvous Rd Vasse 6280 WA	Possibly contaminated - investigation required	26/03/2018	A plume of metals, aromatic hydrocarbons (benzene) and chlorinated hydrocarbons (such as from solvents and their breakdown products) in groundwater has migrated in a north north-westerly direction from the waste facility to the south and is likely to extend to beneath this site.
15/12/2016	Reserve 38279, Pithara 6608 WA	Possibly contaminated - investigation required	10/01/2017	Fragments of Asbestos containing material are present in soils at the site.
16/12/2016	5 Malvolio Rd Coolbellup 6163 WA	Report not substantiated	2/02/2017	No contamination has been identified.
16/12/2016	60 Mather Dr Neerabup 6031 WA	Decontaminated	19/01/2018	Following remediation, no contamination remains at the site.
16/12/2016	4610 Phillips Rd Mundaring 6073 WA	Decontaminated	8/06/2017	Following remediation, no contamination remains at the site
20/12/2016	496 Marmion St Booragoon 6154 WA	Possibly contaminated - investigation required	19/08/2020	<p>Chlorinated hydrocarbons (such as from dry cleaning solvents) are present in surface soil and soil vapour adjacent to or beneath Unit 1, and in sediment and water within a soakwell at the rear of Unit 1.</p> <p>Volatile organic compounds (such as solvents) are present as a plume in groundwater beneath adjacent properties to the south-east which extends beneath this site.</p>
20/12/2016	10 Clayton Rd Narrogin 6312 WA	Remediated for restricted use	17/02/2021	Light non-aqueous phase liquid (LNAPL) (e.g. pure diesel) is present in groundwater beneath the site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
21/12/2016	Lot 59, 372 Grand Promenade Road, Dianella 6059 WA	Report not substantiated	25/01/2017	No contamination has been identified.
21/12/2016	20 Dan Cl Walliston 6076 WA	Report not substantiated	31/01/2017	No contamination has been identified.
22/12/2016	111 Rawlinson St O'Connor 6163 WA	Not contaminated - unrestricted use	4/04/2017	Investigations found that no contamination is present in soil at the site.
28/12/2016	2884 Pemberton Way Karratha Industrial Estate 6714 WA	Decontaminated	31/01/2017	Following remediation, no contamination remains at the site.
4/01/2017	41 Moore Rd Herne Hill 6056 WA	Possibly contaminated - investigation required	5/01/2021	This site appears to have been used historically for the disposal of solid wastes, including asbestos-containing material.
9/01/2017	Part of Lot 208 On Plan 238219, Indee, 6721 WA	Decontaminated	23/07/2018	Following remediation, no contamination remains at the site.
9/01/2017	Part of De Grey Location 8, Crown Reserve 18938, Newman 6753 WA	Report not substantiated	30/03/2017	A portion of the site is used as a landfill for the disposal of mine site waste. No contamination investigations have been submitted to the Department of Environment Regulation and the quality of soil and groundwater at the site is unknown.
9/01/2017	Part of Lot 1500 On Plan 68275, Nullagine 6758 WA	Report not substantiated	2/08/2018	No contamination has been identified.
9/01/2017	Part of Lot 347 On Plan 55942, Marble Bar 6760 WA	Possibly contaminated - investigation required	30/03/2017	A portion of the site is used as a landfill for the disposal of putrescible waste. No contamination investigations have been submitted to the Department of Environment Regulation and the quality of soil and groundwater at the site is unknown.
11/01/2017	250 A (Lot 1)Ewen St Woodlands 6018 WA	Remediated for restricted use	7/03/2018	Total petroleum hydrocarbons are present in groundwater beneath the site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
11/01/2017	250 A (Lot 2)Ewen St Woodlands 6018 WA	Remediated for restricted use	7/03/2018	Total petroleum hydrocarbons are present in groundwater beneath the site.
11/01/2017	250 A (Lot 3)Ewen St Woodlands 6018 WA	Remediated for restricted use	7/03/2018	Total petroleum hydrocarbons are present in groundwater beneath the site.
11/01/2017	250 A (Lot 4)Ewen St Woodlands 6018 WA	Remediated for restricted use	7/03/2018	Total petroleum hydrocarbons are present in groundwater beneath the site.
11/01/2017	3 Bowra Ave (Lot 1) Woodlands 6018 WA	Remediated for restricted use	7/03/2018	Total petroleum hydrocarbons are present in groundwater beneath the site.
11/01/2017	3 Bowra Ave (Lot 2) Woodlands 6018 WA	Remediated for restricted use	7/03/2018	Total petroleum hydrocarbons are present in groundwater beneath the site.
11/01/2017	3 Bowra Ave (Lot 3) Woodlands 6018 WA	Remediated for restricted use	7/03/2018	Total petroleum hydrocarbons are present in groundwater beneath the site.
11/01/2017	3 Bowra Ave (Lot 4) Woodlands 6018 WA	Remediated for restricted use	7/03/2018	Total petroleum hydrocarbons are present in groundwater beneath the site.
11/01/2017	3 Bowra Ave (Lot 5) Woodlands 6018 WA	Remediated for restricted use	7/03/2018	Total petroleum hydrocarbons are present in groundwater beneath the site.
11/01/2017	3 Bowra Ave (Lot 6) Woodlands 6018 WA	Remediated for restricted use	7/03/2018	Total petroleum hydrocarbons are present in groundwater beneath the site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
11/01/2017	3 Bowra Ave (Lot 8) Woodlands 6018 WA	Remediated for restricted use	7/03/2018	Total petroleum hydrocarbons are present in groundwater beneath the site.
11/01/2017	252 (Lot 1) Ewen St Woodlands 6018 WA	Remediated for restricted use	7/03/2018	Total petroleum hydrocarbons are present in groundwater beneath the site.
11/01/2017	252 (Lot 2) Ewen St Woodlands 6018 WA	Remediated for restricted use	7/03/2018	Total petroleum hydrocarbons are present in groundwater beneath the site.
12/01/2017	15 Williams St Kalamunda 6076 WA	Decontaminated	4/01/2023	Following remedial works, no contamination remains across the site.
18/01/2017	2 Poinsettia Way Dianella 6059 WA	Decontaminated	8/06/2017	Prior to demolition of the building, small amounts of asbestos-containing material were identified on site. Following demolition no asbestos products have been identified on site.
18/01/2017	M15/645, Coolgardie 6429 WA	Contaminated - remediation required	4/09/2018	Soil surrounding a building footprint located in the central portion of the mining tenement is impacted by asbestos-containing material. Groundwater beneath the site is impacted by cyanide and arsenic.
23/01/2017	2 Hope Rd North Lake 6163 WA	Report not substantiated	1/03/2017	No contamination has been identified.
24/01/2017	304 Mount Rd Mount Magnet 6638 WA	Possibly contaminated - investigation required	29/03/2017	Petroleum hydrocarbons (such as from diesel or oil) have been observed in soil and groundwater beneath the site. Various waste materials have been buried within the on-site putrescible landfill. The quality of soil and groundwater at the site has not been investigated.
27/01/2017	7 Bowra Ave Woodlands 6018 WA	Remediated for restricted use	7/03/2018	Total petroleum hydrocarbons are present in groundwater beneath the site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
27/01/2017	9 Bowra Ave Woodlands 6018 WA	Remediated for restricted use	7/03/2018	Total petroleum hydrocarbons are present in groundwater beneath the site.
1/02/2017	304 Mount Rd Mount Magnet 6638 WA	Possibly contaminated - investigation required	29/03/2017	Petroleum hydrocarbons (such as from diesel or oil) have been observed in soil and groundwater beneath the site. Various waste materials have been buried within the on-site putrescible landfill. The quality of soil and groundwater at the site has not been investigated.
2/02/2017	Sections of Lot 62 on Deposited Plan 55278 and Lot 52 on Plan 54397, Fortescue 6716 WA	Possibly contaminated - investigation required	15/03/2017	Hydrocarbons (such as from oil and/or diesel) were visually identified within surface soils at the base of the oil burning pit, associated with the former power station.
2/02/2017	Section of Lot 24 on Deposited Plan 241372, Burrup 6714 WA	Possibly contaminated - investigation required	15/03/2017	The site has been used as a landfill for the disposal of waste materials associated with the adjacent iron ore and port operations. However, the quality of soil and groundwater at the site has not been investigated.
9/02/2017	2 Irene St Castletown 6450 WA	Decontaminated	9/06/2022	Following remediation, no known contamination remains at the site.
13/02/2017	Winton Rd Joondalup 6027 WA	Possibly contaminated - investigation required	29/07/2020	Petroleum hydrocarbons (such as from diesel) and metals are present in the groundwater beneath the site.
13/02/2017	2293 Albany Hwy Gosnells 6110 WA	Classification timeframe extended under s.14(1)(b)		
13/02/2017	2285 Albany Hwy Gosnells 6110 WA	Classification timeframe extended under s.14(1)(b)		
13/02/2017	2294 Albany Hwy Gosnells 6110 WA	Classification timeframe extended under s.14(1)(b)		

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
13/02/2017	2292 Albany Hwy Gosnells 6110 WA	Classification timeframe extended under s.14(1)(b)		
13/02/2017	2288 Albany Hwy Gosnells 6110 WA	Classification timeframe extended under s.14(1)(b)		
13/02/2017	2282 Albany Hwy Gosnells 6110 WA	Classification timeframe extended under s.14(1)(b)		
13/02/2017	2278 Albany Hwy Gosnells 6110 WA	Classification timeframe extended under s.14(1)(b)		
13/02/2017	2294 Albany Hwy Gosnells 6110 WA	Classification timeframe extended under s.14(1)(b)		
13/02/2017	2260 Albany Hwy Gosnells 6110 WA	Classification timeframe extended under s.14(1)(b)		
13/02/2017	5 Astley St Gosnells 6110 WA	Classification timeframe extended under s.14(1)(b)		
13/02/2017	3 Astley St Gosnells 6110 WA	Classification timeframe extended under s.14(1)(b)		
13/02/2017	4 Astley St Gosnells 6110 WA	Classification timeframe extended under s.14(1)(b)		

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
13/02/2017	Lot 3881 on Diagram 84821 Gosnells 6110 WA	Classification timeframe extended under s.14(1)(b)		
13/02/2017	Lot 99 on Plan 27616 Gosnells 6110 WA	Classification timeframe extended under s.14(1)(b)		
14/02/2017	Lot 301 on Deposited Plan 47451 East Perth 6004 WA	Classification timeframe extended under s.14(1)(b)		
15/02/2017	5 Casella Pl Kewdale 6105 WA	Remediated for restricted use	20/04/2018	Following remediation, hydrocarbons (such as petrol or diesel) remain in groundwater beneath the central eastern portion of the site.
21/02/2017	314 Johnson Rd Wellard 6170 WA	Decontaminated	24/05/2017	Following remediation, no contamination remains at the site.
3/03/2017	25 Mitchell Rd Mount Barker 6324 WA	Possibly contaminated - investigation required	23/03/2017	Hydrocarbons (such as from petrol) have been detected in groundwater beneath the eastern portion of the site.
3/03/2017	Lot 502 on Plan 411135, Wickham 6720 WA	Remediated for restricted use	13/04/2017	Asbestos-impacted fill is buried in a containment cell beneath this site, below a minimum one metre of inert fill.
3/03/2017	300 Bayly Av Gap Ridge 6714 WA	Report not substantiated	30/03/2017	Low levels of hydrocarbons (such as from aviation fuel) have been detected in an isolated area within shallow soil adjacent to the helipad.
8/03/2017	30 Ocean St Kwinana Beach 6167 WA	Decontaminated	31/08/2017	Low concentrations of hydrocarbons (such as diesel and oil) are present in soils beneath the site.
10/03/2017	Armstrong Rd Wilson 6107 WA	Decontaminated	6/01/2021	No contamination remains at this site.
13/03/2017	Lot 1879 Ledger Road Piesse Brook 6076	Possibly contaminated - investigation required	13/04/2017	Uncontrolled fill is present along the western boundary of the site.
15/03/2017	Mining Tenements M77/721 & G77/126 Southern Cross 6426 WA	Report not substantiated	27/04/2017	Overburden containing minerals amosite and Actinolite fibres (asbestos) are present in the waste rock dump.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
15/03/2017	2 Waterway Cr Ascot 6104 WA	Remediated for restricted use	25/06/2020	Asbestos-impacted fill material is present at the site and is located beneath a geotextile warning barrier and a minimum of 0.5 metres of clean fill.
16/03/2017	155 Todd St Merredin 6415 WA	Decontaminated	26/03/2018	Following remediation, no contamination remains at the site
22/03/2017	Lot 319 No. 57 Moore Street, Manjimup	Decontaminated	26/04/2018	Following remediation, no contamination remains at the site.
30/03/2017	92 Gardiner St Moora 6510 WA	Remediated for restricted use	21/01/2020	Hydrocarbon contaminated groundwater (such as from petrol) is present beneath the adjacent service station (the source site) and extends beneath this site. Chlorinated hydrocarbons were identified in groundwater beneath an access road (an affected site) located immediately south of the service station. Chlorinated hydrocarbons were not detected beneath other parcels of land at concentrations above non-potable groundwater use criteria.
4/04/2017	272 Stirling Hwy Claremont 6010 WA	Decontaminated	28/01/2022	Following a period of remediation (by natural attenuation), groundwater monitoring has demonstrated that no contamination remains present beneath this site.
6/04/2017	19 Eucalyptus Way Maida Vale 6057 WA	Possibly contaminated - investigation required	21/06/2017	Fragments of asbestos-containing material (ACM) were found present in fill material adjacent to the driveway along the western boundary extending to the rear of the on-site dwelling.
6/04/2017	100 Harrow St West Swan 6055 WA	Remediated for restricted use	15/02/2018	Hydrocarbons (such as from natural gas condensate) are likely to be present in soils and groundwater beneath below ground infrastructure.
6/04/2017	51 Stanley Rd Wellesley 6233 WA	Contaminated - remediation required	15/09/2021	<p>Groundwater beneath the site has been impacted by putrescible landfill leachate. Groundwater impacts are characterised by elevated total dissolved solids, ammonia, metals (including aluminium and iron), hydrocarbons (such as from oils, greases, humics and fatty acids) and per- and poly-fluoroalkyl substances (PFAS). These substances extend off-site in groundwater to the west and south-west and may also extend off-site to the south-east.</p> <p>Landfill gases (methane and carbon dioxide) are being generated from within the landfill material in the south-western portion of the site.</p> <p>Asbestos-containing material and animal and medical wastes may be present at two metres below ground level to the eastern perimeter of the landfill cell known as Cell 1.</p>

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
11/04/2017	130 Rendezvous Rd Vasse 6280 WA	Possibly contaminated - investigation required	26/03/2018	A plume of metals, aromatic hydrocarbons (benzene) and chlorinated hydrocarbons (such as from solvents and their breakdown products) in groundwater has migrated in a north north-westerly direction from the waste facility to the south and is likely to extend to beneath this site.
12/04/2017	Lot 12753 on DP 193243 Bassendean 6054 WA	Contaminated - remediation required	26/05/2020	Hydrocarbons (such as from petrol or diesel), metals and chlorobenzene have been detected in groundwater beneath the site, present as a plume extending from adjacent land to the south.
13/04/2017	95 Rendezvous Rd Vasse 6280 WA	Contaminated - restricted use	26/03/2018	A plume of metals, aromatic hydrocarbons (benzene) and chlorinated hydrocarbons (such as from solvents and their breakdown products) is present in groundwater beneath this site that has migrated in a north north-westerly direction from the adjacent waste facility to the south.
13/04/2017	130 Rendezvous Rd Vasse 6280 WA	Possibly contaminated - investigation required	26/03/2018	A plume of metals, aromatic hydrocarbons (benzene) and chlorinated hydrocarbons (such as from solvents and their breakdown products) in groundwater has migrated in a north north-westerly direction from the waste facility to the south and is likely to extend to beneath this site.
18/04/2017	7 Wellington St Bunbury 6230 WA	Remediated for restricted use	18/05/2017	Hydrocarbons (such as from petrol, diesel or oils) are present in soil beneath the site.
28/04/2017	35 Stanley Rd Wellesley 6233 WA	Possibly contaminated - investigation required	15/09/2021	Groundwater beneath this site has been impacted by putrescible landfill leachate. Groundwater impacts are characterised by elevated total dissolved solids, ammonia, metals (including aluminium and iron), hydrocarbons (such as from oils, greases, humics and fatty acids) and per- and poly-fluoroalkyl substances (PFAS). Landfill gases (methane and carbon dioxide) are being generated from within landfill material to the east and may also be present beneath this site.
2/05/2017	388 South Western Hwy Waroona 6215 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	2 Wallis St Ballidu 6606 WA	Possibly contaminated - investigation required	21/10/2020	Fire-fighting foams containing perfluoroalkyl and polyfluoroalkyl substances (PFAS) have been stored, mixed and/or discharged to the environment at the site. Limited testing at the site confirmed the presence of PFAS in soil. Further investigations are required to determine the nature and extent of impacts, and to inform assessment of potential risks.
2/05/2017	236 A The Strand Dianella 6059 WA	Classification timeframe extended under s.14(1)(b)		

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
2/05/2017	47 Hardey Rd Belmont 6104 WA	Contaminated - restricted use	10/11/2020	Perfluoroalkyl and polyfluoroalkyl substances (PFAS) (such as from fire-fighting foams) are present in groundwater beneath the site. PFAS is present in soils at the southern boundary of Lot 743 at depths of 5.5 to 6.5 meters below ground level.
2/05/2017	68 Queen St Busselton 6280 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	110 Burt St Boulder 6432 WA	Possibly contaminated - investigation required	12/03/2019	Fire-fighting foams containing perfluoroalkyl and polyfluoroalkyl substances (PFAS) have been stored and discharged to the environment at the site. Investigations are required to determine the nature and extent of potential impacts, and to inform assessment of potential risks.
2/05/2017	44 George Way Cannington 6107 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	441 Stirling Hwy Claremont 6010 WA	Possibly contaminated - investigation required	11/03/2021	Fire-fighting foams containing perfluoroalkyl and polyfluoroalkyl substances (PFAS) have been stored and used at the site.
2/05/2017	35 Abel St Boyup Brook 6244 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	66 Sylvester St Coolgardie 6429 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	35 John St Bremer Bay 6338 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	64 Banksia Dr Coral Bay 6701 WA	Classification timeframe extended under s.14(1)(b)		

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
2/05/2017	11 Leahy St Dalwallinu 6609 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	378 Prinsep St Bunbury 6230 WA	Report not substantiated	2/06/2021	No contamination has been identified.
2/05/2017	11 High St Dampier 6713 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	111 Dampier Rd Denham 6537 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	31 Marri Dr Dunsborough 6281 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	8 Russ St Port Denison 6525 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	8 Darcy St Halls Creek 6770 WA	Report not substantiated	14/07/2022	No known contamination has been identified.
2/05/2017	2 Meadow St Guildford 6055 WA	Report not substantiated	1/07/2021	Fire-fighting foams containing perfluoroalkyl and polyfluoroalkyl substances (PFAS) have been stored, mixed and discharged to the environment at the site.
2/05/2017	13 Robinson St Gingin 6503 WA	Classification timeframe extended under s.14(1)(b)		

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
2/05/2017	18 Phillimore St Fremantle 6160 WA	Report not substantiated	3/09/2020	No contamination has been identified.
2/05/2017	98 Fallon Rd Fitzroy Crossing 6765 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	68 A Cobblers St Falcon 6210 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	21 Payne St Exmouth 6707 WA	Possibly contaminated - investigation required	8/07/2021	Fire-fighting foams containing per-and poly-fluoroalkyl substances (PFAS) have been stored, mixed and/or discharged to the environment at the site. Further investigations are required to determine the nature and extent of impacts, and to inform assessment of potential risks.
2/05/2017	4 Ennis St Eaton 6232 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	6 Hamilton Rd Eaton 6232 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	24 Yurkla Way Eucla 6443 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	25 Camilleri St Busselton 6280 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	547 Dundas Rd Forrestfield 6058 WA	Contaminated - remediation required	13/12/2017	A complex plume, comprising volatile organic compounds (including chlorinated solvents and petroleum hydrocarbons), metals and perfluoroalkyl and polyfluoroalkyl substances (PFAS) is present in soils and groundwater beneath the site and extends off-site to the west.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
2/05/2017	387 Albany Hwy Victoria Park 6100 WA	Report not substantiated	27/05/2021	No contamination has been identified.
2/05/2017	9 Vista St Walpole 6398 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	78 Adams St Trayning 6488 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	854 Central Rd Tom Price 6751 WA	Possibly contaminated - investigation required	15/02/2023	Per-and poly-fluoroalkyl substances (PFAS) (such as from fire-fighting foams) are present in soil and groundwater beneath the site and surface water in the adjacent drainage channel. Further investigation of off-site groundwater and surface water are required to determine the nature and extent of impacts, and to inform assessment of potential risks.
2/05/2017	365 Hammond Rd Success 6164 WA	Possibly contaminated - investigation required	19/08/2020	Firefighting foams containing perfluoroalkyl and polyfluoroalkyl substances (PFAS) have been stored, used for training and potentially discharged to the environment at the site. Limited testing at the site confirmed the presence of PFAS in the surface water present in on-site drains. Further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks to human health and the environment.
2/05/2017	978 Antares St Southern Cross 6426 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	34 Altair St Southern Cross 6426 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	59 Hill St Meekatharra 6642 WA	Classification timeframe extended under s.14(1)(b)		

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
2/05/2017	369 Canning Hwy Palmyra 6157 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	3 The Crescent Midland 6056 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	Lot 31 On Plan 222818 Moora 6510 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	71 Hepburn St Mount Magnet 6638 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	46 Laurie St Mount Magnet 6638 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	44 Egerton St Narrogin 6312 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	1621 Newman Dr Newman 6753 WA	Possibly contaminated - investigation required	17/03/2021	Fire-fighting foams containing perfluoroalkyl and polyfluoroalkyl substances (PFAS) have been stored, mixed and/or discharged to the environment at the site. Limited testing at the site confirmed the presence of PFAS in soil. Further investigations are required to determine the nature and extent of impacts, and to inform assessment of potential risks.
2/05/2017	10 Banksia St Northcliffe 6262 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	87 Duke St Northam 6401 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	77 Collie St Albany 6330 WA	Possibly contaminated - investigation required	20/03/2018	Fire-fighting foams containing perfluoroalkyl and polyfluoroalkyl substances (PFAS) have been stored, mixed and discharged to the environment at the site. Limited testing at the site confirmed the presence of PFAS in sediments associated with the site drainage system. However, further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
2/05/2017	438 Green Av Armadale 6112 WA	Possibly contaminated - investigation required	8/02/2018	<p>Fire-fighting foams containing perfluoroalkyl and polyfluoroalkyl substances (PFAS) have been stored, mixed and discharged to the environment at the site.</p> <p>Limited testing at the site confirmed the presence of PFAS in soil and surface water associated with the site drainage system.</p> <p>However, further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.</p>
2/05/2017	62 Allnut Tce Augusta 6290 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	14 Parker St Bassendean 6054 WA	Possibly contaminated - investigation required	1/02/2018	<p>Fire-fighting foams containing perfluoroalkyl and polyfluoroalkyl substances (PFAS) have been stored, mixed and discharged to the environment at the site.</p> <p>Limited testing at the site confirmed the presence of PFAS in soil.</p> <p>However, further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.</p>
2/05/2017	Gardiner St Moora 6510 WA	Possibly contaminated - investigation required	6/06/2017	<p>An abandoned UST is present beneath the site.</p> <p>Petroleum impacted groundwater is present beneath the site.</p>
2/05/2017	132 Forrest St Collie 6225 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	8 Myers St Dalwallinu 6609 WA	Report not substantiated	6/08/2020	No contamination has been identified.
2/05/2017	3 Bentley St Donnybrook 6239 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	160 Great Eastern Hwy Midvale 6056 WA	Classification timeframe extended under s.14(1)(b)		

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
2/05/2017	9 Padbury St Mullewa 6630 WA	Possibly contaminated - investigation required	28/03/2018	Fire-fighting foams containing perfluoroalkyl and polyfluoroalkyl substances (PFAS) have been stored, mixed and discharged to the environment at the site. Limited testing at the site confirmed the presence of PFAS in the groundwater. However, further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.
2/05/2017	480 Hay St Perth 6000 WA	Remediated for restricted use	10/08/2017	Perfluoroalkyl and polyfluoroalkyl substances (PFAS) (such as from fire-fighting foams) are present in groundwater beneath the site.
2/05/2017	18 Williams St Brookton 6306 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	6 Austral Tce Katanning 6317 WA	Report not substantiated	13/04/2021	No contamination has been identified.
2/05/2017	501 Great Eastern Hwy Redcliffe 6104 WA	Report not substantiated	16/06/2017	No contamination has been identified.
2/05/2017	497 Great Eastern Hwy Redcliffe 6104 WA	Report not substantiated	16/06/2017	No contamination has been identified.
2/05/2017	20 Brooking St Williams 6391 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	312 Boronia Av Wundowie 6560 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	20 St Pauls Way Wyndham 6740 WA	Classification timeframe extended under s.14(1)(b)		

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
2/05/2017	151 Avon Tce York 6302 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	53 Thompson Rd North Fremantle 6159 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	15 Murray St Pinjarra 6208 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	16 Jennaberring Rd Quairading 6383 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	99 Dixon Rd Rockingham 6168 WA	Possibly contaminated - investigation required	10/03/2021	Fire-fighting foams containing perfluoroalkyl and polyfluoroalkyl substances (PFAS) are likely to have been stored, mixed and discharged to the environment at the site. Further investigations are required to determine the nature and extent of impacts, and to inform assessment of potential risks.
2/05/2017	23 Sholl St Roebourne 6718 WA	Possibly contaminated - investigation required	20/02/2020	Per-and poly-fluoroalkyl substances (PFAS) (such as from fire-fighting foams) may have been stored and used at the site for training purposes. Residual asbestos-impacted soil may remain in-situ beneath the site after historical remediation works. Further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.
2/05/2017	44 Jarrah Rd Roleystone 6111 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	99 B Coode St South Perth 6151 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	30 Fitzgerald St Koolyanobbing 6427 WA	Classification timeframe extended under s.14(1)(b)		

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
2/05/2017	20 Johnston St Kulin 6365 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	26 Atkinson Way Lancelin 6044 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	1 Euro St Laverton 6440 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	2 Mccourt St West Leederville 6007 WA	Report not substantiated	1/07/2021	No contamination has been identified.
2/05/2017	56 Gwalia St Leonora 6438 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	33 Eighth Av Maylands 6051 WA	Report not substantiated	17/03/2021	No contamination has been identified.
2/05/2017	13 Lynch St Hyden 6359 WA	Possibly contaminated - investigation required	10/03/2021	Fire-fighting foams containing perfluoroalkyl and polyfluoroalkyl substances (PFAS) have been stored and/or mixed at the site. Limited testing at the site did not detect the presence of PFAS in soil. Further investigations are required to determine the presence and/or nature and extent of potential impacts, and to inform assessment of risk at the site.
2/05/2017	11 Magee Cr Kalbarri 6536 WA	Classification timeframe extended under s.14(1)(b)		

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
2/05/2017	189 Boulder Rd South Kalgoorlie 6430 WA	Possibly contaminated - investigation required	22/02/2018	Fire-fighting foams containing perfluoroalkyl and polyfluoroalkyl substances (PFAS) have been stored and discharged to the environment at the site. Limited testing at the site confirmed the presence of PFAS in soil. However, further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.
2/05/2017	32 Brookman St Kalgoorlie 6430 WA	Report not substantiated	27/05/2021	No contamination has been identified.
2/05/2017	47 Hare St Piccadilly 6430 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	71 Leake St Kellerberrin 6410 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	4 Ripper Street Kellerberrin 6410 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	Lot 331 Graham Street Kondinin 6367 WA	Possibly contaminated - investigation required	11/03/2021	Fire-fighting foams containing perfluoroalkyl and polyfluoroalkyl substances (PFAS) have been stored, mixed and discharged to the environment at the site. Limited testing has confirmed the presence of PFAS in soil at the site. Further investigation is required to characterise the nature and extent of these impacts.
2/05/2017	81 Pinjarra Rd Mandurah 6210 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	47 Drovers Pl Wanneroo 6065 WA	Possibly contaminated - investigation required	4/08/2020	Fire-fighting foams containing perfluoroalkyl and polyfluoroalkyl substances (PFAS) have reportedly been stored, mixed and discharged to the environment at the site.
2/05/2017	73 Bashford St Jurien Bay 6516 WA	Classification timeframe extended under s.14(1)(b)		

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
2/05/2017	246 Spearwood Av Spearwood 6163 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	380 Welshpool Rd Welshpool 6106 WA	Classification timeframe extended under s.14(1)(b)		
2/05/2017	357 Wickham Dr Wickham 6720 WA	Classification timeframe extended under s.14(1)(b)		
3/05/2017	2 Williamson Way Port Hedland 6721 WA	Possibly contaminated - investigation required	15/06/2017	<p>Perfluoroalkyl and polyfluoroalkyl substances (such as from fire-fighting foams) are present in groundwater beneath the site adjacent to the operational fire-fighting training ground and to the north of the main runway at the location of a historical training ground.</p> <p>Lead is present in soil beneath the concrete foundation of an aviation hangar at the location of a former fuel depot.</p> <p>Fragments of suspected asbestos-containing material have been observed on the soil surface in numerous locations across the site.</p> <p>Soil staining has been observed in multiple locations associated with current or former airport related infrastructure and activities.</p>
5/05/2017	4845 Great Eastern Hwy Parkerville 6081 WA	Decontaminated	16/04/2018	Following remediation, no contamination remains at the site.
5/05/2017	4975 Great Eastern Hwy Parkerville 6081 WA	Decontaminated	16/04/2018	Following remediation, no contamination remains at the site.
5/05/2017	125 Kintore Rd Parkerville 6081 WA	Decontaminated	16/04/2018	Following remediation, no contamination remains at the site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
5/05/2017	Roebourne-Wittenoom Rd Millstream 6716 WA	Contaminated - remediation required	13/06/2017	Asbestos fibres have been identified in several locations along the road.
5/05/2017	29 Blundell St Dayton 6055 WA	Classification timeframe extended under s.14(1)(b)		
9/05/2017	309 Guildford Rd Bassendean 6054 WA	Contaminated - remediation required	22/11/2017	Hydrocarbons (such as from petrol) are present in groundwater beneath this site, extending to the western and eastern site boundaries.
11/05/2017	39 Resource Way Malaga 6090 WA	Remediated for restricted use	27/04/2021	Hydrocarbons (such as from diesel or oil) are present in soil and may remain in groundwater beneath the site following remediation. Metals (copper, nickel and zinc) are present in groundwater.
12/05/2017	40 Great Northern Hwy Middle Swan 6056 WA	Remediated for restricted use	26/06/2019	Hydrocarbons (such as from petrol) are present in minor concentrations in groundwater in the western portion of the site.
17/05/2017	South Western Hwy Donnybrook 6239 WA	Possibly contaminated - investigation required	14/06/2017	Strong hydrocarbon odours were noted during excavation works. However, the quality of groundwater beneath the site has not been investigated.
19/05/2017	Goulds Rd Narngulu 6532 WA	Contaminated - restricted use	21/12/2022	Radiation monitoring has detected elevated levels of gamma radiation at the site.
23/05/2017	3 Edenderry Tce Subiaco 6008 WA	Remediated for restricted use	20/09/2017	Metals (such as copper, zinc and lead) and asbestos are present in soils adjacent to the railway tunnel at a depth of 2 metres below ground level.
29/05/2017	212 (Lot 28) Albany Hwy Centennial Park 6330 WA	Possibly contaminated - investigation required	8/02/2018	Dissolved-phase hydrocarbons (such as from petrol) are present in groundwater beneath the site.
29/05/2017	212 (Lot 29) Albany Hwy Centennial Park 6330 WA	Possibly contaminated - investigation required	8/02/2018	Dissolved-phase hydrocarbons (such as from petrol) are present in groundwater beneath the site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
30/05/2017	227 York St Albany 6330 WA	Possibly contaminated - investigation required	12/04/2016	Hydrocarbons (such as from diesel/petrol), metals and pesticides are present in soils across the site. Metals and Polycyclic aromatic hydrocarbons are present in groundwater beneath the site.
1/06/2017	1361 Barrack St Merredin 6415 WA	Possibly contaminated - investigation required	5/07/2017	Bonded potential asbestos-containing material fragments were identified within surface soil of the site.
1/06/2017	1576 Princess Royal Dr Port Albany 6330 WA	Decontaminated	8/01/2020	Following remediation, no contamination remains at the site.
2/06/2017	77 Canning Hwy Victoria Park 6100 WA	Decontaminated	4/10/2017	Following removal of fragments of asbestos-containing material, no contamination remains at the site.
6/06/2017	7 Balannup Rd Harrisdale 6112 WA	Contaminated - restricted use	20/07/2017	Asbestos-impacted soil and asbestos-containing material (ACM) is buried beneath the eastern portion of the site at a depth of between 0.2 and 2.2 m below ground level.
6/06/2017	Lot 2 Nanga Road Nanga 6573 WA	Remediated for restricted use	31/08/2017	The site has been used as a landfill site for the disposal of domestic waste and asbestos sheeting.
9/06/2017	127 Giblett St Manjimup 6258 WA	Possibly contaminated - investigation required	25/06/2020	Hydrocarbons (such as from petrol and diesel) are present in soil beneath the site. Hydrocarbons and chlorinated hydrocarbons are present in groundwater beneath the site.
9/06/2017	27 Hawkins Rd Wanneroo 6065 WA	Report not substantiated	17/07/2017	No contamination has been identified.
12/06/2017	1851 Albany Hwy Maddington 6109 WA	Report not substantiated	9/08/2018	No contamination has been identified.
12/06/2017	9 Herbert St Maddington 6109 WA	Report not substantiated	9/08/2018	No contamination has been identified.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
12/06/2017	1845 Albany Hwy Maddington 6109 WA	Report not substantiated	9/08/2018	No contamination has been identified.
12/06/2017	201 Burslem Dr Maddington 6109 WA	Report not substantiated	9/08/2018	No contamination has been identified.
12/06/2017	38 Attfield St Maddington 6109 WA	Report not substantiated	9/08/2018	No contamination has been identified.
12/06/2017	21 Boundary St South Kalgoorlie 6430 WA	Report not substantiated	13/07/2017	No contamination has been identified.
12/06/2017	19 Boundary St South Kalgoorlie 6430 WA	Report not substantiated	13/07/2017	No contamination has been identified.
12/06/2017	Lane St road reserve South Kalgoorlie 6430 WA	Report not substantiated	13/07/2017	No contamination has been identified.
12/06/2017	Laneway South Kalgoorlie 6430 WA	Report not substantiated	13/07/2017	No contamination has been identified.
13/06/2017	1 - 5 Bell St Canning Vale 6155 WA	Remediated for restricted use	6/06/2018	Hydrocarbons (such as from diesel or oil) are present in groundwater and soil beneath a triple interceptor near the centre of the site.
16/06/2017	17 Murray St Bayswater 6053 WA	Decontaminated	31/10/2017	Following remediation, no contamination remains at the site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
19/06/2017	278 Stirling Hwy Claremont 6010 WA	Not contaminated - unrestricted use	13/11/2019	No contamination has been identified.
19/06/2017	60 Peel Rd O'connor 6163 WA	Contaminated - remediation required	30/06/2020	Per- and polyfluoroalkyl substances (PFAS, such as from fire-fighting foams) are present in groundwater beneath the site and extending off-site to the north-west.
19/06/2017	1626 Coolinda St Port Hedland 6721 WA	Possibly contaminated - investigation required	9/03/2018	Fire-fighting foams containing perfluoroalkyl and polyfluoroalkyl substances (PFAS) have been stored and discharged to the environment at the site. Investigations are required to determine the nature and extent of impacts both on and off-site, and to inform assessment of potential risks.
19/06/2017	1 Mackie St Wangara 6065 WA	Classification timeframe extended under s.14(1)(b)		
19/06/2017	146 Vincent St Beverley 6304 WA	Classification timeframe extended under s.14(1)(b)		
19/06/2017	35 Clarendon St Derby 6728 WA	Classification timeframe extended under s.14(1)(b)		
19/06/2017	105 Stirling Tce Toodyay 6566 WA	Classification timeframe extended under s.14(1)(b)		
19/06/2017	56 Walcott St Broome 6725 WA	Possibly contaminated - investigation required	26/03/2018	Fire-fighting foams containing per-and poly-fluoroalkyl substances (PFAS) have been stored, mixed and discharged to the environment at the site. Limited testing at the site confirmed the presence of PFAS in soil at the site. However, further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.
19/06/2017	4 Sommers Rd Brunswick 6224 WA	Classification timeframe extended under s.14(1)(b)		

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
19/06/2017	32 Forrest Av South Bunbury 6230 WA	Possibly contaminated - investigation required	16/06/2020	Fire-fighting foams containing per- and poly-fluoroalkyl substances (PFAS) have been stored, mixed and discharged to the environment at the site. PFAS is present in the soil and groundwater at the site. PFAS impacted groundwater is potentially migrating from site in a south, south easterly direction.
19/06/2017	13 Catalano Rd Canning Vale 6155 WA	Classification timeframe extended under s.14(1)(b)		
19/06/2017	12 Egan St Carnarvon 6701 WA	Possibly contaminated - investigation required	16/09/2020	Fire-fighting foams containing perfluoroalkyl and polyfluoroalkyl substances (PFAS) have been stored, mixed and discharged to the environment at the site. Investigations are required to determine the nature and extent of impacts, and to inform assessment of potential risks.
19/06/2017	8 Congdon St Claremont 6010 WA	Possibly contaminated - investigation required	11/03/2021	Perfluoroalkyl and polyfluoroalkyl substances (PFAS) (such as from fire fighting foams) have been identified in soil and sediments at the site.
19/06/2017	64 Sylvester St Coolgardie 6429 WA	Classification timeframe extended under s.14(1)(b)		
19/06/2017	15 Robinson St Cue 6640 WA	Classification timeframe extended under s.14(1)(b)		
19/06/2017	36 Lundy Av Cunderdin 6407 WA	Possibly contaminated - investigation required	8/03/2018	Fire-fighting foams containing perfluoroalkyl and polyfluoroalkyl substances (PFAS) have been stored and discharged to the environment at the site. Limited testing at the site confirmed the presence of PFAS in surface soils associated with the site drainage system.
19/06/2017	221 Stubbs Tce Shenton Park 6008 WA	Possibly contaminated - investigation required	30/01/2018	Fire-fighting foams containing perfluoroalkyl and polyfluoroalkyl substances (PFAS) have been stored, mixed and discharged to the environment at the site. Limited testing at the site confirmed the presence of PFAS in soil and surface water associated with the site drainage system. However, further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.
19/06/2017	Lot 257 Horsley Road Denmark 6333 WA	Possibly contaminated - investigation required	22/09/2021	Per-and poly-fluoroalkyl substances (PFAS) (such as from fire-fighting foams) are present in soil and surface water at the site. Further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
19/06/2017	23 Harvey St Dumbleyung 6350 WA	Classification timeframe extended under s.14(1)(b)		
19/06/2017	1 Forrest St Esperance 6450 WA	Classification timeframe extended under s.14(1)(b)		
19/06/2017	20 Phillimore St Fremantle 6160 WA	Possibly contaminated - investigation required	6/01/2021	Perfluoroalkyl and polyfluoroalkyl substances (such as from fire-fighting foams) are present in groundwater beneath the site and may be migrating off-site in a westerly direction. Further investigation is required to determine the nature and extent of impacted soil and groundwater both on and off-site.
19/06/2017	59 Durlacher St Geraldton 6530 WA	Possibly contaminated - investigation required	4/08/2021	Fire-fighting foams containing per-and poly-fluoroalkyl substances (PFAS) have been stored, mixed and/or discharged to the environment at the site. Limited testing at the site confirmed the presence of PFAS in soil. Further investigations are required to determine the nature and extent of impacts, and to inform assessment of potential risks.
19/06/2017	12 Quinlan St Goomalling 6460 WA	Classification timeframe extended under s.14(1)(b)		
19/06/2017	43 Hayward St Harvey 6220 WA	Possibly contaminated - investigation required	8/02/2018	Fire-fighting foams containing perfluoroalkyl and polyfluoroalkyl substances (PFAS) have been stored, mixed and discharged to the environment at the site. Further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.
19/06/2017	38 Central Rd Kalamunda 6076 WA	Possibly contaminated - investigation required	16/02/2018	Fire-fighting foams containing perfluoroalkyl and polyfluoroalkyl substances (PFAS) have been stored, mixed and discharged at the site.
19/06/2017	49 Hillview Rd Karratha 6714 WA	Possibly contaminated - investigation required	15/02/2022	Fire-fighting foams containing per-and poly-fluoroalkyl substances (PFAS) have been stored, mixed and/or discharged to the environment at the site. Limited testing at the site confirmed the presence of PFAS in soil. Further investigations are required to determine the nature and extent of impacts, and to inform assessment of potential risks.
19/06/2017	21 George St Kensington 6151 WA	Possibly contaminated - investigation required	30/09/2020	Fire-fighting foams containing perfluoroalkyl and polyfluoroalkyl substances (PFAS) have been stored and discharged to the environment at the site. Investigations are required to determine the nature and extent of impacts, and to inform assessment of potential risks.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
19/06/2017	92 Albany Hwy Kojonup 6395 WA	Classification timeframe extended under s.14(1)(b)		
19/06/2017	67 Day St Kulin 6365 WA	Classification timeframe extended under s.14(1)(b)		
19/06/2017	10 Chisham Av Kwinana Town Centre 6167 WA	Possibly contaminated - investigation required	13/02/2018	The on-site soak well and sump are likely preferential pathways for infiltration of perfluoroalkyl and polyfluoroalkyl substances (PFAS) into the underlying aquifer from storage and historical use of firefighting foams containing PFAS during fire training activities.
19/06/2017	40 Bennett St Lake Grace 6353 WA	Classification timeframe extended under s.14(1)(b)		
19/06/2017	71 Tower St Leonora 6438 WA	Classification timeframe extended under s.14(1)(b)		
19/06/2017	1965 Albany Hwy Maddington 6109 WA	Possibly contaminated - investigation required	17/06/2021	Per-and poly-fluoroalkyl substances (PFAS) (such as from fire-fighting foams) are likely to have been stored and used at the site for training purposes. Further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.
19/06/2017	14 Irvine Dr Malaga 6090 WA	Classification timeframe extended under s.14(1)(b)		
19/06/2017	39 Pantan Rd Greenfields 6210 WA	Classification timeframe extended under s.14(1)(b)		
19/06/2017	44 Bohemia St Marble Bar 6760 WA	Classification timeframe extended under s.14(1)(b)		

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
19/06/2017	62 Willmott Av Margaret River 6285 WA	Possibly contaminated - investigation required	10/03/2022	Fire-fighting foams containing per- and polyfluoroalkyl substances (PFAS) were stored, mixed and discharged to the environment at the site. Limited testing at the site confirmed the presence of PFAS in soil at the site.
19/06/2017	28 Bates St Merredin 6415 WA	Classification timeframe extended under s.14(1)(b)		
19/06/2017	60 Valentine St Morawa 6623 WA	Classification timeframe extended under s.14(1)(b)		
19/06/2017	13 Adam St Nannup 6275 WA	Classification timeframe extended under s.14(1)(b)		
19/06/2017	1 Kipling St Narrogin 6312 WA	Classification timeframe extended under s.14(1)(b)		
19/06/2017	43 Wellington St Northam 6401 WA	Classification timeframe extended under s.14(1)(b)		
19/06/2017	501 Mcgrath Av Onslow 6710 WA	Classification timeframe extended under s.14(1)(b)		
19/06/2017	47 Collingwood St Osborne Park 6017 WA	Possibly contaminated - investigation required	2/06/2021	Fire-fighting foams containing perfluoroalkyl and polyfluoroalkyl substances (PFAS) have been stored, mixed and/or discharged to the environment at the site. Further investigations are required to determine the nature and extent of impacts, and to inform assessment of potential risks.
19/06/2017	274 Scarborough Beach Rd Osborne Park 6017 WA	Possibly contaminated - investigation required	7/10/2020	Fire-fighting foams containing perfluoroalkyl and polyfluoroalkyl substances (PFAS) have been stored and used at the site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
19/06/2017	Lot 230 Hepple Place Pemberton 6260 WA	Possibly contaminated - investigation required	11/11/2020	Fire-fighting foams containing perfluoroalkyl and polyfluoroalkyl substances (PFAS) have been stored, mixed and/or discharged to the environment at the site. Limited testing at the site confirmed the presence of PFAS in soil. Further investigations are required to determine the nature and extent of impacts, and to inform assessment of potential risks.
19/06/2017	24 Dunn St Ravensthorpe 6346 WA	Classification timeframe extended under s.14(1)(b)		
19/06/2017	73 Hamilton Rd South Hedland 6722 WA	Possibly contaminated - investigation required	4/09/2019	Hydrocarbons (such as from petrol) are present in groundwater beneath the south-eastern portion of the site. Soil vapour has not been investigated and groundwater requires further investigation.
19/06/2017	7 Traverse St Wagin 6315 WA	Possibly contaminated - investigation required	15/03/2018	Fire-fighting foams containing perfluoroalkyl and polyfluoroalkyl substances (PFAS) have been stored, mixed and discharged to the environment at the site. Limited testing at the site confirmed the presence of PFAS in soil and surface water associated with the site drainage system. However, further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.
19/06/2017	22 Brooking St Williams 6391 WA	Possibly contaminated - investigation required	23/09/2020	Fire-fighting foams containing per- and polyfluoroalkyl substances (PFAS) are likely to have been stored, mixed and discharged to the environment at the site. Limited testing at the site confirmed the presence of PFAS in soil in the southern portion of the site. Further investigations are required to determine the nature and extent of impacts, and to inform assessment of potential risks.
19/06/2017	53 Fenton Pl Wongan Hills 6603 WA	Classification timeframe extended under s.14(1)(b)		
19/06/2017	26 Maxwell St York 6302 WA	Classification timeframe extended under s.14(1)(b)		
19/06/2017	191 Avon Tce York 6302 WA	Classification timeframe extended under s.14(1)(b)		
19/06/2017	2 Glenrothes Cr Yanchep 6035 WA	Possibly contaminated - investigation required	22/02/2018	Fire-fighting foams containing perfluoroalkyl and polyfluoroalkyl substances (PFAS) have been stored, mixed and discharged at the site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
19/06/2017	14 Clarkhill Rd Secret Harbour 6173 WA	Classification timeframe extended under s.14(1)(b)		
19/06/2017	2 B Goyder St Corrigin 6375 WA	Classification timeframe extended under s.14(1)(b)		
19/06/2017	175 Hampton St Bridgetown 6255 WA	Possibly contaminated - investigation required	17/03/2021	Fire-fighting foams containing perfluoroalkyl and polyfluoroalkyl substances (PFAS) have been stored, mixed and discharged to the environment at the site. Limited testing at the site confirmed the presence of PFAS in soil. However, further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.
19/06/2017	275 Belmont Av Cloverdale 6105 WA	Classification timeframe extended under s.14(1)(b)		
19/06/2017	44 Bath St Manjimup 6258 WA	Classification timeframe extended under s.14(1)(b)		
19/06/2017	4 Hefron St Rockingham 6168 WA	Possibly contaminated - investigation required	22/12/2022	Per-and poly-fluoroalkyl substances (PFAS) (such as from fire-fighting foams) are likely to have been stored and used at the site for training purposes. Further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.
19/06/2017	20 Pasture St Pingelly 6308 WA	Classification timeframe extended under s.14(1)(b)		
19/06/2017	41 D Delawney St Balcatta 6021 WA	Possibly contaminated - investigation required	14/07/2022	Fire-fighting foams containing perfluoroalkyl and polyfluoroalkyl substances (PFAS) are likely to have been stored and discharged to the environment at the site. Investigations are required to determine the nature and extent of potential impacts, and to inform assessment of potential risks.
19/06/2017	2 Adams St O'connor 6163 WA	Classification timeframe extended under s.14(1)(b)		

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
19/06/2017	5 Donnan St Tammin 6409 WA	Possibly contaminated - investigation required	8/07/2021	Fire-fighting foams suspected of containing per-and poly-fluoroalkyl substances (PFAS) have been stored at the site. Further investigations are required to confirm PFAS use and determine the nature and extent of impacts to inform assessment of potential risks.
19/06/2017	28 Lowood Rd Mount Barker 6324 WA	Possibly contaminated - investigation required	13/04/2021	Per-and poly-fluoroalkyl substances (PFAS) (such as from fire-fighting foams) are likely to have been stored and used at the site for training purposes. Further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.
20/06/2017	Stirling Hwy Claremont 6010 WA	Decontaminated	28/01/2022	Following a period of remediation (by natural attenuation), groundwater monitoring has demonstrated that no contamination remains present beneath this site.
23/06/2017	20 Foskew Way Narngulu 6532 WA	Decontaminated	26/07/2017	Following remediation, no known contamination remains beneath the electricity transformer. The quality of soil and groundwater beneath the remainder of the site has not been investigated.
28/06/2017	Vacant Crown Land, Brand Highway Eneabba 6518 WA	Possibly contaminated - investigation required	24/06/2021	Naturally-occurring radioactive materials are present at elevated concentrations in some portions of the site. Following remediation, no contamination remains at the location of a former fuel storage and dispensing area known as the 'South Mine Fuel Farm'.
29/06/2017	35 Resource Way Malaga 6090 WA	Remediated for restricted use	27/04/2021	Hydrocarbons (such as from diesel or oil) are present in soil and may remain in groundwater beneath the site following remediation. Metals (copper, nickel and zinc) are present in groundwater.
3/07/2017	39 Rushton Rd Martin 6110 WA	Contaminated - remediation required	16/08/2017	Asbestos containing material and foundry waste are present at the site
3/07/2017	1 Rushton Rd Martin 6110 WA	Contaminated - remediation required	16/08/2017	Asbestos containing material and foundry waste are present at the site
3/07/2017	15 Rushton Rd Martin 6110 WA	Contaminated - remediation required	16/08/2017	Asbestos containing material and foundry waste are present at the site

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
3/07/2017	27 Rushton Rd Martin 6110 WA	Contaminated - remediation required	16/08/2017	Asbestos containing material and foundry waste are present at the site
3/07/2017	Lot 9 on Plan 36549 Martin 6110 WA	Contaminated - remediation required	16/08/2017	Asbestos containing material and foundry waste are present at the site
3/07/2017	Lot 11 on Plan 36549 Martin 6110 WA	Contaminated - remediation required	16/08/2017	Asbestos containing material and foundry waste are present at the site
6/07/2017	Lots 100, 300 & 15444 West Coast Drive Marmion 6020 WA	Possibly contaminated - investigation required	10/08/2017	Asbestos-impacted fill material was visually identified on surface soil surrounding a sea wall during renovation and construction. The identified asbestos-containing material (ACM) was removed however possible ACM remains in soil and the extent of this has not been delineated.
18/07/2017	7 Zig Zag Rd Baldivis 6171 WA	Decontaminated	9/05/2019	Following remediation, no contamination has been identified at the site.
18/07/2017	29 Sabrina Rd Baldivis 6171 WA	Decontaminated	9/05/2019	Following remediation, no contamination has been identified at the site.
18/07/2017	43 Sabrina Rd Baldivis 6171 WA	Not contaminated - unrestricted use	9/05/2019	Investigations found that no contamination is present in soil and groundwater at the site.
18/07/2017	State Forest 24 Cardiff 6225 WA	Possibly contaminated - investigation required	30/08/2017	Hydrocarbons (such as from petrol/diesel) are suspected to have leaked from underground storage tanks at the site in the vicinity of mine site buildings.
19/07/2017	702 Buller Rd Waroona 6215 WA	Possibly contaminated - investigation required	26/10/2022	Metals and nutrients are present in groundwater in a plume that extends to the western boundary of the site.
19/07/2017	Lot 1619 Coronation Road Waroona 6215 WA	Possibly contaminated - investigation required	7/08/2017	The site has been used as a landfill site for the disposal of wastes, including putrescible waste. However, the quality of soil and groundwater at the site has not been investigated.
24/07/2017	Lot 309 Robinson St Kingsford 6701 WA	Contaminated - restricted use	7/09/2017	Hydrocarbons (such as from petrol) are present in groundwater at the service station located at 595 Robinson Road as a plume that extends in a south-westerly direction beneath this site.
25/07/2017	Reserve 12188 Wiluna 6646 WA	Report not substantiated	7/09/2017	No contamination has been identified

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
25/07/2017	22 Laverton-leonora Rd Leonora 6438 WA	Report not substantiated	31/08/2017	No contamination has been identified.
27/07/2017	Lot 20 Port Rd Kwinana Beach 6167 WA	Possibly contaminated - investigation required	5/05/2021	Arsenic, nutrients and hydrocarbons are present in soils beneath localised portions of the site. Arsenic, nutrients (mainly in the form of ammonia), hydrocarbons, chlorophenols and ammonium sulfate are present in groundwater beneath the site. Co-mingled groundwater plumes associated with onsite and offsite sources are migrating off-site towards Cockburn Sound.
1/08/2017	Lot 1404 Truscott Crescent Exmouth 6707 WA	Possibly contaminated - investigation required	25/02/2021	The site has historically been used for uncontrolled waste disposal. Further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.
2/08/2017	Leonora St Yakamia 6330 WA	Remediated for restricted use	17/07/2019	Petroleum hydrocarbons (such as from petrol and diesel) are present in groundwater beneath the former fuel depot located at 107 Chester Pass Road, Milpara, which extends as a plume in a south-easterly direction beneath this site.
3/08/2017	Lot 9001 Mcaulley Rd Onslow 6710 WA	Possibly contaminated - investigation required	31/08/2017	An area in the north of Lot 9001 has been used as a landfill site, potentially for the disposal of degradable wastes. However, the quality of soil and groundwater at the site has not been investigated.
3/08/2017	45 Marble Bar Pool Rd Marble Bar 6760 WA	Report not substantiated	7/09/2017	No contamination has been identified.
4/08/2017	Thornlie Ave Thornlie 6108 WA	Remediated for restricted use	28/03/2018	Hydrocarbons (such as from petrol/diesel) and lead are present in groundwater beneath the site.
4/08/2017	318 Spencer Rd Thornlie 6108 WA	Remediated for restricted use	28/03/2018	Hydrocarbons (such as from petrol/diesel) and lead are present in groundwater beneath the site. Hydrocarbon-impacted soils (such as from petrol/diesel) are present at depths associated with the groundwater smear-zone, and beneath or adjacent to active fuel-related infrastructure.
4/08/2017	Lot 21523 Dowerin-Wyalkatchem Rd Dowerin 6461 WA	Report not substantiated	7/09/2017	No contamination has been identified.
4/08/2017	Lot 2842 Nugadong East Rd Nugadong	Report not substantiated	7/09/2017	No contamination has been identified.
4/08/2017	Lot 21523 Dowerin-Wyalkatchem Rd Dowerin 6461 WA	Report not substantiated	7/09/2017	No contamination has been identified.
8/08/2017	15 Piccadilly St Piccadilly 6430 WA	Decontaminated	20/04/2018	Following remediation, no contamination remains at the site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
9/08/2017	223 Collier Rd Bayswater 6053 WA	Possibly contaminated - investigation required	7/04/2020	Soils are impacted by herbicides and pesticides. Groundwater beneath the site is impacted by agrochemicals.
9/08/2017	Lot 227 on Plan 240259, Naval Base 6165	Possibly contaminated - investigation required	6/08/2020	Aluminium, vanadium, molybdenum and arsenic are present in groundwater beneath the site.
9/08/2017	Lot 228 on Plan 240259, Naval Base 6165	Possibly contaminated - investigation required	6/08/2020	Aluminium, vanadium, molybdenum and arsenic are present in groundwater beneath the site.
9/08/2017	Lot 171 on Deposited Plan 180286 Naval Base 6165 WA	Possibly contaminated - investigation required	6/08/2020	Aluminium, vanadium, molybdenum and arsenic are present in groundwater beneath the site.
15/08/2017	603 Gas Bay Rd Gnarabup 6285 WA	Possibly contaminated - investigation required	3/11/2021	Arsenic, lead, manganese, nitrate and phosphorus are present in groundwater beneath the site.
15/08/2017	Mining Tenements M39/228, M39/18, M39/261 & M39/248 Laverton 6440 WA	Possibly contaminated - investigation required	6/09/2017	Hydrocarbons (such as from diesel) were visually identified on surface soils surrounding the location of a diesel storage tank, where diesel is known to have leaked from the tank on two separate occasions between 2011 and 2017. Hydrocarbons (such as from diesel) are potentially present in soil from the disposal of contaminated soil. However no contamination investigations have been carried and the quality of soil and groundwater at the site is unknown. Elevated cyanide and total dissolved solids are likely to be present in groundwater. However no contamination investigations have been carried out and the quality of soil and groundwater at the site is unknown.
16/08/2017	15 Piccadilly St Piccadilly 6430 WA	Decontaminated	20/04/2018	Following remediation, no contamination remains at the site.
21/08/2017	13 Mudlark Pl Vasse 6280 WA	Report not substantiated	26/03/2018	No contamination has been identified.
22/08/2017	Lot 973 Shanks Road Onslow 6710 WA	Possibly contaminated - investigation required	7/09/2017	Unauthorised disposal of wastes has occurred on this site. However, the quality of soil and groundwater at the site has not been investigated.
23/08/2017	36 Stony Brook Lane Roleystone 6111 WA	Possibly contaminated - investigation required	6/10/2017	Asbestos-containing material is present in demolition waste used as fill at the site.
24/08/2017	Lot 7 Beckwith Rd Chadwick 6450 WA	Remediated for restricted use	25/01/2018	Hydrocarbon-impacted groundwater (such as from petrol) is present beneath the adjacent self-service truck stop (the source site) and extends to the south and south-east beneath this site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
25/08/2017	Reserve 49037 Exmouth 6707 WA	Possibly contaminated - investigation required	14/09/2017	Hydrocarbons (such as from petrol or diesel) were visually identified in soil from 1.3 metres below ground level around a former fuel line located on the eastern side of the marina.
5/09/2017	Lot 50 On Diagram 44792 Hillside 6312	Possibly contaminated - investigation required	13/10/2017	Asbestos-containing material is located on the embankment of the reservoir.
7/09/2017	634 Casella Pl Kewdale 6105 WA	Decontaminated	9/10/2019	Following remediation, no significant contamination has been identified as remaining at the site.
7/09/2017	120 Babbage Island Rd Morgantown 6701 WA	Possibly contaminated - investigation required	14/07/2021	Per- and poly-fluoroalkyl substances (PFAS) (such as from PFAS-containing wastewater) and nutrients are present in groundwater beneath the site. Further investigation is required to inform assessment of potential risks to ecological receptors.
9/09/2017	40 Frame Ct Leederville 6007 WA	Remediated for restricted use	17/06/2019	Following remedial works, residual hydrocarbon impacts remain in soil and groundwater within the southern portion of the site.
12/09/2017	159 Badgerup Rd Wanneroo 6065 WA	Report not substantiated	12/03/2019	No contamination has been identified.
14/09/2017	20 Uppill Pl Wangara 6065 WA	Report not substantiated	13/10/2017	No contamination has been identified.
21/09/2017	68 Old Perth Rd Bassendean 6054 WA	Possibly contaminated - investigation required	2/11/2017	Fragments of asbestos-containing material, metals (such as lead and nickel), and hydrocarbons (such as from petrol and diesel) are present in shallow soils at the site. Hydrocarbons (such as from petrol and diesel), metals (such as copper and zinc) and volatile organic compounds (such as vinyl chloride) are present in shallow groundwater in the south-eastern corner of the site.
26/09/2017	300 Arthur St Dayton 6055 WA	Remediated for restricted use	10/11/2017	Asbestos-containing material was removed from the site during investigative works. However, additional asbestos-containing material may remain buried within the site.
28/09/2017	Lot 501 Fox Rd Burlong 6401 WA	Decontaminated	18/09/2019	Following remediation, hydrocarbons (such as from diesel, oil or bitumen), remain present in soils at bedrock exceeding ecological investigation levels. However, the impacted soils are localised and are unlikely to pose a significant risk to the environment.
28/09/2017	Crown Reserve 37899 De Grey 6722 WA	Possibly contaminated - investigation required	7/11/2017	Debris from asbestos-coated water pipes has been identified at the site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
3/10/2017	25 Asquith St Mount Claremont 6010 WA	Report not substantiated	10/11/2017	No contamination has been identified.
11/10/2017	2 North Lake Rd Alfred Cove 6154 WA	Remediated for restricted use	23/11/2017	Hydrocarbons (such as from petrol and diesel) are present in groundwater beneath the north east corner of the site. Hydrocarbon-impacted soil remains in-situ beneath the north east corner of the site at a depth of approximately 3 metres below ground surface.
12/10/2017	50 Forrest Rd Pickering Brook 6076 WA	Contaminated - remediation required	28/03/2018	Microbiological contaminants are present in groundwater beneath the site.
12/10/2017	61 Dempster St Esperance 6450 WA	Contaminated - restricted use	21/01/2020	Hydrocarbons, such as from petrol and diesel, are present in shallow groundwater at the south-eastern boundary of the site. Hydrocarbons, such as from petrol and diesel, may remain in soils in the south-eastern portion of the site adjacent to the former underground fuel storage tanks.
12/10/2017	342 Beaufort St Perth 6000 WA	Remediated for restricted use	17/11/2021	Hydrocarbons (such as from petrol and diesel) are present in soil and groundwater beneath the site.
12/10/2017	115 Strelly St Busselton 6280 WA	Contaminated - restricted use	28/07/2021	Hydrocarbon-contaminated groundwater (such as from petrol) is present as a dissolved-phase plume beneath the site.
13/10/2017	112 Oakleigh Dr Erskine 6210 WA	Remediated for restricted use	18/09/2019	Hydrocarbons (such as from petrol or diesel) are present in groundwater beneath the site in the vicinity of the remote fill point and tank pit. Hydrocarbon impact may also remain in soil beneath the forecourt area.
13/10/2017	North Rd Bassendean 6054 WA	Possibly contaminated - investigation required	3/06/2021	Hydrocarbons (such as from petrol or diesel) are present in soil and groundwater beneath the site.
13/10/2017	309 Guildford Rd Bassendean 6054 WA	Contaminated - remediation required	22/11/2017	Hydrocarbons (such as from petrol) are present in groundwater beneath this site, extending to the western and eastern site boundaries.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
17/10/2017	67 Hamilton Rd South Hedland 6722 WA	Contaminated - remediation required	28/11/2017	Hydrocarbons (such as from petrol) are present in groundwater beneath the east and south-eastern portions of the site. Soil vapour has not been investigated and groundwater requires further investigation off-site to the east and south east.
18/10/2017	6 Cockram Rd Martin 6110 WA	Possibly contaminated - investigation required	1/12/2017	Unauthorised disposal of wastes has occurred on this site. However, soil and groundwater quality at the site has not been investigated.
18/10/2017	520 Robinson St Kingsford 6701 WA	Contaminated - remediation required	1/12/2017	Hydrocarbons (such as from petrol/diesel) are present in soils beneath the eastern portion of the site. Hydrocarbons (such as from petrol/diesel) are present in groundwater, including light non-aqueous phase liquids, beneath the eastern portion of the site as a plume which extends off-site to the north.
19/10/2017	Lot 9109 On Deposited Plan 419061 Dalyellup 6230 WA	Possibly contaminated - investigation required	5/11/2020	The site predominantly comprises endemic bushland with a portion of the western area of the site previously used for activities associated with the adjacent former Waste Residue Disposal Facility. Treated solid residues were visually identified on the ground surface and at shallow depths in localised areas where the historical activities had occurred. Metals are also present in groundwater below the site.
19/10/2017	25 Strickland St Mount Claremont 6010 WA	Report not substantiated	10/11/2017	No contamination has been identified.
24/10/2017	31 Wotton St Wiluna 6646 WA	Report not substantiated	8/12/2017	No contamination has been identified.
24/10/2017	Lifford St Utakarra 6530 WA	Remediated for restricted use	6/08/2020	Following remediation, hydrocarbons (such as from transformer oil) remain in subsurface soil beneath the site.
24/10/2017	2022 Frankland Av Hammond Park 6164 WA	Possibly contaminated - investigation required	8/12/2017	The south-eastern portion of the site appears to have been historically used for the disposal of liquid wastes. The quality of the soil and groundwater is unknown as the site has not been investigated.
25/10/2017	10 Jon Sanders Dr Glendalough 6016 WA	Decontaminated	3/09/2020	Following a period of remediation by natural attenuation, groundwater monitoring has demonstrated that no contamination remains present beneath this site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
25/10/2017	614 Baldivis Rd Baldivis 6171 WA	Remediated for restricted use	10/01/2019	Hydrocarbon contaminated groundwater (such as from petrol and diesel) is present beneath the central portion of the site.
30/10/2017	312 Laine Jones Dr Kununurra 6743 WA	Remediated for restricted use	22/05/2018	Hydrocarbons (such as from aviation fuel) are present in soil and may also be present in groundwater beneath the site.
31/10/2017	Lot 36 Albany Hwy Arthur River 6315 WA	Possibly contaminated - investigation required	12/12/2017	Hydrocarbon-contaminated groundwater (such as from petrol or diesel) is present in groundwater beneath a former service station to the north, and beneath Albany Highway to the west, and is likely to extend beneath this site.
31/10/2017	Lot 67 Albany Hwy Arthur River 6315 WA	Possibly contaminated - investigation required	12/12/2017	Hydrocarbon-contaminated groundwater (such as from petrol or diesel) is present in groundwater beneath a former service station to the north, and beneath Albany Highway to the west, and is likely to extend beneath this site.
31/10/2017	Lot 377 Albany Hwy Arthur River 6315 WA	Possibly contaminated - investigation required	12/12/2017	Hydrocarbon-contaminated groundwater (such as from petrol or diesel) is present in groundwater beneath a former service station to the north, and beneath Albany Highway to the west, and is likely to extend beneath this site.
31/10/2017	537 Lake Rd Seville Grove 6112 WA	Remediated for restricted use	24/11/2021	Hydrocarbons (such as from petrol and diesel) are present in soil and groundwater at localised locations beneath the site.
3/11/2017	94 Kitchener Rd Alfred Cove 6154 WA	Classification timeframe extended under s.14(1)(b)		
6/11/2017	882 Abernethy Rd High Wycombe 6057 WA	Contaminated - remediation required	18/11/2020	Hydrocarbons, such as from diesel and oil, are present in shallow soils in multiple locations across the site associated with rail yard-related activities, such as locomotive refuelling. Perfluoroalkyl and polyfluoroalkyl substances (such as those found in fire-fighting foams), and hydrocarbons, such as from diesel, are present in groundwater beneath the site. Light non-aqueous phase liquid (i.e. liquid diesel) is present in groundwater adjacent to the bulk fuel pump house and the 'standard gauge trip services' facility.
7/11/2017	99 McCabe St Mosman Park 6012 WA	Decontaminated	19/12/2017	Following remediation, no contamination remains at the site.
10/11/2017	8 B South Western Hwy Boyanup 6237 WA	Possibly contaminated - investigation required	20/12/2017	Hydrocarbons (such as from petrol) are present in groundwater beneath the site near the eastern boundary.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
16/11/2017	2 Ozymanney St Hamilton Hill 6163 WA	Decontaminated	23/09/2020	Following remediation, no significant contamination remains at the site that poses an unacceptable risk to human health or ecological receptors based on advice from Department of Health.
17/11/2017	Bannister Rd Canning Vale 6155 WA	Possibly contaminated - investigation required	9/01/2018	Nutrients (such as ammonia) are present in groundwater at high concentrations adjacent to this site's boundary and are likely to extend beneath this site.
17/11/2017	Lots 104 & 105 Brand Highway Beermulla 6503 WA	Possibly contaminated - investigation required	20/12/2017	Buried waste (such as poultry carcasses and other wastes) is present in burial pits beneath the site.
17/11/2017	120 Douglas Rd Beermullah 6503 WA	Possibly contaminated - investigation required	20/12/2017	Buried waste (such as poultry carcasses and other wastes) is present in burial pits beneath the site.
27/11/2017	90 Bickley Rd Beckenham 6107 WA	Decontaminated	4/02/2020	Following remediation, no contamination remains at the site.
30/11/2017	178 Claisebrook Rd Perth 6000 WA	Possibly contaminated - investigation required	2/01/2018	Chlorinated hydrocarbons (such as from dry cleaning solvents) are present in soil vapour beneath the site and have also been identified in indoor air.
6/12/2017	60 Russell St Morley 6062 WA	Possibly contaminated - investigation required	3/03/2022	Hydrocarbons (such as from petrol/diesel) are present in groundwater beneath the northern portion of the site.
7/12/2017	Mining Tenement L59/151 Daggar Hills 6638 WA	Possibly contaminated - investigation required	22/10/2018	Hydrocarbons (such as from diesel) are present in soils beneath the location of the former power generators.
7/12/2017	11 Broadway Nedlands 6009 WA	Remediated for restricted use	13/03/2023	Hydrocarbons (such as from petrol or diesel) are present in groundwater beneath the adjacent former service station to the north and extends to the south beneath this site.
7/12/2017	Lots 2 & 66 Broadway Street Nedlands 6009 WA	Remediated for restricted use	8/03/2023	Hydrocarbons (such as from petrol or diesel) are present in groundwater beneath the adjacent former service station to the north and extends to the south beneath this site.
7/12/2017	Broadway Nedlands 6009 WA	Report not substantiated	8/03/2023	No known contamination has been identified.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
7/12/2017	Lots 90 & 91 Picton Rd Carey Park 6230 WA	Remediated for restricted use	12/03/2019	Fragments of asbestos-containing material remain in the south west corner of the site beneath a geotextile warning barrier layer.
12/12/2017	14730 Great Northern Hwy Walebing 6510 WA	Remediated for restricted use	3/04/2019	The Organochloride pesticides aldrin and dieldrin are present in soil beneath the central western portion of the site.
12/12/2017	123 Helena St Midland 6056 WA	Remediated for restricted use	8/01/2020	Nutrients and metals (copper and zinc) are present in soils beneath the 'bus way' area in the eastern portion of the site. Nutrients and metals (copper and zinc) are present in groundwater down hydraulic gradient (west portion) beneath the site.
21/12/2017	Albany Hwy Mount Melville 6330 WA	Possibly contaminated - investigation required	7/02/2018	Hydrocarbon-contaminated groundwater (such as from petrol and diesel) is present beneath the adjacent former service station (the source site), and extends to the north-east beneath this site.
21/12/2017	4 Ramsay St Norseman 6443 WA	Classification timeframe extended under s.14(1)(b)		
21/12/2017	52 Wilson St Wyalkatchem 6485 WA	Classification timeframe extended under s.14(1)(b)		
21/12/2017	18 Williams St Brookton 6306 WA	Classification timeframe extended under s.14(1)(b)		
21/12/2017	111 A Wilson St South Kalgoorlie 6430 WA	Classification timeframe extended under s.14(1)(b)		
21/12/2017	129 Coolibah Dr Kununurra 6743 WA	Classification timeframe extended under s.14(1)(b)		
22/12/2017	259 Webberton Rd Wonthella 6530 WA	Possibly contaminated - investigation required	24/01/2018	Nutrients (such as from waste water) have been detected in groundwater beneath the site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
22/12/2017	37 Davies St Bridgetown 6255 WA	Classification timeframe extended under s.14(1)(b)		
2/01/2018	Lot 21 On Diagram 19887 Glenfield 6532	Possibly contaminated - investigation required	7/02/2018	Nutrients (such as from waste water) have been detected in groundwater beneath the site.
2/01/2018	56 The Esplanade Esperance 6450 WA	Possibly contaminated - investigation required	7/02/2018	Hydrocarbons (such as from petrol) are present in soil and groundwater beneath the eastern portion of site at the location of former fuel storage and dispensing infrastructure. However, the nature and extent of contamination has not been fully investigated.
2/01/2018	2 Moorland Loop Gosnells 6110 WA	Decontaminated	14/04/2021	Ammonia, iron and aluminium identified in groundwater above aesthetic criteria, but are unlikely to pose a health risk to humans if used for non-potable purposes.
16/01/2018	4 A Adams St O'Connor 6163 WA	Contaminated - restricted use	30/06/2020	Per- and poly-fluoroalkyl substances (PFAS, such as from fire-fighting foams) are present in groundwater beneath the site and extend off-site to the west/north-west.
22/01/2018	108 Poole St Welshpool 6106 WA	Contaminated - restricted use	18/08/2011	Asbestos and hydrocarbons (such as from petrol, diesel or oil) are present in soils on the site, contained beneath a bitumen hardcover. Further investigations are required to determine the extent of hydrocarbon impacts in soil and groundwater.
23/01/2018	200 Lesmurdie Rd Lesmurdie 6076 WA	Decontaminated	13/03/2018	Following remediation, no identified contamination remains at the site.
24/01/2018	Lot 9109 On Deposited Plan 419061 Dalyellup 6230 WA	Possibly contaminated - investigation required	5/11/2020	The site predominantly comprises endemic bushland with a portion of the western area of the site previously used for activities associated with the adjacent former Waste Residue Disposal Facility. Treated solid residues were visually identified on the ground surface and at shallow depths in localised areas where the historical activities had occurred. Metals are also present in groundwater below the site.
24/01/2018	Toodyay Rd Stratton 6056 WA	Classification timeframe extended under s.14(1)(b)		
30/01/2018	Lot 333 on Deposited Plan 55302 Kunawarriritji 0872 WA	Possibly contaminated - investigation required	1/02/2019	Hydrocarbon (such as from diesel/oil) impacted soil remains on site in the vicinity of the power station. Groundwater has not been investigated.
1/02/2018	Great Eastern Hwy Midvale 6056 WA	Remediated for restricted use	22/02/2018	Hydrocarbon-impacted soil (such as from petrol and diesel) remains in the vicinity of the former tank pit at the northern boundary of the road reserve.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
6/02/2018	179 Jackson Rd Oldbury 6121 WA	Possibly contaminated - investigation required	23/03/2018	Unauthorised disposal of construction and demolition waste including asbestos-containing material (ACM) has occurred on this site.
6/02/2018	8883 Bisdee Rd Millendon 6056 WA	Possibly contaminated - investigation required	21/10/2020	Hydrocarbons (such as from diesel or oil), metals (such as cadmium and lead) and fragments of asbestos-containing material are present within soils in isolated areas of the site.
6/02/2018	48 Kelvin Rd Maddington 6109 WA	Possibly contaminated - investigation required	21/03/2019	Lead crucibles (such as from a mining process) were previously stored on soils at this site. The lead crucibles and 0.5 metres of impacted soil have been removed, but groundwater quality at the site has not been investigated.
9/02/2018	72 Fremantle Rd Gosnells 6110 WA	Report not substantiated	26/03/2018	Following enquiries, no contamination has been identified.
13/02/2018	11 Peel Tce Northam 6401 WA	Contaminated - restricted use	20/10/2022	Hydrocarbons (such as from petrol or diesel) are present in groundwater beneath adjacent land which extends to the north to beneath this the site.
19/02/2018	13 Allendale Ent North Lake 6163 WA	Classification timeframe extended under s.14(1)(b)		
19/02/2018	3 Cheshunt Gdns North Lake 6163 WA	Classification timeframe extended under s.14(1)(b)		
19/02/2018	5a Cheshunt Gdns North Lake 6163 WA	Classification timeframe extended under s.14(1)(b)		
19/02/2018	5b Cheshunt Gdns North Lake 6163 WA	Classification timeframe extended under s.14(1)(b)		

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
19/02/2018	7 Cheshunt Gdns North Lake 6163 WA	Classification timeframe extended under s.14(1)(b)		
19/02/2018	8 Cheshunt Gdns North Lake 6163 WA	Classification timeframe extended under s.14(1)(b)		
19/02/2018	10 Cheshunt Gdns North Lake 6163 WA	Classification timeframe extended under s.14(1)(b)		
19/02/2018	12 Cheshunt Gdns North Lake 6163 WA	Classification timeframe extended under s.14(1)(b)		
19/02/2018	Cheshunt Gdns road reserve North Lake 6163 WA	Classification timeframe extended under s.14(1)(b)		
19/02/2018	181 Louisa Cir Morangup 6083 WA	Decontaminated	18/09/2018	Following remediation, no contamination remains at the site.
21/02/2018	15 Symmons St Bunbury 6230 WA	Report not substantiated	7/04/2018	No substantial evidence of contamination has been identified.
22/02/2018	LOT 115 ON PLAN 69110 Leda 6170 WA	Possibly contaminated - investigation required	26/04/2018	Sulfate, ammonia/ammonium, chloride, nitrate, arsenic, copper and manganese are present in groundwater beneath this site.
22/02/2018	LOT 503 ON PLAN 56798 Leda 6170 WA	Possibly contaminated - investigation required	26/04/2018	Sulfate, ammonia/ammonium, chloride, nitrate, arsenic, copper and manganese are present in groundwater beneath this site.
22/02/2018	LOT 504 ON PLAN 56798 Leda 6170 WA	Possibly contaminated - investigation required	26/04/2018	Sulfate, ammonia/ammonium, chloride, nitrate, arsenic, copper and manganese are present in groundwater beneath this site.
22/02/2018	LOT 505 ON PLAN 56798 Leda 6170 WA	Possibly contaminated - investigation required	26/04/2018	Sulfate, ammonia/ammonium, chloride, nitrate, arsenic, copper and manganese are present in groundwater beneath this site.
22/02/2018	LOT 776 ON PLAN 3893 Leda 6170 WA	Possibly contaminated - investigation required	26/04/2018	Sulfate, ammonia/ammonium, chloride, nitrate, arsenic, copper and manganese are present in groundwater beneath this site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
22/02/2018	851 Mandurah Rd Baldivis 6171 WA	Decontaminated	26/04/2018	Following remediation, no contamination remains at the site.
23/02/2018	144 Carrington St O'Connor 6163 WA	Decontaminated	10/06/2020	Following remediation, no contamination remains at the site.
26/02/2018	328 Gibb Road Metricup 6280 WA	Remediated for restricted use	13/08/2020	All visible asbestos-containing material (ACM) fragments have been collected and removed from the site. However, ACM material may remain on site within soil.
27/02/2018	1514 Eradu North Rd Ambania 6632 WA	Contaminated - restricted use	5/04/2018	Hydrocarbons (such as from waste oil) are present in soils localised around the underground storage tank and associated infrastructure.
27/02/2018	Lot 11484 on Deposited Plan 215624 Eneabba 6518 WA	Contaminated - restricted use	5/04/2018	Hydrocarbons (such as from waste oil) are present in soils localised around the underground storage tank and associated infrastructure.
27/02/2018	6018 Brand Hwy Red Gully 6503 WA	Contaminated - restricted use	5/04/2018	Hydrocarbons (such as from waste oil) are present in soils localised around the underground storage tank and associated infrastructure.
6/03/2018	350 Jacobs Well Rd Morbinning 6304 WA	Classification timeframe extended under s.14(1)(b)		
6/03/2018	Kerosene Lane Leda 6170 WA	Possibly contaminated - investigation required	26/04/2018	Sulfate, ammonia/ammonium, chloride, nitrate, arsenic, copper and manganese are present in groundwater beneath this site.
7/03/2018	13 Mudlark Pl Vasse 6280 WA	Report not substantiated	26/03/2018	No contamination has been identified.
7/03/2018	Lot 105 on Plan 213911 Roebourne 6718	Report not substantiated	16/04/2018	No contamination has been identified.
8/03/2018	545 Gale Rd Kaloorup 6280 WA	Possibly contaminated - investigation required	12/04/2018	Unauthorised disposal of wastes including building rubble has occurred on this site. However, soil and groundwater quality at the site has not been investigated.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
8/03/2018	328 Gibb Road Metricup 6280 WA	Remediated for restricted use	13/08/2020	All visible asbestos-containing material (ACM) fragments have been collected and removed from the site. However, ACM material may remain on site within soil.
12/03/2018	6 Austral Pde East Bunbury 6230 WA	Remediated for restricted use	13/08/2020	Following remediation, hydrocarbons (such as from petrol, diesel or oil) remain present in soil beneath the location of former underground fuel storage tanks in the north east and central east portions of the site.
13/03/2018	Lot 115 on P69110 Kerosene Lane Leda 6170 WA	Possibly contaminated - investigation required	26/04/2018	Sulfate, ammonia/ammonium, chloride, nitrate, arsenic, copper and manganese are present in groundwater beneath this site.
20/03/2018	Albany Hwy Mount Melville 6330 WA	Possibly contaminated - investigation required	7/02/2018	Hydrocarbon-contaminated groundwater (such as from petrol and diesel) is present beneath the adjacent former service station (the source site), and extends to the north-east beneath this site.
20/03/2018	130 Rendezvous Rd Vasse 6280 WA	Possibly contaminated - investigation required	26/03/2018	A plume of metals, aromatic hydrocarbons (benzene) and chlorinated hydrocarbons (such as from solvents and their breakdown products) in groundwater has migrated in a north north-westerly direction from the waste facility to the south and is likely to extend to beneath this site.
20/03/2018	118 Rendezvous Rd Vasse 6280 WA	Possibly contaminated - investigation required	26/03/2018	A plume of metals, aromatic hydrocarbons (benzene) and chlorinated hydrocarbons (such as from solvents and their breakdown products) in groundwater has migrated in a north north-westerly direction from the waste facility to the south and is likely to extend to beneath this site.
20/03/2018	98 Rendezvous Rd Vasse 6280 WA	Possibly contaminated - investigation required	26/03/2018	A plume of metals, aromatic hydrocarbons (benzene) and chlorinated hydrocarbons (such as from solvents and their breakdown products) in groundwater has migrated in a north north-westerly direction from the waste facility to the south and is likely to extend to beneath this site.
20/03/2018	95 Rendezvous Rd Vasse 6280 WA	Contaminated - restricted use	26/03/2018	A plume of metals, aromatic hydrocarbons (benzene) and chlorinated hydrocarbons (such as from solvents and their breakdown products) is present in groundwater beneath this site that has migrated in a north north-westerly direction from the adjacent waste facility to the south.
20/03/2018	82 Rendezvous Rd Vasse 6280 WA	Contaminated - restricted use	26/03/2018	A plume of metals, aromatic hydrocarbons (benzene) and chlorinated hydrocarbons (such as from solvents and their breakdown products) is present in groundwater beneath this site that has migrated in a north north-westerly direction from the adjacent waste facility to the south.
20/03/2018	70 Rendezvous Rd Vasse 6280 WA	Contaminated - restricted use	26/03/2018	A plume of metals, aromatic hydrocarbons (benzene) and chlorinated hydrocarbons (such as from solvents and their breakdown products) is present in groundwater beneath this site that has migrated in a north north-westerly direction from the adjacent waste facility to the south.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
20/03/2018	62 Rendezvous Rd Vasse 6280 WA	Contaminated - restricted use	26/03/2018	A plume of metals, aromatic hydrocarbons (benzene) and chlorinated hydrocarbons (such as from solvents and their breakdown products) is present in groundwater beneath this site that has migrated in a north north-westerly direction from the adjacent waste facility to the south.
20/03/2018	50 Rendezvous Rd Vasse 6280 WA	Contaminated - restricted use	26/03/2018	A plume of metals, aromatic hydrocarbons (benzene) and chlorinated hydrocarbons (such as from solvents and their breakdown products) is present in groundwater beneath this site that has migrated in a north north-westerly direction from the adjacent waste facility to the south.
20/03/2018	Lot 102 Sutton / Cockburn Roads Naval Base 6165 WA	Possibly contaminated - investigation required	6/08/2020	Aluminium, vanadium, molybdenum and arsenic are present in groundwater beneath the site.
21/03/2018	Irene St Castletown 6450 WA	Remediated for restricted use	9/06/2022	Hydrocarbons (such as from petrol, diesel and oil) are present in groundwater beneath the site.
21/03/2018	Lot 115 on P69110 Kerosene Lane Leda 6170 WA	Possibly contaminated - investigation required	26/04/2018	Sulfate, ammonia/ammonium, chloride, nitrate, arsenic, copper and manganese are present in groundwater beneath this site.
28/03/2018	2118 Top Beverley-york Rd Mount Hardey 6302 WA	Possibly contaminated - investigation required	15/05/2018	Unauthorised storage of waste material has occurred on this site. Some material remains on site in a former dam located on the eastern portion of the property.
3/04/2018	61 Wattleup Rd Wattleup 6166 WA	Report not substantiated	28/03/2019	Following enquiries, no significant secondary evidence of contamination has been identified at the site.
4/04/2018	3 Uglow St Lockyer 6330 WA	Contaminated - remediation required	22/10/2018	Asbestos and lead are present in surface soils.
5/04/2018	Lots 101 & 244 Wagerup 6215 WA	Remediated for restricted use	4/01/2023	Mineral sands process tailings, which may contain elevated amounts of radioactive minerals, have been buried at the site at a depth of at least 2 metres below the surface.
16/04/2018	1 Killarney St Mount Hawthorn 6016 WA	Decontaminated	13/08/2019	Following remediation, no contamination remains at the site.
17/04/2018	24517 South Western Hwy Bridgetown 6255 WA	Report not substantiated	31/05/2018	No contamination has been identified at the site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
18/04/2018	4040 Great Northern Hwy Muchea 6501 WA	Possibly contaminated - investigation required	17/05/2018	Soil is suspected to be impacted with elevated concentrations of metals and nutrients from landfilling waste stockpiles formerly located on the site.
24/04/2018	Lot 18 Plan 220344 South Murchison 6635 WA	Possibly contaminated - investigation required	29/05/2018	Hydrocarbons (such as from diesel and oil) are present in shallow soils at locations associated with fuel storage and vehicle maintenance.
24/04/2018	113 Great Eastern Hwy Rivervale 6103 WA	Possibly contaminated - investigation required	9/10/2019	Hydrocarbons (such as from petrol) are present in groundwater beneath the north west portion of the site and extending off site to the west. The extent of these off-site impacts have not been fully delineated.
25/04/2018	2927 Toodyay Rd Gidgegannup 6083 WA	Possibly contaminated - investigation required	31/05/2018	Disposal of building wastes material has occurred on this site. Asbestos-containing material was identified in soil at the site.
26/04/2018	21 Combes Dr Merredin 6415 WA	Possibly contaminated - investigation required	23/08/2018	Hydrocarbons (such as from oil) are present in surface soils at the site.
27/04/2018	175 Kwinana Beach Rd Kwinana Beach 6167 WA	Possibly contaminated - investigation required	31/08/2018	Ammonia, sulfate, cobalt and nickel are present in groundwater beneath the adjacent Kwinana Nickel Refinery at 270 Patterson Road, Kwinana Beach (the source site) and extends west beneath this site.
27/04/2018	214 Patterson Rd Kwinana Beach 6167 WA	Possibly contaminated - investigation required	31/08/2018	Ammonia, sulfate, cobalt and nickel are present in groundwater beneath the adjacent Kwinana Nickel Refinery at 270 Patterson Road, Kwinana Beach (the source site) and extends west beneath this site.
27/04/2018	Lot 300 & 503 Great Eastern Highway Merredin 6415 WA	Possibly contaminated - investigation required	23/08/2018	Scattered asbestos containing material (ACM) fragments were identified in surface soil.
30/04/2018	Reserve 24966 Ngaanyatjarra-giles 0872 WA	Possibly contaminated - investigation required	15/03/2019	Hydrocarbon staining is visible in the surface soils adjacent to the power generator plant and in a supply line. The depth and extent of the staining is unknown.
1/05/2018	Lot 502 South Yuna 6532 WA	Possibly contaminated - investigation required	31/05/2018	Asbestos containing material was reported in surface soils at the site. The nature and extent of asbestos impacts remaining at the site is unknown.
1/05/2018	Lot 19 on P223186 Wagin 6315 WA	Possibly contaminated - investigation required	19/06/2018	Nutrients (such as phosphorous) and pathogens are present in treated wastewater on the site.
15/05/2018	10 Macpherson St Djugun 6725 WA	Remediated for restricted use	8/03/2023	Hydrocarbons (such as from aviation fuel or diesel) are present in soil and groundwater beneath a former fuel storage area on the southern portion of the site. Perfluoroalkyl and polyfluoroalkyl substances (PFAS) are present in soils beneath former fire training grounds located on the northern and south-western portion of the site. Groundwater in the vicinity of former fire training grounds is impacted with perfluoroalkyl and polyfluoroalkyl substances (PFAS).
16/05/2018	Adams St O'Connor 6163 WA	Possibly contaminated - investigation required	30/06/2020	Per- and polyfluoroalkyl substances (PFAS, such as from fire-fighting foams) are present in groundwater beneath the site. Further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
16/05/2018	58 Peel Rd O'Connor 6163 WA	Possibly contaminated - investigation required	30/06/2020	Per- and polyfluoroalkyl substances (PFAS, such as from fire-fighting foams) are present in groundwater beneath the site. Further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.
17/05/2018	309 West Coast Hwy Scarborough 6019 WA	Classification timeframe extended under s.14(1)(b)		
30/05/2018	501 Quinlan St Wongan Hills 6603 WA	Remediated for restricted use	11/03/2019	Hydrocarbons (such as from transformer oil) remain present in soil at depth within an isolated location.
5/06/2018	Mandurah Tce Mandurah 6210 WA	Possibly contaminated - investigation required	11/12/2012	Hydrocarbon-contaminated groundwater (such as from petrol or diesel) is present beneath the former service station on 119 and 121 Mandurah Terrace (the source site), and extends beneath this site.
7/06/2018	Lot 386 on DP 221146 Boodarie 6722 WA	Not contaminated - unrestricted use	25/03/2020	Investigations found that no contamination is present in soil or groundwater at the site.
11/06/2018	44 Barberry Way Bibra Lake 6163 WA	Possibly contaminated - investigation required	26/07/2018	Following a fire, lead contamination was identified on site.
11/06/2018	10 Main Gate Midland 6056 WA	Remediated for restricted use	11/07/2018	<p>Residual waste fill deposits containing metals, including mercury, and isolated areas of asbestos fibres remain at the site beneath and near the former Power House/Boiler House and Element Shop.</p> <p>Hydrocarbons (such as from petrol, diesel or oil) and chlorinated hydrocarbons (such as from solvents) are also present in soils in isolated areas. Any waste fill deposits outside the heritage areas described above are contained beneath warning barriers and/or clean fill cover of at least 0.5 metres depth.</p> <p>Chlorinated hydrocarbons (such as from solvents) and heavy metals are also present in groundwater beneath the southern and south-western portions of site.</p> <p>More information on the nature and extent of contamination at the site is provided in the Subsurface Constraints Register, which is publicly available from the Metropolitan Redevelopment Authority's website.</p>
13/06/2018	1 Sleat Road Applecross 6153 WA	Remediated for restricted use	2/07/2020	Hydrocarbons (such as from transformer oil) are present in soils beneath the electrical transformer on this site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
19/06/2018	77 Uduc Rd Harvey 6220 WA	Possibly contaminated - investigation required	1/08/2018	Hydrocarbons have been identified in groundwater beneath the central portion of the site at a depth of greater than 3 metres below ground level.
19/06/2018	4 Newell St Harvey 6220 WA	Possibly contaminated - investigation required	1/08/2018	Hydrocarbons have been identified in groundwater beneath the central portion of the site at a depth of greater than 3 metres below ground level.
27/06/2018	Reserve 8045 Ularring 6436 WA	Possibly contaminated - investigation required	1/08/2018	The site has historically been used as a battery and mineral processing facility with waste, scrap and tailings remaining at the site. Soil and groundwater quality has not been investigated.
27/06/2018	29672 Brand Hwy Yardarino 6525 WA	Possibly contaminated - investigation required	2/08/2018	Hydrocarbons remain present in soils.
28/06/2018	7 Macpherson St Djugun 6725 WA	Report not substantiated	2/08/2018	The site has been used for storage of chemicals and potentially as a service station more than 40 years ago. However no contamination has currently been identified.
3/07/2018	Reserve 9897 Mount Jackson 6426 WA	Possibly contaminated - investigation required	9/08/2018	The site has historically been used as a battery and mineral processing facility with waste, scrap and tailings remaining at the site. Soil and groundwater quality has not been investigated.
9/07/2018	309 West Coast Hwy Scarborough 6019 WA	Classification timeframe extended under s.14(1)(b)		
11/07/2018	43 Attfield St Maddington 6109 WA	Contaminated - restricted use	18/02/2021	Chlorinated hydrocarbons (such as from dry cleaning solvents) are present in groundwater and soil vapour beneath the former dry cleaner and neighbouring premises.
12/07/2018	1 Underwood Av Shenton Park 6008 WA	Possibly contaminated - investigation required	27/09/2018	Asbestos-containing material is present in soils across the site. Investigations have partially delineated the extent of asbestos containing material in some areas of the site however further investigations are required to determine the nature and extend across the site as a whole.
23/07/2018	35 Bussell Hwy Cowaramup 6284 WA	Remediated for restricted use	11/11/2020	The site has historically been used as an agricultural depot including fuel storage and retail.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
7/08/2018	40 Woolgar Av Merredin 6415 WA	Remediated for restricted use	10/06/2020	Asbestos containing materials (ACM) may be present in sub-surface soils at the site.
9/08/2018	Mining Tenement E59/1241 Yalgoo 6635 WA	Possibly contaminated - investigation required	2/09/2020	Surface water and soil at this site are impacted by metals, sulfate and salinity as a result of dewatering discharge. The extent impacts were inferred by areas of vegetation death and a visible salt crust on the ground surface. However, further investigation and delineation is required.
13/08/2018	311 Coolgardie-esperance Hwy Widgiemooltha 6443 WA	Possibly contaminated - investigation required	18/09/2018	The site has historically been used as a battery, mineral processing facility and waste disposal. Waste material and tailings remain at the site. Soil and groundwater quality has not been investigated.
14/08/2018	17 A Woolgar Av Merredin 6415 WA	Remediated for restricted use	17/06/2020	Asbestos containing materials (ACM) may be present in sub-surface soils at the site.
20/08/2018	1 North Rd Bassendean 6054 WA	Possibly contaminated - investigation required	4/10/2018	Hydrocarbon contaminated groundwater (such as from petrol or diesel) is present beneath the adjacent road reserve to the west, and is likely to extend beneath this site.
20/08/2018	3 North Rd Bassendean 6054 WA	Possibly contaminated - investigation required	4/10/2018	Hydrocarbon contaminated groundwater (such as from petrol or diesel) is present beneath the adjacent road reserve to the west, and is likely to extend beneath this site.
28/08/2018	6 Robson Way Murdoch 6150 WA	Not contaminated - unrestricted use	18/09/2019	Investigations have found that no significant contamination is present at the site.
28/08/2018	22 Purser Cove Murdoch 6150 WA	Not contaminated - unrestricted use	18/09/2019	Investigations have found that no significant contamination is present at the site.
28/08/2018	206 Wesco Rd Nowergup 6032 WA	Remediated for restricted use	17/08/2022	Nutrients, metals and per-and poly-fluoroalkyl substances (PFAS) (such as from PFAS-containing waste) are present in groundwater in localised areas beneath the site. Marginally elevated concentrations of e.coli are present in groundwater in one localised area near a waste stockpile in the southern portion of the site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
28/08/2018	5895 Great Eastern Hwy Mundaring 6073 WA	Possibly contaminated - investigation required	1/10/2018	Hydrocarbon-impacted groundwater remains in-situ beneath the location of former underground fuel storage tanks in the western portion of the site at a depth of approximately 8.5 metres below ground surface.
28/08/2018	940 Coppin Rd Mundaring 6073 WA	Possibly contaminated - investigation required	1/10/2018	Hydrocarbon contaminated groundwater (such as from petrol) is present beneath the adjacent former service station (the source site), and is likely to extend beneath to the southern portion of this site.
29/08/2018	8 Lisford Av Two Rocks 6037 WA	Classification timeframe extended under s.14(1)(b)		
31/08/2018	73 Railway Pde Yarloop 6218 WA	Remediated for restricted use	29/10/2018	Asbestos-containing material, lead and hydrocarbons have been identified in soil in the central portion of the site. Access to the impacted soil is restricted by the application of a geo-fabric layer, crushed compacted limestone and clean fill sand to ground surface level.
31/08/2018	141 Rendezvous Rd Vasse 6280 WA	Possibly contaminated - investigation required	11/10/2018	Perfluoroalkyl and polyfluoroalkyl substances (PFAS), such as those found in non-stick cookware; fabrics, furniture and carpets treated with stain protection; and food packaging, have been identified in a sample of groundwater collected from a private bore in the north-eastern corner of this site. PFAS have also been identified in groundwater adjacent to this site to the north and east.
4/09/2018	92 Gardiner St Moora 6510 WA	Remediated for restricted use	21/01/2020	Hydrocarbon contaminated groundwater (such as from petrol) is present beneath the adjacent service station (the source site) and extends beneath this site. Chlorinated hydrocarbons were identified in groundwater beneath an access road (an affected site) located immediately south of the service station. Chlorinated hydrocarbons were not detected beneath other parcels of land at concentrations above non-potable groundwater use criteria.
7/09/2018	1346 Highway road reserve Cannington 6107 WA	Remediated for restricted use	18/10/2018	Volatile organic compounds (including chlorinated hydrocarbons and petroleum hydrocarbons) are present in groundwater extending as a plume beneath this site from the neighbouring service station at Lot 2, 1346 Albany Highway Cannington.
17/09/2018	69 Hutt St Northam 6401 WA	Report not substantiated	9/11/2018	No contamination has been identified.
17/09/2018	Lot 1001 on DP 422668 Northam 6401 WA	Contaminated - remediation required	18/02/2021	Unauthorised disposal of wastes including asbestos-containing material (ACM) has occurred on this site. ACM remains present within stockpiles and subsurface soils across the site.
18/09/2018	Lot 300 on Plan 411247 South Hedland 6722 WA	Possibly contaminated - investigation required	23/10/2018	Hydrocarbons (such as from petrol) are present in groundwater beneath the east and south-eastern portions of the site. Soil vapour has not been investigated and groundwater requires further investigation off-site to the east and south east.
18/09/2018	35 Roberts St South Hedland 6722 WA	Possibly contaminated - investigation required	23/10/2018	Hydrocarbons (such as from petrol) are present in groundwater beneath the east and south-eastern portions of the site. Soil vapour has not been investigated and groundwater requires further investigation off-site to the east and south east.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
18/09/2018	Hamilton Rd Road Reserve South Hedland 6722 WA	Possibly contaminated - investigation required	23/10/2018	Hydrocarbons (such as from petrol) are present in groundwater beneath the east and south-eastern portions of the site. Soil vapour has not been investigated and groundwater requires further investigation off-site to the east and south east.
19/09/2018	Lot 110 Marble Bar 6760 WA	Classification timeframe extended under s.14(1)(b)		
21/09/2018	205 Abercrombie Rd Hope Valley 6165 WA	Possibly contaminated - investigation required	25/10/2018	Groundwater beneath the site is affected by an alkaline plume migrating from Lot 501 Anketell Road, Hope Valley.
21/09/2018	Abercrombie Rd road reserve Hope Valley 6165 WA	Possibly contaminated - investigation required	25/10/2018	Groundwater beneath the site is affected by an alkaline plume migrating from Lot 501 Anketell Road, Hope Valley.
26/09/2018	11 Hickory Rd Quinns Rocks 6030 WA	Not contaminated - unrestricted use	30/07/2019	Investigations found that no contamination is present at the site.
26/09/2018	Great Eastern Hwy Ghooli 6426 WA	Possibly contaminated - investigation required	11/07/2019	Hydrocarbons (such as from oil) and metals have been detected in soils.
2/10/2018	41 D Delawney St Balcatta 6021 WA	Possibly contaminated - investigation required	14/07/2022	Fire-fighting foams containing perfluoroalkyl and polyfluoroalkyl substances (PFAS) are likely to have been stored and discharged to the environment at the site. Investigations are required to determine the nature and extent of potential impacts, and to inform assessment of potential risks.
11/10/2018	Lot 89 One Arm Point Rd Dampier Peninsula 6725 WA	Classification timeframe extended under s.14(1)(b)		
11/10/2018	Reserve 38399 and Portion of Frazier Downs Station Lagrange 6725 WA	Classification timeframe extended under s.14(1)(b)		
12/10/2018	38 Bickley St Naval Base 6165 WA	Possibly contaminated - investigation required	17/04/2019	Elevated concentrations of aluminium and arsenic are potentially present in groundwater beneath the site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
12/10/2018	Bickley St road reserve Naval Base 6165 WA	Possibly contaminated - investigation required	17/04/2019	Elevated concentrations of aluminium and arsenic are potentially present in groundwater beneath the site.
12/10/2018	Henry St Naval Base 6165 WA	Possibly contaminated - investigation required	17/04/2019	Elevated concentrations of aluminium and arsenic are potentially present in groundwater beneath the site.
12/10/2018	Coolgardie-Esperance Hwy Coolgardie 6429 WA	Possibly contaminated - investigation required	26/11/2018	Arsenic is present in surface soils at concentrations above the ecological assessments levels.
18/10/2018	112 Doghill Rd Baldivis 6171 WA	Possibly contaminated - investigation required	30/11/2018	Asbestos containing material may be present in surface soils.
23/10/2018	Lot 373 on Deposited Plan 220266 Dampier Peninsula 6725 WA	Remediated for restricted use	7/02/2023	Asbestos-impacted fill is buried in a containment cell beneath this site, below a geofabric warning barrier and a minimum of 0.5 metres of clean fill.
23/10/2018	91 Graham St Condingup 6450 WA	Possibly contaminated - investigation required	24/10/2018	Hydrocarbons (such as from petrol or diesel) were visually identified on surface soil surrounding the location of an above ground fuel storage tank located at the site.
25/10/2018	3017 Village Rd Burrup 6714 WA	Contaminated - remediation required	6/02/2023	Site investigations have found ammonia, nitrate and nitrite to be present in soils, groundwater, surface water and sediments at the site and off-site.
29/10/2018	6 Clavering Rd Bayswater 6053 WA	Possibly contaminated - investigation required	2/11/2021	Per-and poly-fluoroalkyl substances (PFAS) (such as from fire-fighting foams) are present in soil, sediments and groundwater at the site. Further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential environmental risks.
30/10/2018	676 Albany Hwy Bedfordale 6112 WA	Possibly contaminated - investigation required	20/11/2018	Methyl tert-butyl ether (MTBE) (a fuel additive) is present in groundwater beneath the site. It is suspected to have originated from a service station to the south-east.
2/11/2018	Lot 145 Lombadina Rd Dampier Peninsula 6725 WA	Classification timeframe extended under s.14(1)(b)		

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
2/11/2018	85 Derby-gibb River Rd Derby 6728 WA	Classification timeframe extended under s.14(1)(b)		
5/11/2018	Reserve 24966 Ngaanyatjarra-giles 0872 WA	Possibly contaminated - investigation required	15/03/2019	Hydrocarbon staining is visible in the surface soils adjacent to the power generator plant and in a supply line. The depth and extent of the staining is unknown.
6/11/2018	55 Hutt St Northam 6401 WA	Decontaminated	14/04/2021	Following remediation, no known contamination remains present at the site.
13/11/2018	Beagle Bay Rd Dampier Peninsula 6725 WA	Classification timeframe extended under s.14(1)(b)		
19/11/2018	Elverd St Ravensthorpe 6346 WA	Possibly contaminated - investigation required	19/06/2019	Mine tailings containing elevated levels of acidity and metals (such as copper) are present at the site. The tailings have historically been uncontained and have dispersed via wind and water erosion. Dams at the site which receive surface water runoff from the tailings storage areas have elevated levels of acidity and metals (such as copper, nickel and zinc).
20/11/2018	Lot 9077 on Deposited Plan 60716 Road Portion, Dalyellup 6230 WA	Not contaminated - unrestricted use	31/07/2019	Soil or groundwater investigations have not been undertaken at the site. However, a review of available information has found there are no reasonable grounds to suspect that contamination is present in the material comprising the road, or in soils beneath the road.
21/11/2018	4 Leonora St Yakamia 6330 WA	Remediated for restricted use	17/07/2019	Petroleum hydrocarbons (such as from petrol and diesel) are present in groundwater beneath the former fuel depot located at 107 Chester Pass Road, Milpara, which extends as a plume in a south-easterly direction beneath this site.
21/11/2018	6 Leonora St Yakamia 6330 WA	Remediated for restricted use	17/07/2019	Petroleum hydrocarbons (such as from petrol and diesel) are present in groundwater beneath the former fuel depot located at 107 Chester Pass Road, Milpara, which extends as a plume in a south-easterly direction beneath this site.
21/11/2018	8 Leonora St Yakamia 6330 WA	Remediated for restricted use	17/07/2019	Petroleum hydrocarbons (such as from petrol and diesel) are present in groundwater beneath the former fuel depot located at 107 Chester Pass Road, Milpara, which extends as a plume in a south-easterly direction beneath this site.
21/11/2018	Lot 9000 on Plan 54691 Yakamia 6330 WA	Remediated for restricted use	17/07/2019	Petroleum hydrocarbons (such as from petrol and diesel) are present in groundwater beneath the former fuel depot located at 107 Chester Pass Road, Milpara, which extends as a plume in a south-easterly direction beneath this site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
21/11/2018	40 Leslie Rd Wandi 6167 WA	Possibly contaminated - investigation required	2/01/2019	Unauthorised disposal of wastes has occurred on the site including suspected asbestos. Soil and groundwater quality at the site has not been investigated.
23/11/2018	Lot 23982 Bulyee Rd, East Pingelly 6308 WA	Possibly contaminated - investigation required	2/01/2019	Asbestos-containing material is present in construction rubble waste used as fill at the site.
29/11/2018	766 King Rd Oldbury 6121 WA	Possibly contaminated - investigation required	29/01/2019	Asbestos-containing material is present in processing waste at the site.
29/11/2018	Lot 100 Barton Loop Kalumburu 6740 WA	Possibly contaminated - investigation required	10/01/2019	Localised hydrocarbon contamination is present on the site. Other contaminants associated with a former power station use may also be present in soil and groundwater at the site.
29/11/2018	Beechboro Rd Beechboro 6063 WA	Possibly contaminated - investigation required	16/01/2019	Hydrocarbons (such as from petrol/diesel) are present in soil and groundwater beneath the road reserve adjoining the service station.
5/12/2018	4A Modal Cr Canning Vale 6155 WA	Remediated for restricted use	17/01/2019	Residual hydrocarbon-impacted soil remain present beneath the existing electrical transformer located in the central portion of the site.
5/12/2018	5F Hastie Ct Somerville 6430 WA	Remediated for restricted use	17/01/2019	Residual hydrocarbon-impacted soil remain present beneath the existing electrical transformer located in the central portion of the site.
5/12/2018	36 Gwendoline Dr Beldon 6027 WA	Classification timeframe extended under s.14(1)(b)		
5/12/2018	Lot 51, No. 11 Riverway, Applecross 6153 WA	Remediated for restricted use	11/01/2019	Hydrocarbons (such as from oils) are present in soil beneath the site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
5/12/2018	12 Cressall Rd Balcatta 6021 WA	Remediated for restricted use	17/04/2019	Residual hydrocarbon-impacted soils remain present directly below the footprint of the existing electrical transformer (located in the north-west corner of Lot 51).
5/12/2018	47 Strickland Dr Dalwallinu 6609 WA	Remediated for restricted use	25/06/2019	Residual hydrocarbon-impacted soils remain present beneath the existing electrical transformer (located on the eastern boundary of Lot 5).
5/12/2018	11 Prendiville Av Ocean Reef 6027 WA	Remediated for restricted use	18/09/2019	Hydrocarbons (such as from transformer oil), are present in soils directly below the footprint of the existing electrical transformer.
5/12/2018	36 Berthold St Orelia 6167 WA	Report not substantiated	23/10/2019	No contamination has been identified.
6/12/2018	10 Dalby St Warwick 6024 WA	Remediated for restricted use	29/03/2019	Following limited remediation of the site, asbestos fragments remain in surface soils on the site.
7/12/2018	78 Adams Dr Welshpool 6106 WA	Remediated for restricted use	6/03/2019	Following remediation, hydrocarbons (such as from diesel or oil) remain present in soils at the site. Hydrocarbons and Metals remain present in groundwater beneath the site
10/12/2018	99 Kennedy St South Hedland 6722 WA	Report not substantiated	19/06/2019	No contamination has been identified.
12/12/2018	900 Woodlands Rd Stoneville 6081 WA	Remediated for restricted use	8/02/2019	Fragments of asbestos-containing material are present within surface soils across large portions of the site where buildings were historically demolished.
13/12/2018	Unallocated Crown Land, LOT 1146 ON PLAN 231889, Sandy Gully 6535 WA	Contaminated - remediation required	16/09/2020	Significant stockpiles of lead tailings are present on this site. Baseline groundwater investigations have identified the presence of metals in groundwater beneath the site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
13/12/2018	5680 Drage St Northampton 6535 WA	Possibly contaminated - investigation required	7/03/2019	Lead tailings which have originated from the adjacent Lot 1146 are present on the surface of the site in the south-west corner.
18/12/2018	6 Hampton St Burswood 6100 WA	Possibly contaminated - investigation required	14/05/2020	Hydrocarbons (such as from transformer oil) are present in surface soils beneath the pad mounted transformer.
18/12/2018	367 Albany Hwy Orana 6330 WA	Report not substantiated	14/01/2019	No contamination has been identified.
2/01/2019	Lot 32 Christmas Creek-Beefwood Park Rd Mueller Ranges 6770 WA	Possibly contaminated - investigation required	3/04/2019	Hydrocarbons (such as from oil/diesel) have been visually identified on the ground in the power station compound near generators, and above ground fuel storage tank and a fill point.
2/01/2019	Tjuntjuntjarra Community, Plumridge Lakes 6431 WA	Possibly contaminated - investigation required	15/02/2019	Hydrocarbons (such as from oil/diesel) have been visually identified in soils at the power station compound, adjacent to the truck connection point and fill point.
2/01/2019	Lot 8 Landor-Mount Augustus Rd Gascoyne River 6705 WA	Possibly contaminated - investigation required	1/02/2019	Evidence of diesel and oil spills were observed on unsealed ground around the remote fill points and fuel storage tanks.
2/01/2019	Pia Wadjari Remote Aboriginal Community, Lot 7, Crown Reserve 297, South Murchison 6635 WA	Possibly contaminated - investigation required	27/01/2016	Hydrocarbons (such as diesel) are present in soils to a depth of 2 metres below ground level, in the vicinity of the diesel generator, in the south eastern portion of the site.
2/01/2019	Lot 110 Marble Bar 6760 WA	Classification timeframe extended under s.14(1)(b)		
2/01/2019	within Lot 333 on Deposited Plan 55302, Kunawarritji 0872 WA	Possibly contaminated - investigation required	1/02/2019	Hydrocarbon (such as from diesel/oil) impacted soil remains on site in the vicinity of the power station. Groundwater has not been investigated.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
2/01/2019	Lot 9 Blackstone-Warburton Rd Blackstone WA	Possibly contaminated - investigation required	8/02/2019	Hydrocarbons (such as from oil/diesel) have been visually identified on the ground adjacent to the fill point and tanker unloading area.
2/01/2019	Lot 55 Great Central Rd Cosmo Newbery 6440 WA	Report not substantiated	19/02/2019	Hydrocarbons (such as from petrol/oil/diesel) were visually identified on surface soil surrounding the fill point, unloading area, oil storage, generator and above/underground ground storage tank.
2/01/2019	Gibb River Road Derby 6728 WA	Possibly contaminated - investigation required	8/02/2019	Hydrocarbons (such as from petrol/oil/diesel) were visually identified on surface soil surrounding the fill point and fuel dispensing pipes.
2/01/2019	10 Niyikina Rd St George Ranges 6728 WA	Possibly contaminated - investigation required	1/02/2019	Hydrocarbons (such as from oil/diesel) have been visually identified on the ground adjacent to the day tank, outside compound and fill point.
2/01/2019	Moongardie Aboriginal Community, Lot 787, Fitzroy Crossing 6765 WA	Possibly contaminated - investigation required	8/02/2019	Hydrocarbons (such as from oil/diesel) have been visually identified on surface soil surrounding the fill point, unloading area, oil storage, generator and fuel storage tanks.
2/01/2019	7 Tanami Rd Sturt Creek 6770 WA	Possibly contaminated - investigation required	4/02/2019	Hydrocarbons (such as from oil and diesel) were visually identified on surface soils in the power generation compound that extend to areas outside the compound.
2/01/2019	Lot 10 Dunham Dr Durack 6743 WA	Possibly contaminated - investigation required	15/02/2019	Hydrocarbons (such as from oil/diesel) have been visually identified on the ground adjacent to the day tank, outside compound and fill point.
2/01/2019	Galamunda Community, Lot 337, King Leopold Ranges 6728 WA	Possibly contaminated - investigation required	15/02/2019	Hydrocarbons (such as from petrol/oil/diesel) were visually identified on surface soil adjacent to the above ground storage tank.
2/01/2019	Imintji Community, Lot 503, Derby 6728 WA	Possibly contaminated - investigation required	8/02/2019	Hydrocarbons (such as from oil/diesel) have been visually identified on the ground adjacent to the fill point and tanker unloading area.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
2/01/2019	Innawonga Aboriginal Community, Lot 134, Rocklea 6751 WA	Possibly contaminated - investigation required	11/01/2023	Hydrocarbons (such as from petrol/oil/diesel) are present in soil, mainly surrounding above-ground pipes, diesel and lubricant oil drums and in an emergency liquid shut off area (ELSOA) located adjacent to the southern boundary of site.
2/01/2019	Jameson Aboriginal Community, Lot 9, Ngaanyatjarra-Giles 0872 WA	Possibly contaminated - investigation required	13/12/2021	Hydrocarbons (such as from oil/diesel) have been visually identified on the ground adjacent to the power station fill point and tanker unloading area in the northern portion of the site. Portions of the site have been used as a landfill for the disposal of various household and construction waste. Possible asbestos-containing materials have been identified on the surface of the current and former landfill and scrap vehicle areas.
2/01/2019	Jarlmandangah Aboriginal Community, Lot 237, Jarlmandangah 6728 WA	Possibly contaminated - investigation required	4/02/2019	Hydrocarbons (such as from petrol/oil/diesel) were visually identified on surface soil surrounding the tank, fill point and unloading area.
2/01/2019	Lot 275 Great Northern Hwy Camballin 6728 WA	Report not substantiated	12/02/2019	No contamination has been identified.
2/01/2019	Lot 11 St George Ranges 6728 WA	Possibly contaminated - investigation required	15/02/2019	Hydrocarbons (such as from oil or diesel) have been visually identified on the ground adjacent to the fill point and tanker unloading area.
2/01/2019	Kiwirrkurra Aboriginal Community, Lot 3, Gibson Desert North 0872 WA	Possibly contaminated - investigation required	19/02/2019	Minor hydrocarbons (such as from petrol, oil and diesel) were visually identified on surface soil surrounding the fill point, unloading area, oil storage, generator and above/underground ground storage tank.
2/01/2019	Kutkabubba Aboriginal Community, Lot 48, Kutkabubba 6646 WA	Report not substantiated	4/02/2019	No contamination has been identified.
2/01/2019	Glen Hill Road Lake Argyle 6743 WA	Possibly contaminated - investigation required	5/02/2019	Hydrocarbons (such as from oil/diesel) have been visually identified on the ground adjacent to the power station and associated fuel infrastructure.
2/01/2019	8 Lake Gregory Rd Sturt Creek 6770 WA	Possibly contaminated - investigation required	19/02/2019	Hydrocarbons (such as from petrol or diesel) are present in soils associated with fuel infrastructure.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
2/01/2019	Lot 1564 Mueller Ranges 6770 WA	Possibly contaminated - investigation required	12/02/2019	Hydrocarbons (such as from diesel and oil) were visually identified in surface soils beneath the diesel above-ground storage tank, generator door and surrounding the fuel storage drums.
2/01/2019	Lot 40 Cherrabun Rd St George Ranges 6728 WA	Possibly contaminated - investigation required	26/02/2019	Hydrocarbons (such as from oil/diesel) have been visually identified on the ground at a fill point and below a day tank.
2/01/2019	Lot 302 Durack 6743 WA	Report not substantiated	13/02/2019	No evidence of significant contamination has been identified.
2/01/2019	Yulga Jinna Aboriginal Community, Lot 57, Peak Hill 6642 WA	Possibly contaminated - investigation required	13/02/2019	Hydrocarbons (such as from diesel) were visually identified on surface soil outside the diesel above-ground storage tank bund and surrounding the transfer pump.
2/01/2019	Warakurna Aboriginal Community, Lot 9, Ngaanyatjarra-Giles 0872 WA	Possibly contaminated - investigation required	14/12/2021	Hydrocarbons (such as from oil and diesel) have been visually identified at the power station on the ground at and adjacent to fill point and generators. Portions of the site have been used as a landfill for the disposal of various household and construction waste. Possible asbestos-containing materials have been identified on the surface of the scrap vehicle areas.
2/01/2019	Lot 8 Warburton 6431 WA	Possibly contaminated - investigation required	16/12/2021	Hydrocarbons (such as from oil and diesel) have been visually identified on the ground near the fill point and beneath above-ground storage tanks. Portions of the site have been used as a landfill for the disposal of various household and construction waste. Possible asbestos-containing materials have been identified on the surface of the current and former landfill areas.
2/01/2019	Lot 108 Marble Bar 6760 WA	Possibly contaminated - investigation required	15/02/2019	Hydrocarbons (such as from oil and diesel) have been visually identified on the ground near the fill point, the unloading area, the transfer pump and an oil drum storage area.
2/01/2019	Lot 45 St George Ranges 6728 WA	Possibly contaminated - investigation required	15/02/2019	Hydrocarbons (such as from oil/diesel) have been visually identified on the ground adjacent to the above ground storage tank and fill point.
2/01/2019	Lot 9 Ngaanyatjarra-Giles 0872 WA	Possibly contaminated - investigation required	15/02/2019	Hydrocarbons (such as from oil or diesel) have been visually identified on the ground within and adjacent to the power station.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
2/01/2019	North West Coastal Highway Mingullatharndo 6718 WA	Possibly contaminated - investigation required	5/02/2019	Hydrocarbons (such as from petrol/oil/diesel) were visually identified on surface soil surrounding the fill point, generator shed and unloading area.
2/01/2019	Ngurawaana Aboriginal Community, Lot 244, Ngurrawaana 6716 WA	Possibly contaminated - investigation required	21/12/2022	Hydrocarbons (such as from petrol/oil/diesel) are present in soil, mainly surrounding a diesel storage tank within the southeast portion of the site.
2/01/2019	Great Northern Highway Fitzroy Crossing 6765 WA	Possibly contaminated - investigation required	5/02/2019	Hydrocarbons (such as from petrol/oil/diesel) were visually identified on surface soil surrounding the fill point.
2/01/2019	353 Derby Hwy Willare 6728 WA	Possibly contaminated - investigation required	1/02/2019	Hydrocarbons (such as from petrol/oil/diesel) were visually identified on surface soil surrounding the fill point.
2/01/2019	Lot 25 Mueller Ranges 6770 WA	Possibly contaminated - investigation required	15/02/2019	Hydrocarbons (such as from oil/diesel) have been visually identified on the ground adjacent to the fill point.
2/01/2019	Lot 2 Gibson Desert South 0872 WA	Possibly contaminated - investigation required	16/12/2021	Hydrocarbons (such as from oil/diesel) have been visually identified at the power station on the ground adjacent to the fill point. Portions of the site have been used as a landfill for the disposal of various household and construction waste. Possible asbestos-containing materials have been identified on the surface of the current and former landfill and scrap vehicle areas.
2/01/2019	Lot 9 Ngaanyatjarra-Giles 0872 WA	Possibly contaminated - investigation required	14/12/2021	Hydrocarbons (such as from oil/diesel) have been visually identified on the ground adjacent to the above ground storage tank and fill point. Portions of the site have been used as a landfill for the disposal of various household and construction waste. Possible asbestos-containing materials have been identified on the surface of the current and former landfill areas as well as the scrap vehicle storage areas.
2/01/2019	Lot 13 Telfer 6762 WA	Possibly contaminated - investigation required	15/02/2019	Hydrocarbons (such as from oil or diesel) have been visually identified on the ground adjacent to the fill point, generators, self bunded tanks and the tanker unloading area.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
2/01/2019	Lot 13 Telfer 6762 WA	Possibly contaminated - investigation required	15/02/2019	Hydrocarbons (such as from oil/diesel) have been visually identified on the ground adjacent to the fill point and tanker unloading area.
2/01/2019	Lot 14 Gibson Desert South 0872 WA	Report not substantiated	13/02/2019	No secondary signs of contamination have been identified.
2/01/2019	Lot 17 Gibb 6743 WA	Possibly contaminated - investigation required	15/02/2019	Hydrocarbons (such as from oil/diesel) have been visually identified on the ground at a fill point and below a day tank.
2/01/2019	Lot 26 Cherratta Rd Maitland 6714 WA	Possibly contaminated - investigation required	13/02/2019	Hydrocarbons (such as from oil/diesel) have been visually identified on surface soil surrounding the fill point, generator and oil storage tanks.
2/01/2019	Windidda Aboriginal Community, Lot 2, Lake Carnegie 6646 WA	Possibly contaminated - investigation required	13/02/2019	Hydrocarbons (such as from oil/diesel) have been visually identified on surface soil surrounding the storage tank.
2/01/2019	Lot 9 Ngaanyatjarra-Giles 0872 WA	Possibly contaminated - investigation required	13/02/2019	Hydrocarbons (such as from oil/diesel) have been visually identified on surface soil surrounding the fill point and generator.
2/01/2019	Lot 31 Mueller Ranges 6770 WA	Possibly contaminated - investigation required	15/02/2019	Hydrocarbons (such as from petrol, oil and diesel) were visually identified on surface soil surrounding the fill point, unloading area, oil storage, generator and above/underground ground storage tank
2/01/2019	Lot 11 Christmas Creek Rd St George Ranges 6728 WA	Possibly contaminated - investigation required	15/02/2019	Hydrocarbons (such as from oil or diesel) have been visually identified on the ground adjacent to the power station.
2/01/2019	Djugerari Aboriginal Community, Lot 89, St George Ranges 6728 WA	Report not substantiated	1/02/2019	No contamination has been identified.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
2/01/2019	Lot 149 Peedamulla 6710 WA	Possibly contaminated - investigation required	19/02/2019	Hydrocarbons (such as from oil and diesel) have been visually identified on the ground near the fill point, day tank and oil storage area.
2/01/2019	Lot 86 Mueller Ranges 6770 WA	Possibly contaminated - investigation required	15/02/2019	Hydrocarbons (such as from oil/diesel) have been visually identified on the ground at a fill point and below a day tank.
2/01/2019	Lot 33 Derby-gibb River Rd King Leopold Ranges 6728 WA	Possibly contaminated - investigation required	12/02/2019	Evidence of diesel and oil spillage were observed on unsealed ground adjacent to the power generator infrastructure.
2/01/2019	Marta Marta Aboriginal Community, Lot 98, De Grey 6722 WA	Possibly contaminated - investigation required	8/02/2019	Hydrocarbons (such as from oil/diesel) have been visually identified on the ground adjacent to the fill point and tanker unloading area.
2/01/2019	Lot 510 Mueller Ranges 6770 WA	Possibly contaminated - investigation required	15/02/2019	Hydrocarbons (such as from oil/diesel) have been visually identified on the ground adjacent to the above ground storage tank and fill point.
2/01/2019	Lot 21 Mount Margaret-Mount Morgans Rd Laverton 6440 WA	Possibly contaminated - investigation required	15/02/2019	Hydrocarbons (such as from oil or diesel) have been visually identified on the ground adjacent to the fill point and tanker unloading area.
2/01/2019	Lot 39 Banda 6440 WA	Possibly contaminated - investigation required	15/02/2019	Hydrocarbons (such as from oil/diesel) have been visually identified on the ground within the power station area.
2/01/2019	Lot 100 Luurnpa Cir Tanami 6770 WA	Possibly contaminated - investigation required	15/02/2019	Hydrocarbons (such as from oil/diesel) have been visually identified on the ground adjacent to the above ground storage tank and fill point.
2/01/2019	Lot 44 Great Northern Hwy Ord River 6770 WA	Possibly contaminated - investigation required	15/02/2019	Hydrocarbons (such as from oil/diesel) have been visually identified on the ground adjacent to the above ground storage tank and fill point.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
2/01/2019	Lot 141 Munjina Rd Mulga Downs 6751 WA	Possibly contaminated - investigation required	19/02/2019	Minor hydrocarbons (such as from petrol, oil and diesel) were visually identified on surface soil surrounding the fill point, unloading area, oil storage, generator and above/underground ground storage tank.
2/01/2019	Lot 62 Sturt Creek 6770 WA	Possibly contaminated - investigation required	19/02/2019	Hydrocarbons (such as from oil/diesel) have been observed in soils at various locations around the power station compound.
2/01/2019	639 E Welshpool Rd Wattle Grove 6107 WA	Report not substantiated	21/05/2019	No contamination has been identified.
3/01/2019	Lot 306 on DP 45988, Tardun 6628 WA	Possibly contaminated - investigation required	15/02/2019	Unauthorised disposal of wastes have occurred on the south-western portion of the site. However, soil and groundwater quality at the site has not been investigated.
4/01/2019	Former WA Agricultural College, James Stirling Place, Lot 25 Harvey 6220 WA	Possibly contaminated - investigation required	19/02/2019	Hydrocarbons (such as from diesel) remain in soil beneath the former UST area in the south central portion of the site.
4/01/2019	5 Yalgoo North Rd Yalgoo 6635 WA	Report not substantiated	18/02/2019	No contamination has been identified.
4/01/2019	366 Grand Prom Dianella 6059 WA	Contaminated - restricted use	22/03/2021	Chlorinated hydrocarbons, such as from solvents, remain present in soil vapour beneath the site.
8/01/2019	Lot 502 Warmun 6743 WA	Possibly contaminated - investigation required	7/10/2009	Hydrocarbons (such as from diesel and oil) are present in groundwater. Hydrocarbons (such as from diesel and oil) and metals (copper and molybdenum) are present in soil.
8/01/2019	Lot 33 Great Northern Highway, Warmun 6743 WA	Possibly contaminated - investigation required	3/09/2012	The site has been used as a landfill site for the disposal of degradable wastes, including household and green waste. However, no contamination investigations have been carried out and the quality of soil and groundwater at the site is unknown.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
14/01/2019	42 Quill Way, Henderson 6166 WA	Remediated for restricted use	11/05/2021	Metals and tributyltin are present in soils at the site, contained beneath a pavement hardcover. Metals and tributyltin are present in groundwater at the site.
14/01/2019	124 Quill Way, Henderson 6166 WA	Remediated for restricted use	11/05/2021	Metals and tributyltin are present in soils at the site, contained beneath a pavement hardcover. Metals and tributyltin are present in groundwater at the site.
15/01/2019	Lot 30 Margaret River Rd St George Ranges 6728 WA	Possibly contaminated - investigation required	15/02/2019	Hydrocarbons (such as from oil and diesel) have been visually identified on the ground near the generators and at the fill point.
24/01/2019	440 Hope Rd Jandakot 6164 WA	Classification timeframe extended under s.14(1)(b)		
31/01/2019	236 Great Eastern Hwy Midland 6056 WA	Contaminated - restricted use	29/11/2019	Chlorinated hydrocarbons (such as from dry cleaning solvents) are present in groundwater and soil vapour beneath the north-western portion of site.
1/02/2019	17F Mandurah Rd Kwinana Beach 6167 WA	Remediated for restricted use	13/08/2020	Hydrocarbons (such as from oil) are present in soils beneath the electrical transformer on this site.
4/02/2019	Lot 105 Tom Price-Paraburdoo Rd Rocklea 6751 WA	Possibly contaminated - investigation required	11/01/2023	Hydrocarbons (such as from petrol/oil/diesel) are present in soil mainly within south-east and central non-bunded portions of site.
5/02/2019	419 Great Eastern Hwy Redcliffe 6104 WA	Remediated for restricted use	21/01/2020	Hydrocarbons (such as from petrol, diesel and oil) are present in groundwater as a plume extending off site in a northerly direction. Hydrocarbons (such as from petrol) are present in soil beneath hardstand in the central portion of the site.
5/02/2019	Lot 567 Victoria Highway, Reserve 28875, Kununurra 6743 WA	Possibly contaminated - investigation required	12/06/2019	The site has been used as a landfill for the disposal of liquid wastes. Hydrocarbons (such as from waste oil) were visually identified on surface soils in a portion of the site following an incident.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
5/02/2019	Mount Whaleback Iron Ore Mine Newman 6753 WA	Contaminated - remediation required	10/12/2020	<p>Soils and groundwater in the mine operations area are impacted by petroleum hydrocarbons (such as from diesel or oil), perfluoroalkyl and polyfluoroalkyl substances (PFAS) and asbestos.</p> <p>Petroleum hydrocarbons have been identified in surface and sub-surface soils to 45 meters below ground level, at the former power station site. Light non-aqueous phase liquid hydrocarbons (such as pure petrol or diesel) has been observed floating on the surface of the watertable beneath the former power station site.</p> <p>PFAS, associated with fire suppression foam application and disposal at the site, has been detected in groundwater beneath the site.</p> <p>Asbestos containing materials (ACM) are present in former and current asbestos waste disposal areas and in general landfill.</p>
5/02/2019	Lot 500 on Deposited Plan 422881 Newman 6753 WA	Remediated for restricted use	15/09/2022	Asbestos-impacted fill is buried beneath this site, covered by no less than 5 to 10 metres of waste rock.
7/02/2019	80 Great Northern Hwy Wubin 6612 WA	Possibly contaminated - investigation required	21/03/2019	Hydrocarbons (such as from petrol) are present in groundwater near the south-western site boundary.
14/02/2019	Georgina Rd Greenough 6532 WA	Remediated for restricted use	28/03/2019	Hydrocarbon-impacted soil remains in-situ at depth beneath the location of the pole top transformer.
25/02/2019	Bulwer St Perth 6000 WA	Decontaminated	17/11/2021	Following remediation, no known contamination remains at the site.
26/02/2019	14 Preston Dr Munster 6166 WA	Decontaminated	10/04/2019	Following remediation, no contamination remains at the site.
7/03/2019	Reserve 32091 (Lots 353 & 390), 15 Inkpen Street, Northam 6401 WA	Possibly contaminated - investigation required	17/04/2019	Asbestos-containing materials were identified in surface soils. The identified fragments have been removed, but validation sampling has not been carried out. The quality of surface soils on the site is unknown.
7/03/2019	140 Morawa-three Springs Rd Morawa 6623 WA	Possibly contaminated - investigation required	28/03/2019	Hydrocarbon staining (such as from petrol/oil/diesel) was visually identified in the chemical shed, farm workshop, machinery sheds and wash down bays.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
12/03/2019	82 Forest Lakes Dr Thornlie 6108 WA	Report not substantiated	26/04/2019	No contamination has been identified.
22/03/2019	Lot 90 Leonora 6438 WA	Possibly contaminated - investigation required	26/04/2019	Asbestos containing material including fibrous asbestos is present in soil on the site.
2/04/2019	80 Tower Rd Mount Barker 6324 WA	Report not substantiated	15/05/2019	No contamination has been identified.
3/04/2019	2B Rawlins St Glendalough 6016 WA	Decontaminated	21/10/2020	Following remediation, no contamination remains.
4/04/2019	9 Peel Tce Northam 6401 WA	Contaminated - restricted use	20/10/2022	Hydrocarbons (such as from petrol or diesel) are present in groundwater beneath adjacent land which extends to the north to beneath this the site.
5/04/2019	390 Victoria Rd Malaga 6090 WA	Report not substantiated	15/05/2019	No contamination has been identified.
5/04/2019	Lot 10 Kakata Ct St George Ranges 6728 WA	Classification timeframe extended under s.14(1)(b)		
8/04/2019	500 Kalamunda Rd High Wycombe 6057 WA	Possibly contaminated - investigation required	22/05/2019	Hydrocarbon contaminated groundwater (such as from petrol) is present beneath a nearby service station (the source site), which extends beneath the south-eastern portion of this site.
8/04/2019	Mining Tenement M25/97, Bulong 6431 WA	Contaminated - restricted use	4/08/2021	The site comprises a former chromium and cobalt mine leachate residue storage facility and evaporation ponds. Metals (such as chromium and nickel) were identified in the leachate residue storage facility, the evaporation ponds and in groundwater beneath the site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
8/04/2019	19 Katanning St Bayswater 6053 WA	Remediated for restricted use	6/05/2020	An electrical transformer is present on the southern portion of this site, adjacent to Katanning Street, which has leaked hydrocarbons (such as from transformer oil) into soils. Hydrocarbons remain in soil at approximately 0.4 metres below ground level.
12/04/2019	240 Corrigin-naremben Rd Kurrenkutten 6375 WA	Report not substantiated	30/05/2019	No contamination has been identified.
15/04/2019	10 Macpherson St Djugun 6725 WA	Remediated for restricted use	8/03/2023	Hydrocarbons (such as from aviation fuel or diesel) are present in soil and groundwater beneath a former fuel storage area on the southern portion of the site. Perfluoroalkyl and polyfluoroalkyl substances (PFAS) are present in soils beneath former fire training grounds located on the northern and south-western portion of the site. Groundwater in the vicinity of former fire training grounds is impacted with perfluoroalkyl and polyfluoroalkyl substances (PFAS).
15/04/2019	20 Paterson St Mundijong 6123 WA	Contaminated - remediation required	12/03/2020	Hydrocarbons (such as from petrol and diesel) are present in soil within the north-east portion of the site. Hydrocarbons (such as from petrol and diesel) are present in groundwater as a plume extending beneath the site and is likely to migrate offsite in a southerly direction to affect adjoining land.
15/04/2019	Mineral Tenement M37/159 , Leonora 6438 WA	Contaminated - remediation required	28/05/2019	Hydrocarbons (such as oil) have leaked from degraded oil drums into soils at the site. Impacts are localised and remote, but potentially pose a risk to fauna and require remediation.
18/04/2019	5 Hutton St Osborne Park 6017 WA	Remediated for restricted use	19/07/2019	Hydrocarbons (such as from petrol) are present in groundwater beneath a nearby service station at 7 (Lot 152) Hutton Street, Osborne Park and extend to the south-west beneath this site.
18/04/2019	Bayulu Community, St George Ranges 6728 WA	Possibly contaminated - investigation required	28/05/2019	The site is used as a landfill for the disposal of degradable wastes (including household and green waste), building rubble and asbestos containing materials. No detailed contamination investigations have been carried out and the quality of soil and groundwater at the site is unknown.
26/04/2019	66 Hay Rd Ascot 6104 WA	Possibly contaminated - investigation required	13/04/2022	Unauthorised disposal of wastes, including asbestos-containing materials has occurred on this site. Further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
3/05/2019	764 Karrinyup Rd Balcatta 6021 WA	Possibly contaminated - investigation required	6/04/2021	Uncontrolled fill is buried at depths of between 0.3 and 2 metres below ground level across the site. Stockpiles of fly-tipped material including fragments of asbestos containing materials (ACM) were also present on site
6/05/2019	50 Forrest Rd Pickering Brook 6076 WA	Contaminated - remediation required	28/03/2018	Microbiological contaminants are present in groundwater beneath the site.
10/05/2019	Goulds Road Reserve, Narngulu 6532 WA	Contaminated - restricted use	21/12/2022	Radiation monitoring has detected elevated levels of gamma radiation at the site.
21/05/2019	52 Whitemoss Dr Vasse 6280 WA	Classification timeframe extended under s.14(1)(b)		
21/05/2019	70 Whitemoss Dr Vasse 6280 WA	Classification timeframe extended under s.14(1)(b)		
21/05/2019	141 Kookaburra Way Vasse 6280 WA	Classification timeframe extended under s.14(1)(b)		
21/05/2019	19 Jarrah Elb Vasse 6280 WA	Classification timeframe extended under s.14(1)(b)		
21/05/2019	95 Rendezvous Rd Vasse 6280 WA	Contaminated - restricted use	26/03/2018	A plume of metals, aromatic hydrocarbons (benzene) and chlorinated hydrocarbons (such as from solvents and their breakdown products) is present in groundwater beneath this site that has migrated in a north north-westerly direction from the adjacent waste facility to the south.
21/05/2019	127 Kookaburra Way Vasse 6280 WA	Classification timeframe extended under s.14(1)(b)		

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
21/05/2019	69 Whitemoss Drive Vasse 6280 WA	Classification timeframe extended under s.14(1)(b)		
21/05/2019	43 Whitemoss Dr Vasse 6280 WA	Classification timeframe extended under s.14(1)(b)		
21/05/2019	36 Jarrah Elbow Vasse 6280 WA	Possibly contaminated - investigation required	26/03/2018	A plume of metals, aromatic hydrocarbons (benzene) and chlorinated hydrocarbons (such as from solvents and their breakdown products) in groundwater has migrated in a north north-westerly direction from the waste facility to the south and is likely to extend to beneath this site.
21/05/2019	55 Jarrah Elbow Vasse 6280 WA	Classification timeframe extended under s.14(1)(b)		
21/05/2019	30 Jarrah Elbow Vasse 6280 WA	Classification timeframe extended under s.14(1)(b)		
21/05/2019	57 Jarrah Elbow Vasse 6280 WA	Classification timeframe extended under s.14(1)(b)		
21/05/2019	44 Jarrah Elbow Vasse 6280 WA	Contaminated - restricted use	26/03/2018	A plume of metals, aromatic hydrocarbons (benzene) and chlorinated hydrocarbons (such as from solvents and their breakdown products) is present in groundwater beneath this site that has migrated in a north north-westerly direction from the adjacent waste facility to the south.
21/05/2019	52 Jarrah Elbow Vasse 6280 WA	Contaminated - restricted use	26/03/2018	A plume of metals, aromatic hydrocarbons (benzene) and chlorinated hydrocarbons (such as from solvents and their breakdown products) is present in groundwater beneath this site that has migrated in a north north-westerly direction from the adjacent waste facility to the south.
21/05/2019	49 Jarrah Elbow Vasse 6280 WA	Contaminated - restricted use	26/03/2018	A plume of metals, aromatic hydrocarbons (benzene) and chlorinated hydrocarbons (such as from solvents and their breakdown products) is present in groundwater beneath this site that has migrated in a north north-westerly direction from the adjacent waste facility to the south.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
21/05/2019	41 Jarrah Elbow Vasse 6280 WA	Classification timeframe extended under s.14(1)(b)		
21/05/2019	28 Jarrah Elbow Vasse 6280 WA	Classification timeframe extended under s.14(1)(b)		
21/05/2019	46 Jarrah Elbow Vasse 6280 WA	Contaminated - restricted use	26/03/2018	A plume of metals, aromatic hydrocarbons (benzene) and chlorinated hydrocarbons (such as from solvents and their breakdown products) is present in groundwater beneath this site that has migrated in a north north-westerly direction from the adjacent waste facility to the south.
21/05/2019	56 Jarrah Elbow Vasse 6280 WA	Contaminated - restricted use	26/03/2018	A plume of metals, aromatic hydrocarbons (benzene) and chlorinated hydrocarbons (such as from solvents and their breakdown products) is present in groundwater beneath this site that has migrated in a north north-westerly direction from the adjacent waste facility to the south.
21/05/2019	54 Whitemoss Dr Vasse 6280 WA	Classification timeframe extended under s.14(1)(b)		
21/05/2019	49 Whitemoss Dr Vasse 6280 WA	Classification timeframe extended under s.14(1)(b)		
21/05/2019	55 Whitemoss Drive Vasse 6280 WA	Possibly contaminated - investigation required	26/03/2018	A plume of metals, aromatic hydrocarbons (benzene) and chlorinated hydrocarbons (such as from solvents and their breakdown products) in groundwater has migrated in a north north-westerly direction from the waste facility to the south and is likely to extend to beneath this site.
21/05/2019	54 Jarrah Elbow Vasse 6280 WA	Contaminated - restricted use	26/03/2018	A plume of metals, aromatic hydrocarbons (benzene) and chlorinated hydrocarbons (such as from solvents and their breakdown products) is present in groundwater beneath this site that has migrated in a north north-westerly direction from the adjacent waste facility to the south.
21/05/2019	65 Whitemoss Dr Vasse 6280 WA	Classification timeframe extended under s.14(1)(b)		

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
21/05/2019	34 Jarrah Elbow Vasse 6280 WA	Classification timeframe extended under s.14(1)(b)		
21/05/2019	20 Rendezvous Rd Vasse 6280 WA	Contaminated - restricted use	26/03/2018	A plume of metals, aromatic hydrocarbons (benzene) and chlorinated hydrocarbons (such as from solvents and their breakdown products) is present in groundwater beneath this site that has migrated in a north north-westerly direction from the adjacent waste facility to the south.
21/05/2019	39 Jarrah Elbow Vasse 6280 WA	Classification timeframe extended under s.14(1)(b)		
21/05/2019	60 Whitemoss Dr Vasse 6280 WA	Classification timeframe extended under s.14(1)(b)		
21/05/2019	51 Jarrah Elbow Vasse 6280 WA	Classification timeframe extended under s.14(1)(b)		
21/05/2019	73 Whitemoss Dr Vasse 6280 WA	Classification timeframe extended under s.14(1)(b)		
21/05/2019	Lot 307 Whitemoss Drive Vasse 6280 WA	Possibly contaminated - investigation required	26/03/2018	A plume of metals, aromatic hydrocarbons (benzene) and chlorinated hydrocarbons (such as from solvents and their breakdown products) in groundwater has migrated in a north north-westerly direction from the waste facility to the south and is likely to extend to beneath this site.
5/06/2019	39 Leake St Belmont 6104 WA	Remediated for restricted use	27/05/2020	Hydrocarbons (such as from petrol) which have originated from the adjacent service station (Lot 3) are present in groundwater beneath this affected site.
12/06/2019	Lot 336 on Plan 27316 William Keeling Crescent, West Island Cocos (keeling) Is 6799 WA	Contaminated - remediation required	25/07/2019	Fragments of asbestos-containing materials are present in surface soils and beneath a shallow warning barrier in the southern portion of the site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
19/06/2019	304 Roberts Rd Subiaco 6008 WA	Decontaminated	13/04/2021	Following remediation, no contamination remains at the site.
19/06/2019	488 Beechboro Rd Beechboro 6063 WA	Decontaminated	2/02/2023	Following remediation, no contamination remains at the site.
19/06/2019	486 Beechboro Rd Beechboro 6063 WA	Decontaminated	2/02/2023	Following remediation, no contamination remains at the site.
25/06/2019	41 Hamersley St Esperance 6450 WA	Possibly contaminated - investigation required	25/11/2020	Elevated concentrations of perfluoroalkyl and polyfluoroalkyl substances (PFAS) have been detected in groundwater beneath the site.
27/06/2019	Lot 9363 South Western highway, Middlesex 6258 WA	Classification timeframe extended under s.14(1)(b)		
28/06/2019	54 Munday Av Pinjarra 6208 WA	Remediated for restricted use	9/03/2020	Residual hydrocarbons (such as from transformer oil)-are present in soils beneath the existing electrical transformer on-site.
2/07/2019	Braeside Road Katanning 6317 WA	Report not substantiated	5/08/2019	No contamination has been identified at the time of reporting.
2/07/2019	21 Joondalup Dr Edgewater 6027 WA	Remediated for restricted use	16/12/2019	Hydrocarbons (such as from transformer oil) are present in subsurface soils below the pad mounted transformer.
5/07/2019	732 Karrinyup Rd Balcatta 6021 WA	Remediated for restricted use	24/02/2021	Fill material comprising inert building rubble and construction waste and including asbestos containing materials (ACM) are buried at depths of between 0.7 and 3.0 metres below ground level across the site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
9/07/2019	14 Winton Rd Joondalup 6027 WA	Possibly contaminated - investigation required	29/07/2020	Arsenic impacted groundwater is present in the eastern portion of the site. Low levels of dissolved hydrocarbons (such as from diesel) have been detected in the eastern portion of the site. The impacted groundwater is understood to be migrating onto this property from a property located to the east.
10/07/2019	Lot 337 William Keeling Crescent, West Island Cocos (keeling) Is 6799 WA	Remediated for restricted use	21/08/2019	Fragments of asbestos-containing materials are present in soils beneath a shallow warning barrier.
11/07/2019	276 Hope Valley Rd Hope Valley 6165 WA	Decontaminated	25/03/2020	Following remediation, no contamination remains at the site.
15/07/2019	Lot 778 On Plan 189109, Manjimup 6258 WA	Contaminated - remediation required	28/08/2019	Hydrocarbons (such as from bitumen waste, kerosene and/or diesel) are present within soil in the southern portion of the site at the location of pits formerly used for the disposal of bitumen waste.
15/07/2019	16 Wetherell St Manjimup 6258 WA	Possibly contaminated - investigation required	28/08/2019	This site is used for asphalt or bitumen manufacturing, council depot and telecommunications. Hydrocarbons (such as from oil, diesel and/or kerosene) were visually identified on surface soil surrounding hydrocarbon storage and dispensing equipment. Waste-water from the wash-down of vehicles, which is likely to contain hydrocarbons (such as from oil and diesel) has entered soils at the site. However, soil and groundwater quality at the site has not been investigated.
18/07/2019	19A Purser Cove Murdoch 6150 WA	Classification timeframe extended under s.14(1)(b)		
22/07/2019	86 Gardiner St Moora 6510 WA	Classification timeframe extended under s.14(1)(b)		
23/07/2019	Fletcher St Cannington 6107 WA	Possibly contaminated - investigation required	4/09/2019	Chlorinated hydrocarbons (such as vinyl chloride) are present in groundwater adjacent to this site and are likely to extend to groundwater beneath this site.
24/07/2019	180 Smith Rd Bullsbrook 6084 WA	Possibly contaminated - investigation required	4/09/2019	Unauthorised disposal and burial of wastes has occurred on this site. Soil and groundwater quality at the site has not been investigated.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
30/07/2019	44 A South Coast Hwy Denmark 6333 WA	Possibly contaminated - investigation required	12/09/2019	Hydrocarbons (such as from petrol) are present in groundwater in north eastern portion of the site.
30/07/2019	35 Rendezvous Rd Vasse 6280 WA	Contaminated - restricted use	11/09/2019	Groundwater beneath this site has been affected by landfill leachate originating from the adjacent former waste disposal site located to the south. Contaminants identified in groundwater include metals (such as arsenic), aromatic hydrocarbons (benzene), chlorinated hydrocarbons (such as from solvents and their breakdown products), and per-and poly-fluoroalkyl substances.
31/07/2019	151 Welshpool Rd Welshpool 6106 WA	Remediated for restricted use	25/08/2022	Elevated concentrations of hydrocarbons (such as from petrol or diesel), are present in groundwater beneath the site.
1/08/2019	2 Wangalla Pl Koongamia 6056 WA	Possibly contaminated - investigation required	16/12/2020	Asbestos fibres and fragments were found in stockpiled soil on site. Groundwater has not been investigated.
9/08/2019	627 Armadale Rd Piara Waters 6112 WA	Decontaminated	5/11/2019	Following remediation, no contamination remains at the site.
9/08/2019	29 Taylor St Tambellup 6320 WA	Decontaminated	27/05/2020	Following remediation, no contamination remains at the site.
12/08/2019	105 Clarence Beach Rd Henderson 6166 WA	Possibly contaminated - investigation required	4/09/2019	Tributyltin, copper and zinc are present in soils, and copper is present in groundwater beneath the site. Further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks to marine receptors.
12/08/2019	73 Hamilton Rd South Hedland 6722 WA	Possibly contaminated - investigation required	4/09/2019	Hydrocarbons (such as from petrol) are present in groundwater beneath the south-eastern portion of the site. Soil vapour has not been investigated and groundwater requires further investigation.
12/08/2019	Lot 2456 Roberts St South Hedland 6722 WA	Possibly contaminated - investigation required	4/09/2019	Hydrocarbons (such as from petrol) are present in groundwater beneath the south-western portion of the site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
14/08/2019	19 Ferguson Rd Dardanup 6236 WA	Possibly contaminated - investigation required	2/01/2020	Hydrocarbons have been identified in pooled groundwater in the vicinity of the former fuel bowser. However, soil and groundwater quality has not been fully investigated.
16/08/2019	Lot 34 on Plan 238590, Wiluna 6646 WA	Contaminated - remediation required	26/09/2019	Hydrocarbons (such as from diesel or oil) are present in soil at the site.
19/08/2019	143 Morawa-three Springs Rd Morawa 6623 WA	Possibly contaminated - investigation required	26/09/2019	A portion of the site has been used as a landfill site for the disposal of wastes, including potential asbestos and asbestos containing materials, steel drums and car parts associated with the sites use as an agricultural college. Groundwater quality at the site has not been investigated.
21/08/2019	374 Murray St Perth 6000 WA	Decontaminated	5/12/2019	Following remediation, no significant contamination is present at the site.
22/08/2019	10 Ewing St Bentley 6102 WA	Possibly contaminated - investigation required	15/10/2019	Hydrocarbons (such as from transformer oil) are present in soil and groundwater in the vicinity of the existing electrical transformer.
23/08/2019	14 Third Av Kelmscott 6111 WA	Decontaminated	16/12/2019	Following remediation, no contamination remains at the site.
23/08/2019	63 Railway Av Kelmscott 6111 WA	Decontaminated	16/12/2019	Following remediation, no contamination remains at the site.
23/08/2019	61 Railway Av Kelmscott 6111 WA	Decontaminated	16/12/2019	Following remediation, no contamination remains at the site.
23/08/2019	59 Railway Av Kelmscott 6111 WA	Decontaminated	16/12/2019	Following remediation, no contamination remains at the site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
23/08/2019	8 Third Av Kelmscott 6111 WA	Decontaminated	16/12/2019	Following remediation, no contamination remains at the site.
23/08/2019	10 Third Av Kelmscott 6111 WA	Decontaminated	16/12/2019	Following remediation, no contamination remains at the site.
23/08/2019	12 Third Av Kelmscott 6111 WA	Decontaminated	16/12/2019	Following remediation, no contamination remains at the site.
26/08/2019	60 Gingin Rd Lancelin 6044 WA	Decontaminated	14/04/2021	Following remediation, no contamination remains at the site.
27/08/2019	Lot 102 Direction Island, Home Island Cocos (keeling) Is 6799 WA	Report not substantiated	26/09/2019	No contamination has been identified.
30/08/2019	25 Armstrong Rd Wilson 6107 WA	Decontaminated	19/01/2023	Following remediation, no known contamination remains at the site.
30/08/2019	12 Florence Rd Vasse 6280 WA	Decontaminated	3/12/2020	Following remediation, no contamination remains at the site.
30/08/2019	Hannan St Kalgoorlie 6430 WA	Classification timeframe extended under s.14(1)(b)		
4/09/2019	Reserve 21558, Lot 13598 Dumbleyung- Lake Grace Rd, Neendaling 6353 WA	Possibly contaminated - investigation required	7/07/2022	Fragments of asbestos-containing materials are present on the ground surface in the northwest and eastern portions of the site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
4/09/2019	Bussell Hwy Bramley 6285 WA	Decontaminated	5/05/2021	Following remediation, no contamination remains at the site.
17/09/2019	109 Great Eastern Hwy Rivervale 6103 WA	Possibly contaminated - investigation required	9/10/2019	Hydrocarbons (such as from petrol) are present in groundwater beneath the north eastern portion of the site. Soil vapour has not been investigated and further investigation of groundwater is required.
17/09/2019	9 King Edward Rd Osborne Park 6017 WA	Report not substantiated	8/07/2020	Following investigations, no significant contamination has been identified at the site.
17/09/2019	50 Peachey Av Kewdale 6105 WA	Contaminated - restricted use	2/07/2020	Uncontrolled fill material containing asbestos-containing material is present below the surface of Lot 2339. Fill material of a similar composition is present below the surface of Lot 92, indicating that asbestos-containing material may also be present below this lot.
18/09/2019	31 Stuart St Perth 6000 WA	Possibly contaminated - investigation required	2/10/2019	The site is a decommissioned electrical substation. However, soil and groundwater quality at the site has not been investigated.
23/09/2019	Lot 326 Leake Street, Kellerberrin 6410 WA	Contaminated - remediation required	15/07/2020	Asbestos-containing material (ACM) is present in soil beneath the site.
23/09/2019	Lot 417 Leake Street Kellerberrin 6410 WA	Contaminated - remediation required	15/07/2020	Asbestos-containing material (ACM) is present in soil beneath the site.
24/09/2019	Lot 345 Alexander Street, West Island Cocos (keeling) Is 6799 WA	Remediated for restricted use	23/10/2019	Asbestos containing material (ACM) is present-in soil beneath the site.
1/10/2019	Lot 102 on Plan 21133, Naval Base 6165 WA	Remediated for restricted use	13/11/2019	Residual alumina refining slurry is situated around and beneath pipework infrastructure. Elevated alkalinity, aluminium and arsenic has been detected in groundwater beneath the site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
1/10/2019	Lot 492 on Plan 3638 Naval Base 6165 WA	Remediated for restricted use	13/11/2019	Residual alumina refining slurry is situated around and beneath pipework infrastructure. Elevated alkalinity, aluminium and arsenic has been detected in groundwater beneath the site.
3/10/2019	Bandicoot Dr & Pruinosa St Kununurra 6743 WA	Possibly contaminated - investigation required	15/10/2019	Hydrocarbons (such as from petrol) are present in groundwater beneath the western and north-western portions of the source site extending off-site to affect groundwater beneath this site.
11/10/2019	Reserve 22868, 97 Lamont Street, Ongerup 6336 WA	Decontaminated	20/11/2019	Following remediation, no identified contamination remains at the site.
18/10/2019	2 Williamson Way Port Hedland 6721 WA	Possibly contaminated - investigation required	15/06/2017	Perfluoroalkyl and polyfluoroalkyl substances (such as from fire-fighting foams) are present in groundwater beneath the site adjacent to the operational fire-fighting training ground and to the north of the main runway at the location of a historical training ground. Lead is present in soil beneath the concrete foundation of an aviation hangar at the location of a former fuel depot. Fragments of suspected asbestos-containing material have been observed on the soil surface in numerous locations across the site. Soil staining has been observed in multiple locations associated with current or former airport related infrastructure and activities.
21/10/2019	Lot 18 Mason Rd, Kwinana Beach 6167 WA	Contaminated - remediation required	5/12/2019	Hydrocarbons (such as from petrol, diesel or oil), metals and perfluoroalkyl and polyfluoroalkyl (PFAS) substances are present in groundwater beneath the site. Pesticide and phenol compounds are present as a plume in groundwater on the eastern portion of the site. Arsenic and ammonia are present as a plume in groundwater on the southern portion of the site. Hydrocarbons and metals may also be present in soils across the site and PFAS substances within soils associated with the fire training facility. The extent of any impacts in soil is unknown.
22/10/2019	Lot 503 William Street and road reserve, Williams 6391 WA	Contaminated - remediation required	5/12/2019	Hydrocarbon contaminated groundwater (such as from diesel) is present beneath the adjacent former service station (the source site), and extends to the north beneath this site.
22/10/2019	William Street road reserve Williams 6391 WA	Contaminated - remediation required	5/12/2019	Hydrocarbon contaminated groundwater (such as from diesel) is present beneath the adjacent former service station (the source site), and extends to the north beneath this site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
29/10/2019	2775 Toodyay Rd Gidgegannup 6083 WA	Possibly contaminated - investigation required	27/11/2019	Uncontrolled fill has been placed on this site. However, the nature of fill materials and soil quality at the site has not been investigated.
30/10/2019	portion of Russell Rd and Rockingham Rd, Munster 6166 WA	Possibly contaminated - investigation required	5/12/2019	Saline groundwater has possibly migrated onto this site. However, groundwater quality at the site has not been investigated.
13/11/2019	346 Wattleup Rd Hammond Park 6164 WA	Not contaminated - unrestricted use	23/12/2020	No contamination has been identified.
13/11/2019	Lot 75 Wattleup Rd Hammond Park 6164	Not contaminated - unrestricted use	23/12/2020	No contamination has been identified.
14/11/2019	Lot 70 Bishop Road, Middle Swan 6056 WA	Possibly contaminated - investigation required	12/12/2019	Parts of the site have been used as a materials handling and stockpiling yard and fill of unknown origin was historically placed across the site. However, soil and groundwater quality at the site has not been investigated.
19/11/2019	18 Drummond St Moora 6510 WA	Possibly contaminated - investigation required	16/01/2020	Hydrocarbons (such as from petrol) have been identified in groundwater exceeding assessment criteria. No soil results have been provided.
20/11/2019	49 Hardey Rd Belmont 6104 WA	Possibly contaminated - investigation required	16/12/2019	Per-and poly-fluoroalkyl substances, commonly referred to as PFAS (such as from fire-fighting foams) are present in groundwater on the northern boundary of the site. Further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks
22/11/2019	221 Goldfields Hwy South Boulder 6432 WA	Possibly contaminated - investigation required	5/03/2020	Hydrocarbons (such as from petrol, diesel or oil) are present in soil beneath the site. Hydrocarbons, per-and poly-fluoroalkyl substances (PFAS) (such as from PFAS-containing waste) and metals are present in groundwater beneath the site.
22/11/2019	2525 Coolawanyah Rd Karratha Industrial Estate 6714 WA	Possibly contaminated - investigation required	16/12/2019	Hydrocarbons (such as from petrol, diesel or oil) have been identified in surface soils across a majority of the site. Groundwater investigations have not been undertaken.
25/11/2019	Mercury Tce Byford 6122 WA	Remediated for restricted use	2/07/2020	Following remediation, hydrocarbons (such as from transformer oil), remain present in soil beneath the pad-mounted transformer.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
28/11/2019	North Rd Bassendean 6054 WA	Possibly contaminated - investigation required	3/06/2021	Hydrocarbons (such as from petrol or diesel) are present in soil and groundwater beneath the site.
28/11/2019	15 Tanunda Dr Rivervale 6103 WA	Classification timeframe extended under s.14(1)(b)		
3/12/2019	51 Brand Rd High Wycombe 6057 WA	Possibly contaminated - investigation required	1/09/2021	Chlorinated hydrocarbons, suspected to be associated with landfill leachate, have been detected in groundwater along the site's north-eastern boundary. Landfill gas (such as carbon dioxide) was identified beneath the northern portion of the site.
3/12/2019	86 Brand Rd High Wycombe 6057 WA	Classification timeframe extended under s.14(1)(b)		
3/12/2019	78 Brand Rd High Wycombe 6057 WA	Classification timeframe extended under s.14(1)(b)		
3/12/2019	70 Brand Rd High Wycombe 6057 WA	Classification timeframe extended under s.14(1)(b)		
3/12/2019	62 Brand Rd High Wycombe 6057 WA	Classification timeframe extended under s.14(1)(b)		
3/12/2019	39 Smokebush Pl High Wycombe 6057 WA	Possibly contaminated - investigation required	10/08/2021	Chlorinated hydrocarbons (such as from landfill waste) are present in groundwater beneath the adjacent former landfill and are likely to be present in groundwater beneath this site. Ammonia and per-and poly-fluoroalkyl substances (PFAS) are present in groundwater down-hydraulic gradient of this site and are likely to have migrated from the adjacent former landfill. Landfill gases (such as methane and carbon dioxide) are present beneath the adjacent former landfill and are likely to extend beneath this site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
3/12/2019	Brand Rd road reserve High Wycombe 6057 WA	Possibly contaminated - investigation required	10/08/2021	Chlorinated hydrocarbons (such as from landfill waste) are present in groundwater beneath the adjacent former landfill and are likely to be present in groundwater beneath this site. Ammonia and per-and poly-fluoroalkyl substances (PFAS) are present in groundwater down-hydraulic gradient of this site and are likely to have migrated from the adjacent former landfill. Landfill gases (such as methane and carbon dioxide) are present beneath the adjacent former landfill and are likely to extend beneath this site.
3/12/2019	Smokebush Place road reserve High Wycombe 6057 WA	Classification timeframe extended under s.14(1)(b)		
4/12/2019	26 Office Rd East Rockingham 6168 WA	Classification timeframe extended under s.14(1)(b)		
5/12/2019	252 Boomerang Rd Oldbury 6121 WA	Contaminated - remediation required	31/03/2021	Unauthorised disposal of construction and demolition waste containing 'asbestos-containing material' (ACM) has occurred in multiple areas of the site. Crushed construction and demolition material that contains ACM is present within the on-site road base material that comprises the internal site roads, hardstands and surrounding some site infrastructure. There is a potential that construction and demolition wastes that may contain ACM has been buried in some areas of the site.
17/12/2019	Lot 1480 Mortiss St Exmouth 6707 WA	Remediated for restricted use	5/08/2020	Following remediation, hydrocarbons (such as from diesel) remain in soil and groundwater beneath the site.
17/12/2019	Lot 500 Mettawandy Place, Paraburdoo 6754 WA	Possibly contaminated - investigation required	21/01/2020	Hydrocarbons (such as from diesel) were visually identified on surface soil surrounding the location of an above ground storage tank.
19/12/2019	13 Possum Pl Vasse 6280 WA	Report not substantiated	21/01/2020	No contamination has been identified.
19/12/2019	167 Kookaburra Way Vasse 6280 WA	Report not substantiated	21/01/2020	No contamination has been identified.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
19/12/2019	Rangeview Ct Maddington 3109 WA	Remediated for restricted use	28/01/2020	Hydrocarbons (such as from oil) are present in the subsurface soils below the footprint of the existing electrical transformer.
20/12/2019	1700 Marmion Av Tamala Park 6030 WA	Report not substantiated	1/08/2011	No contamination has been identified.
24/12/2019	Cooramining Rd, Dumberning 6312 WA	Classification timeframe extended under s.14(1)(b)		
2/01/2020	30 Fourth Rd Armadale 6112 WA	Report not substantiated	28/01/2020	Following remedial works completed prior to reporting of the site, no contamination has been identified.
3/01/2020	Lot 3013 on Deposited Plan 42282 Burrup 6714 WA	Possibly contaminated - investigation required	6/02/2023	Site investigations have found ammonia, nitrate and nitrite to be present in surface water and sediments at the site which originate from a nearby ammonium nitrate production facility.
3/01/2020	58 Steere St Bridgetown 6255 WA	Report not substantiated	4/02/2020	No contamination has been identified.
3/01/2020	30 Kennedy St Northam 6401 WA	Possibly contaminated - investigation required	16/06/2020	The south-western portion of the site has been used as a landfill. Fragments of asbestos-containing material potentially remain in soils across the horticultural area located in the western portion of the site.
7/01/2020	50 Peachey Av Kewdale 6105 WA	Contaminated - restricted use	2/07/2020	Uncontrolled fill material containing asbestos-containing material is present below the surface of Lot 2339. Fill material of a similar composition is present below the surface of Lot 92, indicating that asbestos-containing material may also be present below this lot.
22/01/2020	56 Routeburn St Wanneroo 6065 WA	Decontaminated	10/08/2021	Following remediation, no contamination remains at the site.
22/01/2020	adjacent to Lot 100, No 811 Abernethy Road, Forrestfield 6058 WA	Remediated for restricted use	26/05/2022	Following remediation, hydrocarbon-impacted soils (such as from transformer oil) remain beneath the transformer pad at a depth of approximately 2.5 metres below ground surface.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
23/01/2020	Geraldton-mount Magnet Road Yalgoo 6635 WA	Possibly contaminated - investigation required	5/03/2020	The site has historically been used as a mineral battery site. No investigation have been undertaken at the site.
23/01/2020	Road Reserve adjacent to 597 Stonehouse Loop, Sawyers Valley 6074 WA	Possibly contaminated - investigation required	27/02/2020	Petroleum hydrocarbons (such as from petrol or diesel) are present in groundwater beneath this site. These hydrocarbons have migrated from a source site located immediately north of the site.
23/01/2020	Lot 1035 Casuarina Dr Bunbury 6230 WA	Not contaminated - unrestricted use	11/08/2021	Investigations found that no contamination is present in soil or groundwater at the site.
29/01/2020	36 Comberton Loop Butler 6036 WA	Remediated for restricted use	27/02/2020	Hydrocarbons are present in soils at approximately 1.1 and 1.5 meters below ground surface. Soil impacts are isolated to the soils immediately surrounding the padmount transformer situated within the south western portion of the site.
31/01/2020	Reserve 21558, Lot 13598 Dumbleyung-Lake Grace Rd, Neendaling 6353 WA	Possibly contaminated - investigation required	7/07/2022	Fragments of asbestos-containing materials are present on the ground surface in the northwest and eastern portions of the site.
3/02/2020	12 Railway Pde Bayswater 6053 WA	Possibly contaminated - investigation required	14/07/2022	<p>Solid wastes, including occasional fragments of asbestos-containing material and putrescible wastes, have been disposed of in the northern portion of this site.</p> <p>Petroleum hydrocarbons, such as from oil, are present in shallow soil in one location in the north-eastern portion of the site.</p> <p>Elevated levels of metals, including arsenic and zinc, are present in soil in isolated locations.</p> <p>Elevated levels of metals, including nickel and zinc, and asbestos fibres and fines, have been detected in sediment at the site withing stormwater drainage features.</p> <p>Groundwater beneath the site has been contaminated by historical industrial activities, including the burial of cinder waste, at adjacent land to the east. The groundwater contamination is characterised by elevated levels of acidity, metals, (such as aluminium and iron), fluoride and nutrients (such as ammonia).</p> <p>Buried wastes are generating landfill gases, with elevated levels of carbon dioxide detected beneath the site.</p>

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
6/02/2020	1 Rawlinson St O'connor 6163 WA	Classification timeframe extended under s.14(1)(b)		
6/02/2020	3 Rawlinson St O'connor 6163 WA	Classification timeframe extended under s.14(1)(b)		
6/02/2020	5 Adams Street O'connor 6163 WA	Classification timeframe extended under s.14(1)(b)		
6/02/2020	7 Adams Street O'connor 6163 WA	Classification timeframe extended under s.14(1)(b)		
6/02/2020	54 Peel Road O'connor 6163 WA	Classification timeframe extended under s.14(1)(b)		
6/02/2020	49 Peel Rd O'connor 6163 WA	Contaminated - restricted use	30/06/2020	Per-and polyfluoroalkyl substances (PFAS, such as from fire-fighting foams) are present in groundwater beneath the site. Further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.
6/02/2020	57A Peel Road O'connor 6163 WA	Classification timeframe extended under s.14(1)(b)		
6/02/2020	Unit 1/63 Peel Road O'connor 6163 WA	Classification timeframe extended under s.14(1)(b)		
6/02/2020	Unit 2/63 Peel Road O'connor 6163 WA	Classification timeframe extended under s.14(1)(b)		

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
6/02/2020	Unit 3/63 Peel Road O'connor 6163 WA	Classification timeframe extended under s.14(1)(b)		
6/02/2020	Unit 4/63 Peel Road O'connor 6163 WA	Classification timeframe extended under s.14(1)(b)		
6/02/2020	3 Adams Street O'connor 6163 WA	Classification timeframe extended under s.14(1)(b)		
6/02/2020	4 Adams Street O'connor 6163 WA	Classification timeframe extended under s.14(1)(b)		
6/02/2020	4 Ladner Street O'connor 6163 WA	Classification timeframe extended under s.14(1)(b)		
6/02/2020	Unit 15/19 Rawlinson Street O'connor 6163 WA	Possibly contaminated - investigation required	30/06/2020	Per- and polyfluoroalkyl substances (PFAS, such as from fire-fighting foams) are present in groundwater beneath the site. Further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.
6/02/2020	55 Peel Road O'connor 6163 WA	Classification timeframe extended under s.14(1)(b)		
6/02/2020	Unit 1/19 Rawlinson Street O'connor 6163 WA	Possibly contaminated - investigation required	30/06/2020	Per- and polyfluoroalkyl substances (PFAS, such as from fire-fighting foams) are present in groundwater beneath the site. Further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.
6/02/2020	Unit 2/19 Rawlinson Street O'connor 6163 WA	Possibly contaminated - investigation required	30/06/2020	Per- and polyfluoroalkyl substances (PFAS, such as from fire-fighting foams) are present in groundwater beneath the site. Further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
6/02/2020	Unit 3/19 Rawlinson Street O'connor 6163 WA	Possibly contaminated - investigation required	30/06/2020	Per- and polyfluoroalkyl substances (PFAS, such as from fire-fighting foams) are present in groundwater beneath the site. Further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.
6/02/2020	Unit 4/19 Rawlinson Street O'connor 6163 WA	Possibly contaminated - investigation required	30/06/2020	Per- and polyfluoroalkyl substances (PFAS, such as from fire-fighting foams) are present in groundwater beneath the site. Further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.
6/02/2020	Unit 5/19 Rawlinson Street O'connor 6163 WA	Possibly contaminated - investigation required	30/06/2020	Per- and polyfluoroalkyl substances (PFAS, such as from fire-fighting foams) are present in groundwater beneath the site. Further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.
6/02/2020	Unit 6/19 Rawlinson Street O'connor 6163 WA	Possibly contaminated - investigation required	30/06/2020	Per- and polyfluoroalkyl substances (PFAS, such as from fire-fighting foams) are present in groundwater beneath the site. Further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.
6/02/2020	Unit 7/19 Rawlinson Street O'connor 6163 WA	Possibly contaminated - investigation required	30/06/2020	Per- and polyfluoroalkyl substances (PFAS, such as from fire-fighting foams) are present in groundwater beneath the site. Further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.
6/02/2020	57B Peel Road O'connor 6163 WA	Classification timeframe extended under s.14(1)(b)		
6/02/2020	Unit 8/19 Rawlinson Street O'connor 6163 WA	Possibly contaminated - investigation required	30/06/2020	Per- and polyfluoroalkyl substances (PFAS, such as from fire-fighting foams) are present in groundwater beneath the site. Further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.
6/02/2020	56 Peel Road O'connor 6163 WA	Classification timeframe extended under s.14(1)(b)		
6/02/2020	Unit 9/19 Rawlinson Street O'connor 6163 WA	Possibly contaminated - investigation required	30/06/2020	Per- and polyfluoroalkyl substances (PFAS, such as from fire-fighting foams) are present in groundwater beneath the site. Further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
6/02/2020	59 Peel Road O'connor 6163 WA	Classification timeframe extended under s.14(1)(b)		
6/02/2020	Unit 10/19 Rawlinson Street O'connor 6163 WA	Possibly contaminated - investigation required	30/06/2020	Per- and polyfluoroalkyl substances (PFAS, such as from fire-fighting foams) are present in groundwater beneath the site. Further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.
6/02/2020	Unit 11/19 Rawlinson Street O'connor 6163 WA	Possibly contaminated - investigation required	30/06/2020	Per- and polyfluoroalkyl substances (PFAS, such as from fire-fighting foams) are present in groundwater beneath the site. Further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.
6/02/2020	Unit 12/19 Rawlinson Street O'connor 6163 WA	Possibly contaminated - investigation required	30/06/2020	Per- and polyfluoroalkyl substances (PFAS, such as from fire-fighting foams) are present in groundwater beneath the site. Further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.
6/02/2020	Unit 13/19 Rawlinson Street O'connor 6163 WA	Possibly contaminated - investigation required	30/06/2020	Per- and polyfluoroalkyl substances (PFAS, such as from fire-fighting foams) are present in groundwater beneath the site. Further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.
6/02/2020	Unit 14/19 Rawlinson Street O'connor 6163 WA	Possibly contaminated - investigation required	30/06/2020	Per- and polyfluoroalkyl substances (PFAS, such as from fire-fighting foams) are present in groundwater beneath the site. Further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.
6/02/2020	Lot 65 Marble Bar 6760 WA	Remediated for restricted use	11/03/2020	Isolated residual hydrocarbon impacted soils following remediation.
14/02/2020	21 Fairbank St Ballidu 6606 WA	Possibly contaminated - investigation required	5/03/2020	Asbestos-containing material (ACM) was historically encountered in sub-surface soil beneath the site.
14/02/2020	77 Barron St Boyup Brook 6244 WA	Possibly contaminated - investigation required	5/03/2020	Historical disposal of wastes has occurred on this site. However, soil and groundwater quality at the site has not been investigated.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
21/02/2020	101 Natham Sq Swan View 6056 WA	Possibly contaminated - investigation required	11/03/2020	Unauthorised disposal of wastes has occurred on this site. Soil and groundwater has not been investigated at the site.
25/02/2020	Mining Tenement M45/764, Telfer 6762 WA	Possibly contaminated - investigation required	11/03/2020	Per-and poly-fluoroalkyl substances (PFAS) (such as from fire-fighting foams) have historically been used at the site for training purposes. However, soil and groundwater quality at the site has not been investigated.
26/02/2020	269 Walter Rd Morley 6062 WA	Contaminated - remediation required	15/06/2022	Chlorinated hydrocarbons (such as from solvents) and petroleum hydrocarbons (such as from petrol or white spirit) are present in soil vapour and groundwater beneath the site in the vicinity of a stormwater sump drain and former dry cleaning infrastructure located in the north-east of the site. Chlorinated hydrocarbons and petroleum hydrocarbons in soil vapour and groundwater extend off-site to the east/south-east onto the adjacent lot.
26/02/2020	69 South Coast Hwy Denmark 6333 WA	Possibly contaminated - investigation required	7/04/2020	Hydrocarbons (such as from petrol), are present in shallow groundwater and soil gas is present in the western portion of the site adjacent to underground fuel storage infrastructure.
26/02/2020	20 Paterson St Mundijong 6123 WA	Contaminated - remediation required	12/03/2020	Hydrocarbons (such as from petrol and diesel) are present in soil within the north-east portion of the site. Hydrocarbons (such as from petrol and diesel) are present in groundwater as a plume extending beneath the site and is likely to migrate offsite in a southerly direction to affect adjoining land.
26/02/2020	18 Paterson St Mundijong 6123 WA	Possibly contaminated - investigation required	12/03/2020	Hydrocarbons (such as from petrol and diesel) are present in groundwater beneath the adjacent service station (the source site), and is likely to be present beneath this site.
4/03/2020	Crown Reserve 6390 Yerilla-Lake Raeside Road Kookynie 6431 WA	Possibly contaminated - investigation required	18/03/2020	Tailings produced from mining operations are stored on site which are potentially impacted by heavy metals (such as mercury). However, soil and groundwater quality at the site has not been investigated.
4/03/2020	Crown Reserve 15441 Mount Keith 6646 WA	Possibly contaminated - investigation required	18/03/2020	Tailings produced from mining operations are stored on site, which are potentially impacted by heavy metals (such as mercury). However, soil and groundwater quality at the site has not been investigated.
6/03/2020	Mining tenements M20/55 Lake Austin 6640 WA	Report not substantiated	15/04/2020	The site has been used for mining and associated land uses including storage and handling of hydrocarbons (such as diesel, petrol or oil) and chemicals, and storage and processing of mineral ore or tailings. No contamination has been identified.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
23/03/2020	24 Stone St Wungong 6112 WA	Decontaminated	28/01/2021	Following remediation, no contamination remains at the site.
23/03/2020	35 Comserv Loop Ellenbrook 6069 WA	Possibly contaminated - investigation required	22/03/2021	Hydrocarbons (such as from diesel) are present in soil and groundwater beneath the site. Risk assessment is required to inform required remediation and/or ongoing management needs.
1/04/2020	500 Katharine St Bellevue 6056 WA	Classification timeframe extended under s.14(1)(b)		
6/04/2020	92 Great Northern Hwy Wyndham 6740 WA	Possibly contaminated - investigation required	11/08/2021	Following remediation, hydrocarbons (such as from diesel) remain in soil beneath site infrastructure.
7/04/2020	Crown Reserve 33582, Lot 501 Edgar Lewis Place, Moora 6510 WA	Possibly contaminated - investigation required	17/06/2021	Hydrocarbon-impacted soil (such as from kerosene) remains at the location of the former underground storage tank adjacent to the laundry and kitchen building. The quality of groundwater is unknown.
8/04/2020	7 Welshpool Rd Lesmurdie 6076 WA	Possibly contaminated - investigation required	20/05/2020	Hydrocarbons (such as from petrol) were identified in soil and groundwater in the central portion of the site.
8/04/2020	Lot 23 Arthur Street, Dayton 6055 WA	Not contaminated - unrestricted use	9/06/2021	Investigations found that no contamination is present in soil or groundwater at the site.
15/04/2020	Kwinana Fwy Salter Point 6152 WA	Report not substantiated	2/06/2020	At the time of reporting, no contamination remained at the site.
16/04/2020	16 Richmond St Nyabing 6341 WA	Possibly contaminated - investigation required	25/03/2021	Hydrocarbons (such as from petrol), are present in soil and groundwater in the north-eastern corner of Lot 12 and in the Richmond Street road reserve adjacent to former fuel storage and dispensing infrastructure. Hydrocarbon vapour is also present in shallow soil in the north-eastern corner of the site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
16/04/2020	Johnson St Bruce Rock 6418 WA	Classification timeframe extended under s.14(1)(b)		
22/04/2020	6 Alexander St South Bunbury 6230 WA	Classification timeframe extended under s.14(1)(b)		
22/04/2020	Lot 166 on Diagram 611 South Bunbury 6230 WA	Classification timeframe extended under s.14(1)(b)		
22/04/2020	Alexander Street road reserve South Bunbury 6230 WA	Classification timeframe extended under s.14(1)(b)		
23/04/2020	Lot 1034 (Part of Forest Reserve 1663) Kingsbury Drive, Serpentine. Keysbrook 6126 WA	Remediated for restricted use	3/12/2020	Asbestos containing material (ACM) and asbestos fines are present in soils located within the concrete burial area.
28/04/2020	26 Albert St Busselton 6280 WA	Remediated for restricted use	2/07/2020	Hydrocarbons (such as from petrol and diesel) remain in soil at a depth of 2m bgl in the north east portion of the site. Hydrocarbons (such as from petrol and diesel) are present in groundwater as a plume beneath the north east portion of the site, extending off site to the east.
28/04/2020	Kingsbury Dr Serpentine 6125 WA	Possibly contaminated - investigation required	9/06/2020	Asbestos-containing material (ACM) is present in soil beneath the site. Further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.
1/05/2020	Trans Access Rd Karonie Emu Flat 6431 WA	Possibly contaminated - investigation required	8/09/2021	Widespread fragments of asbestos-containing materials are present on the site, particularly in the footprint of former station buildings and in small areas associated with localised surface and sub-surface waste stockpiles.
5/05/2020	Lot 167 West Island, West Island Cocos (keeling) Is 6799 WA	Classification timeframe extended under s.14(1)(b)		
5/05/2020	15 Wood St Bassendean 6054 WA	Contaminated - remediation required	26/05/2020	Metals, hydrocarbons (such as from petrol or diesel), benzene and chlorobenzene are present in groundwater beneath the north-eastern portion of the site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
5/05/2020	22 Geddes St Balcatta 6021 WA	Not contaminated - unrestricted use	9/07/2013	No contamination is present at the site.
8/05/2020	12 Goldmead St Bayswater 6053 WA	Report not substantiated	19/08/2020	No contamination has been identified at this site.
8/05/2020	North Lake Rd Coolbellup 6163 WA	Classification timeframe extended under s.14(1)(b)		
11/05/2020	72 Hyne Rd South Guildford 6055 WA	Remediated for restricted use	25/01/2023	Nutrients, hydrocarbons (such as petrol, diesel or oil) and poly-fluoroalkyl substances (PFAS) are present in groundwater beneath the site.
11/05/2020	Lot 552 Fawdon Street, Safety Bay 6169 WA	Possibly contaminated - investigation required	27/05/2020	Following remediation, hydrocarbons (such as from transformer oil) remain in sub-surface soil beneath the site. Groundwater quality at the site has not been investigated.
12/05/2020	1 Winterfold Rd Hamilton Hill 6163 WA	Report not substantiated	17/06/2020	No contamination has been identified.
12/05/2020	43 Whitemoss Dr Vasse 6280 WA	Classification timeframe extended under s.14(1)(b)		
12/05/2020	15 Shovelboard Way Vasse 6280 WA	Classification timeframe extended under s.14(1)(b)		
12/05/2020	51 Jarrah Elbow Vasse 6280 WA	Classification timeframe extended under s.14(1)(b)		

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
12/05/2020	95 Rendezvous Rd Vasse 6280 WA	Contaminated - restricted use	26/03/2018	A plume of metals, aromatic hydrocarbons (benzene) and chlorinated hydrocarbons (such as from solvents and their breakdown products) is present in groundwater beneath this site that has migrated in a north north-westerly direction from the adjacent waste facility to the south.
12/05/2020	39 Jarrah Elbow Vasse 6280 WA	Classification timeframe extended under s.14(1)(b)		
12/05/2020	184 Railway Pde Bassendean 6054 WA	Remediated for restricted use	25/07/2018	Hydrocarbons are present in groundwater as a plume extending in a south westerly direction near the boundary of Lot 11 with Lots 200 and 201.
13/05/2020	60 Bannister Rd Canning Vale 6155 WA	Contaminated - restricted use	16/08/2016	Hydrocarbons are present in groundwater as a plume extending off-site from beneath the north-east portion of the site.
20/05/2020	Lot 700 on Plan 400757, Midland 6056 WA	Classification timeframe extended under s.14(1)(b)		
20/05/2020	131 Muchea East Rd Muchea 6501 WA	Contaminated - remediation required	8/09/2021	The site has been used for storage of green waste. Asbestos-containing materials are present within uncontrolled fill at the site.
26/05/2020	492 Marmion St Booragoon 6154 WA	Contaminated - remediation required	11/11/2020	Volatile organic compounds (such as from solvents and petroleum hydrocarbons) are present in groundwater beneath adjacent properties to the south-east which extends beneath this site.
3/06/2020	14 Rothschild Pl Midvale 6056 WA	Possibly contaminated - investigation required	8/07/2020	Hydrocarbons (such as from oil or diesel) have been identified in sub-surface soils in the vicinity of the fuel dispensing pumps and service pit in the south-western portion of the site. The nature and extent of these impacts have not been adequately delineated.
4/06/2020	Lot 303 Sutcliffe St Condingup 6450 WA	Possibly contaminated - investigation required	6/10/2022	The site was historically used as an unlicensed landfill. Limited soil investigations identified fragments of asbestos-containing material on surface soils in the central portion of the site and in a stockpile located along the western boundary.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
12/06/2020	Lot 56 Ranford Rd, Canning Vale 6155 WA	Possibly contaminated - investigation required	21/07/2020	Contaminants associated with landfill leachate, including nutrients (such as ammonia), chloride and perfluoroalkyl and polyfluoroalkyl substances (PFAS) are present in groundwater adjacent to this site's boundary and are likely to extend beneath this site. Landfill gases (such as methane, hydrogen sulphide and carbon dioxide) are being generated within the former landfill adjacent to this site and have the potential to migrate onto this site.
12/06/2020	Lot 58 Ranford Rd, Canning Vale 6155 WA	Possibly contaminated - investigation required	21/07/2020	Contaminants associated with landfill leachate, including nutrients (such as ammonia), chloride and perfluoroalkyl and polyfluoroalkyl substances (PFAS) are present in groundwater adjacent to this site's boundary and are likely to extend beneath this site. Landfill gases (such as methane, hydrogen sulphide and carbon dioxide) are being generated within the former landfill adjacent to this site and have the potential to migrate onto this site.
12/06/2020	Lot 60 Ranford Rd, Canning Vale 6155 WA	Possibly contaminated - investigation required	21/07/2020	Contaminants associated with landfill leachate, including nutrients (such as ammonia), chloride and perfluoroalkyl and polyfluoroalkyl substances (PFAS) are present in groundwater adjacent to this site's boundary and are likely to extend beneath this site. Landfill gases (such as methane, hydrogen sulphide and carbon dioxide) are being generated within the former landfill adjacent to this site and have the potential to migrate onto this site.
12/06/2020	62 Quinn St Gnowangerup 6335 WA	Possibly contaminated - investigation required	1/09/2021	Hydrocarbons (such as from petrol or diesel) are present in subsurface soil and groundwater in the north-eastern portion of the site associated with former fuel storage and dispensing infrastructure.
22/06/2020	65 Norma Rd Myaree 6154 WA	Classification timeframe extended under s.14(1)(b)		
22/06/2020	67 Norma Rd Myaree 6154 WA	Classification timeframe extended under s.14(1)(b)		
24/06/2020	85 Knight Tce Denham 6537 WA	Possibly contaminated - investigation required	8/07/2020	Hydrocarbons (such as from petrol) have been identified in soil and groundwater in the central portion of the site.
24/06/2020	Lot 229 on Deposited Plan 240259 Naval Base 6165 WA	Possibly contaminated - investigation required	6/08/2020	Aluminium, vanadium, molybdenum and arsenic are present in groundwater beneath the site.
24/06/2020	Lot 2218 on Deposited Plan 240010 Naval Base 6165 WA	Possibly contaminated - investigation required	6/08/2020	Aluminium, vanadium, molybdenum and arsenic are present in groundwater beneath the site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
25/06/2020	Mining Lease ML244SA, Newman 6753 WA	Possibly contaminated - investigation required	29/07/2020	Nutrients (such as nitrogen, phosphorus), pathogens and per- and poly-fluoroalkyl substances (PFAS) may be present in surface water and groundwater at elevated concentrations.
29/06/2020	243 Hampton Rd Northampton 6535 WA	Remediated for restricted use	16/07/2020	Lead tailings which have historically been used as construction fill are present in subsurface soil beneath the site.
30/06/2020	1 Jordan St Two Rocks 6037 WA	Classification timeframe extended under s.14(1)(b)		
30/06/2020	Lot 247 The Esplanade Dampier 6713 WA	Possibly contaminated - investigation required	16/07/2020	Asbestos-containing material (ACM) is present in subsurface soil beneath the site.
30/06/2020	Lot 175 Dampier Rd Gap Ridge 6714 WA	Contaminated - remediation required	12/04/2021	<p>Petroleum hydrocarbons (such as from diesel or oil) are present in the soil at multiple locations across a large portion of the site.</p> <p>Groundwater at the site is impacted by both dissolved phase hydrocarbons and light non-aqueous phase liquid (LNAPL), such as pure hydrocarbon floating on the surface of groundwater. These impacts are present in groundwater in multiple areas across the site.</p> <p>Chlorinated hydrocarbons (such as from chlorinated solvents) and Perfluoroalkyl and Polyfluoroalkyl Substances (PFAS) are also present in groundwater beneath the site in multiple areas.</p>
2/07/2020	Mining Lease M52/743, Peak Hill 6642 WA	Contaminated - remediation required	6/08/2020	Metals, such as copper, are present in shallow soils in various locations across the site and extend off-site to the east within a creek line.
6/07/2020	106 Fisher St Belmont 6104 WA	Remediated for restricted use	1/12/2021	Fragments of asbestos containing materials may be encountered in sub-surface soils across the site.
7/07/2020	Mining Tenement M77/1066 Mount Holland 6426 WA	Possibly contaminated - investigation required	28/10/2020	The site has historically been used as a gold mine and processing facility. However, soil and groundwater quality has not been fully investigated.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
7/07/2020	316 Wattleup Rd Wattleup 6166 WA	Report not substantiated	23/12/2020	No contamination has been identified at the site.
7/07/2020	326 Wattleup Rd Wattleup 6166 WA	Report not substantiated	23/12/2020	No contamination has been identified at the site.
7/07/2020	334 Wattleup Rd Wattleup 6166 WA	Report not substantiated	23/12/2020	No contamination has been identified at the site.
7/07/2020	Range Rd Capel 6271 WA	Possibly contaminated - investigation required	29/07/2020	Fragments of asbestos containing material are present within soils at the site.
10/07/2020	13 Stott Rd Welshpool 6106 WA	Possibly contaminated - investigation required	15/11/2022	Elevated levels of metal, nutrients and hydrocarbons are present in groundwater beneath the site.
13/07/2020	115 Dixon Rd East Rockingham 6168 WA	Possibly contaminated - investigation required	29/07/2020	Hydrocarbons (such as from petrol, diesel or oil) and volatile organic compounds (such as solvents) are present in soil and groundwater beneath the site. Further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks to human health and the environment.
15/07/2020	Lifford St Utakarra 6530 WA	Remediated for restricted use	6/08/2020	Following remediation, hydrocarbons (such as from transformer oil) remain in subsurface soil beneath the site.
16/07/2020	6254 Wilson St Redbank 6721 WA	Possibly contaminated - investigation required	26/08/2020	Hydrocarbons (such as from diesel and oils) are present in soils beneath the north-western portion of the site. Hydrocarbons in groundwater are present as a plume beneath the north-western portion of the site and extend offsite to the north. Hydrocarbons and methane gas are present in soil gases beneath the north-western portion of the site. Per-and poly-fluoroalkyl substances (PFAS) (such as from fire-fighting foams) are present in groundwater beneath the site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
21/07/2020	Bannister Rd Canning Vale 6155 WA	Possibly contaminated - investigation required	9/01/2018	Nutrients (such as ammonia) are present in groundwater at high concentrations adjacent to this site's boundary and are likely to extend beneath this site.
21/07/2020	49 Bickley Rd Beckenham 6107 WA	Possibly contaminated - investigation required	27/08/2020	Groundwater beneath the site has been impacted by hydrocarbons (such as from diesel) following a diesel line failure in the vicinity of the fuel bay.
22/07/2020	1 Roberts Rd Subiaco 6008 WA	Classification timeframe extended under s.14(1)(b)		
31/07/2020	8 Lansdowne Ent Canning Vale 6155 WA	Decontaminated	13/08/2020	Following remediation, no contamination remains at the site.
10/08/2020	11 Ewen St Scarborough 6019 WA	Decontaminated	19/05/2021	Following remediation, no known contamination remains at the site.
18/08/2020	Crown Reserve 7671, Lot 11448 on DP 18456, Sandy Gully 6535 WA	Possibly contaminated - investigation required	16/09/2020	Lead tailings are present in the northern portion of this site associated with historical mining activities and from the adjacent land parcel, Lot 1146. Fragments of suspected asbestos-containing material (ACM) are present on soil along the sites western boundary.
21/08/2020	20 Phillimore St Fremantle 6160 WA	Possibly contaminated - investigation required	6/01/2021	Perfluoroalkyl and polyfluoroalkyl substances (such as from fire-fighting foams) are present in groundwater beneath the site and may be migrating off-site in a westerly direction. Further investigation is required to determine the nature and extent of impacted soil and groundwater both on and off-site.
24/08/2020	389 Sevenoaks St Beckenham 6107 WA	Contaminated - remediation required	10/03/2021	Chromium and hydrocarbon-impacted soils (such as from diesel and waste oil) remain stockpiled on-site and require appropriate remediation and management.
25/08/2020	Lot 67 Skeet Rd Forrestdale 6112 WA	Classification timeframe extended under s.14(1)(b)		

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
27/08/2020	201 Sevenoaks St Cannington 6107 WA	Report not substantiated	23/09/2020	No contamination has been identified.
7/09/2020	33 Boudicca Dr Forrestdale 6112 WA	Decontaminated	18/03/2021	Following remediation, no contamination remains at the site.
9/09/2020	20 Albert St Busselton 6280 WA	Contaminated - restricted use	27/01/2021	The metals lead and zinc are present in fill material within subsurface soils beneath the site.
14/09/2020	70 Motivation Dr Wangara 6065 WA	Contaminated - remediation required	17/06/2021	<p>The site has been used as an unlined landfill for the disposal of degradable household wastes and inert waste (such as building rubble). The landfill wastes are covered by between 0.6 and 5 metres of sand that was placed as capping material.</p> <p>Landfill wastes are generating landfill gases, including methane, carbon dioxide and hydrogen sulfide.</p> <p>Salts (chloride), nutrients (ammonia) and per-and poly-fluoroalkyl substances (PFAS) (such as from PFAS-containing waste) are present in groundwater under the site.</p> <p>Fragments of asbestos-containing materials (ACM) are present in surface soils.</p>
14/09/2020	2824 Clementson St Minyirr 6725 WA	Possibly contaminated - investigation required	12/07/2019	<p>Elevated concentrations of nutrients are present in groundwater beneath the site.</p> <p>Suspected asbestos containing material has been visually identified at some locations on the site.</p>
16/09/2020	Ranford Road & Terrier Place, Forrestdale 6112 WA	Remediated for restricted use	26/08/2020	Hydrocarbons (such as from petrol or diesel) are present in groundwater beneath this site.
23/09/2020	6 Poinciana Pl Wanneroo 6065 WA	Possibly contaminated - investigation required	8/09/2021	Suspected asbestos-containing materials (ACM) are present in near-surface soils located in the central-western portion of the site.
7/10/2020	400 Buckleys Rd Bilingurr 6725 WA	Classification timeframe extended under s.14(1)(b)		

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
9/10/2020	794 Beaufort St Mount Lawley 6050 WA	Classification timeframe extended under s.14(1)(b)		
9/10/2020	71 Fourth Av Mount Lawley 6050 WA	Classification timeframe extended under s.14(1)(b)		
9/10/2020	69 Fourth Av Mount Lawley 6050 WA	Classification timeframe extended under s.14(1)(b)		
9/10/2020	788 Beaufort St Mount Lawley 6050 WA	Classification timeframe extended under s.14(1)(b)		
9/10/2020	44 Ingleton Lane Mount Lawley 6050 WA	Classification timeframe extended under s.14(1)(b)		
9/10/2020	Ingleton Lane road reserve Mount Lawley 6050 WA	Classification timeframe extended under s.14(1)(b)		
14/10/2020	Lot 16 Turee Way Paraburdoo 6754 WA	Possibly contaminated - investigation required	19/11/2020	Hydrocarbons (such as from oil) were visually identified on surface soils surrounding oil drums. However, soil and groundwater quality at the site has not been investigated.
14/10/2020	Lot 14 Camp Rd Paraburdoo 6754 WA	Report not substantiated	18/11/2020	Industrial and general wastes have been identified on the surface of the site, however no contamination has been identified.
15/10/2020	Lot 10194 (Reserve 37229), Lot 12681 (Reserve 37188), Lot 10188 (Reserve 37210), Edgewater 6027 WA	Possibly contaminated - investigation required	28/09/2022	The site is a former quarry which has been filled with materials of unknown origin (including asbestos-containing materials) and has been subject to periodic fly-tipping. Groundwater quality at the site has not been investigated.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
16/10/2020	37 Jarvis St South Bunbury 6230 WA	Possibly contaminated - investigation required	26/11/2020	The site has been used as a landfill site for the disposal of municipal wastes and fly-tipping has occurred. The extent of the landfill material requires further characterisation. Asbestos-impacted fill is buried below the site. Soil and groundwater quality at the site has not been investigated.
20/10/2020	589 Robinson St Kingsford 6701 WA	Classification timeframe extended under s.14(1)(b)		
20/10/2020	24 Padbury St Moora 6510 WA	Classification timeframe extended under s.14(1)(b)		
27/10/2020	581 Dundas Rd Forrestfield 6058 WA	Classification timeframe extended under s.14(1)(b)		
27/10/2020	Lot 9792 on Deposited Plan 182843 South Guildford 6055 WA	Classification timeframe extended under s.14(1)(b)		
27/10/2020	Barker Rd road reserve South Guildford 6055 WA	Classification timeframe extended under s.14(1)(b)		
29/10/2020	52 Griffell Way Duncraig 6023 WA	Report not substantiated	18/11/2020	No contamination has been identified.
29/10/2020	19 George St Kensington 6151 WA	Classification timeframe extended under s.14(1)(b)		
2/11/2020	55 Hope St Watermans Bay 6020 WA	Classification timeframe extended under s.14(1)(b)		
5/11/2020	439 St Albans Rd Baldivis 6171 WA	Not contaminated - unrestricted use	14/02/2023	Investigations found that no contamination is present in soil at the site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
5/11/2020	17 Gwendoline Dr Beldon 6027 WA	Classification timeframe extended under s.14(1)(b)		
12/11/2020	22 Humphreys St Lockyer 6330 WA	Classification timeframe extended under s.14(1)(b)		
16/11/2020	Lot 1547 Marble Bar Road, Newman 6753 WA	Remediated for restricted use	17/12/2020	Following remediation, hydrocarbons (such as from diesel) remain present in soil beneath the site.
19/11/2020	28 Phillimore St Fremantle 6160 WA	Possibly contaminated - investigation required	6/01/2021	Perfluoroalkyl and polyfluoroalkyl substances (PFAS), such as from fire-fighting foams, are present in groundwater at land immediately adjacent to the site's eastern boundary and have the potential to have migrated to impact groundwater beneath this site.
20/11/2020	Colville St Harrisdale 6112 WA	Remediated for restricted use	11/08/2022	Trace concentrations of hydrocarbons (such as from transformer oil) are present in groundwater in the vicinity of an electrical transformer. Residual hydrocarbon impacts (such as from transformer oil) may remain in soils beneath electrical transformer infrastructure.
23/11/2020	Lot 1792 Holmes St Southern River 6110 WA	Not contaminated - unrestricted use	5/11/2021	Investigations found that no contamination is present in soil and groundwater at the site that presents an unacceptable risk to human health, the environment or environmental receptors.
23/11/2020	South Western Hwy Manjimup 6258 WA	Possibly contaminated - investigation required	16/12/2020	Hydrocarbons (such as from petrol or diesel) are present in groundwater beneath the central portion of the site.
24/11/2020	2 Baretta Rd Wangara 6065 WA	Remediated for restricted use	9/12/2020	Residual hydrocarbons (such as from transformer oil), remain present in soils beneath the existing electrical transformer.
2/12/2020	52 Sayer Rd Hope Valley 6165 WA	Decontaminated	15/09/2021	Following remediation, no known contamination remains at the site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
2/12/2020	Lot 98 Sayer Road, Hope Valley 6165 WA	Possibly contaminated - investigation required	28/10/2021	Unauthorised disposal of wastes appears to have historically occurred at this site. However, soil and groundwater quality at the site has not been fully investigated.
4/12/2020	Elliot Rd Trigg 6029 WA	Possibly contaminated - investigation required	7/01/2021	Following remediation, no contamination remains in the immediate vicinity of the transformer. However, the extent of asbestos-containing material (ACM) remaining in soil within the remainder of the road reserve has not been investigated.
9/12/2020	Lot 500, Reserve 50069, Macham Road, Red Hill 6056 WA	Possibly contaminated - investigation required	20/01/2021	Unauthorised disposal of wastes has occurred on this site. However, soil and groundwater quality at the site has not been investigated.
14/12/2020	State Forest 15, Hoffman 6220 WA	Classification timeframe extended under s.14(1)(b)		
15/12/2020	State Forest 14, Nanga Brook 6220 WA	Possibly contaminated - investigation required	14/01/2021	Perfluoroalkyl and polyfluoroalkyl substances (PFAS) (such as from fire-fighting foams) have been used at the site. Investigation is required to determine the nature and extent of any impacts, and to inform assessment of potential risks.
15/12/2020	State Forest 14, Wagerup 6215 WA	Possibly contaminated - investigation required	14/01/2021	Perfluoroalkyl and polyfluoroalkyl substances (PFAS) (such as from fire-fighting foams) have been used at the site. Investigation is required to determine the nature and extent of any impacts, and to inform assessment of potential risks
15/12/2020	Mining Lease ML1SA, Myara 6207 WA	Possibly contaminated - investigation required	14/01/2021	Perfluoroalkyl and polyfluoroalkyl substances (PFAS) (such as from fire-fighting foams) have been used at the site. Investigation is required to determine the nature and extent of any impacts, and to inform assessment of potential risks.
15/12/2020	State Forest 14, Solus 6207 WA	Possibly contaminated - investigation required	14/01/2021	Perfluoroalkyl and polyfluoroalkyl substances (PFAS) (such as from fire-fighting foams) have been used at the site. Investigation is required to determine the nature and extent of any impacts, and to inform assessment of potential risks.
18/12/2020	Gt Northern Hwy Mueller Ranges 6770 WA	Decontaminated	2/06/2021	Following remediation, no contamination remains at the site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
23/12/2020	Crown Reserve 44325, Lot 195 Rifle Range Road, Lake Austin 6640 WA	Report not substantiated	20/01/2021	No contamination has been identified.
23/12/2020	Crown Reserve 22459, Port Denison 6525 WA	Report not substantiated	14/01/2021	No contamination has been identified.
4/01/2021	Lot 208 Coolgardie-esperance Hwy Norseman 6443 WA	Possibly contaminated - investigation required	17/02/2021	Uncontrolled disposal of wastes has occurred on this site including unregulated mixed landfilling. However, soil and groundwater quality at the site has not been investigated
5/01/2021	Styles Rd Port Hedland 6721 WA	Classification timeframe extended under s.14(1)(b)		
7/01/2021	5 Market St Rockingham 6168 WA	Remediated for restricted use	2/02/2022	Asbestos-impacted fill material is present across the site below a geofabric warning barrier and a layer of clean capping material comprising orange/brown sand. The sand cap above the warning barrier is on average 0.55 metres thick, with a minimum thickness of 0.26 metres along the site's western boundary.
7/01/2021	31 McNicholl St Rockingham 6168 WA	Possibly contaminated - investigation required	28/01/2021	Fragments of asbestos-containing material (ACM) have been found present in surface soils across the site.
7/01/2021	33 McNicholl St Rockingham 6168 WA	Possibly contaminated - investigation required	28/01/2021	Fragments of asbestos-containing material (ACM) have been found present in surface soils across the site.
7/01/2021	3 Market St Rockingham 6168 WA	Possibly contaminated - investigation required	28/01/2021	Fragments of asbestos-containing material (ACM) have been found present in surface soils across the site.
7/01/2021	5 Market St Rockingham 6168 WA	Remediated for restricted use	2/02/2022	Asbestos-impacted fill material is present across the site below a geofabric warning barrier and a layer of clean capping material comprising orange/brown sand. The sand cap above the warning barrier is on average 0.55 metres thick, with a minimum thickness of 0.26 metres along the site's western boundary.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
7/01/2021	Market Street road reserve Rockingham 6168 WA	Possibly contaminated - investigation required	28/01/2021	Fragments of asbestos-containing material (ACM) have been found present in surface soils across the site.
7/01/2021	McNicholl Street road reserve Rockingham 6168 WA	Possibly contaminated - investigation required	28/01/2021	Fragments of asbestos-containing material (ACM) have been found present in surface soils across the site.
8/01/2021	Crown Reserve 23357, Lot 27271, No. 241 Adamson Road, Merredin 6415 WA	Report not substantiated	21/01/2021	No contamination has been identified.
8/01/2021	2140 Carnarvon-mullewa Rd Mullewa 6630 WA	Classification timeframe extended under s.14(1)(b)		
13/01/2021	Lot 87 Sutcliffe St Condungup 6450 WA	Possibly contaminated - investigation required	10/02/2021	<p>Fragments of asbestos-containing material (ACM) have been identified (and removed) from surface soils in the north-eastern portion of Lot 87. ACM may remain at depth.</p> <p>ACM-impacted soils are present to the east of the administration building beneath a geofabric barrier and approximately half a metre of clean soil.</p> <p>ACM-impacted soils are present along the eastern boundary of Lot 87 which have been loosely capped in plastic and a thin cover of soil.</p>
14/01/2021	207 Augustus St West End 6530 WA	Possibly contaminated - investigation required	19/05/2021	Per-and poly-fluoroalkyl substances (PFAS) (such as from fire-fighting foams) are present in groundwater beneath the site. Further investigations are required to determine the nature and extent of impacts, and to inform assessment of potential risks.
14/01/2021	222 Shenton St West End 6530 WA	Possibly contaminated - investigation required	4/10/2019	Hydrocarbons (such as from petrol or diesel) and the chemicals perfluoroalkyl and polyfluoroalkyl substances (PFAS) are potentially present in soil and groundwater beneath the site.
14/01/2021	Lot 300 Port Way, West End 6530 WA	Possibly contaminated - investigation required	11/05/2021	<p>Hydrocarbon impacted groundwater (such as from petrol) is present beneath the eastern portion of the site, which has migrated from the adjacent fuel terminal.</p> <p>Per and poly-fluoroalkyl substances (PFAS) are also present in groundwater beneath the site.</p>

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
15/01/2021	99 Gibbs Rd Nowergup 6032 WA	Report not substantiated	11/08/2021	No contamination has been identified.
15/01/2021	12 Annois Rd Bibra Lake 6163 WA	Possibly contaminated - investigation required	6/01/2021	Localised petroleum hydrocarbon impacts (such as from transformer oil) are in soil within the substation transformer soak well area of the site.
18/01/2021	6 Mosshall Place Vasse 6280 WA	Classification timeframe extended under s.14(1)(b)		
18/01/2021	39 Whitemoss Drive Vasse 6280 WA	Classification timeframe extended under s.14(1)(b)		
18/01/2021	25 Shovelboard Way Vasse 6280 WA	Classification timeframe extended under s.14(1)(b)		
18/01/2021	37 Whitemoss Drive Vasse 6280 WA	Classification timeframe extended under s.14(1)(b)		
18/01/2021	46 Whitemoss Drive Vasse 6280 WA	Classification timeframe extended under s.14(1)(b)		
18/01/2021	21 Shovelboard Way Vasse 6280 WA	Classification timeframe extended under s.14(1)(b)		
18/01/2021	12 Mudlark Place Vasse 6280 WA	Classification timeframe extended under s.14(1)(b)		

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
18/01/2021	7 Mosshall Place Vasse 6280 WA	Classification timeframe extended under s.14(1)(b)		
18/01/2021	19 Shovelboard Way Vasse 6280 WA	Classification timeframe extended under s.14(1)(b)		
19/01/2021	97 Northcote St Chidlow 6556 WA	Possibly contaminated - investigation required	24/02/2021	Asbestos containing material (ACM) is present in surface and/or subsurface soils at the site.
4/02/2021	Lot 101 Capricorn 6642 WA	Contaminated - restricted use	17/03/2021	Following remediation, hydrocarbons (such as from lubricating oil), remain present in soils beneath site infrastructure. Excavated waste soil remains on site contained within large storage containers that require offsite disposal and management.
5/02/2021	43 Poole St Welshpool 6106 WA	Contaminated - remediation required	7/01/2015	Chlorinated hydrocarbons (such as trichloroethene), metals, nutrients and organochlorine pesticides (such as chlordane) are present in groundwater beneath the southern portion of this site. Copper and organochlorine pesticides (such as chlordane) are present in soils across the site.
5/02/2021	Lot 2999 West End, West End 6530 WA	Classification timeframe extended under s.14(1)(b)		
12/02/2021	87 Whitfield St Bassendean 6054 WA	Possibly contaminated - investigation required	11/03/2021	Waste materials including metal and building rubble are present in subsurface soils across the majority of the site. The waste material is present at depths of between 0.5 and 2.0 meters below ground level.
15/02/2021	Northcote St Chidlow 6556 WA	Report not substantiated	28/07/2021	There are no grounds to indicate contamination of the site.
4/03/2021	Swan River foreshore East Perth 6004 WA	Classification timeframe extended under s.14(1)(b)		

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
9/03/2021	Lot 800 on DP 415757 (formerly part of Lot 70 and 71 Arthur Street), Dayton 6055 WA	Possibly contaminated - investigation required	21/04/2021	Unauthorised disposal of wastes has occurred on this site. However, soil and groundwater quality at the site has not been investigated.
9/03/2021	5 Market St Rockingham 6168 WA	Remediated for restricted use	2/02/2022	Asbestos-impacted fill material is present across the site below a geofabric warning barrier and a layer of clean capping material comprising orange/brown sand. The sand cap above the warning barrier is on average 0.55 metres thick, with a minimum thickness of 0.26 metres along the site's western boundary.
23/03/2021	419 Holmes St Southern River 6110 WA	Possibly contaminated - investigation required	29/04/2021	Unauthorised importation of fill has occurred on this site. Further investigation is required to determine the nature and extent of potential impacts, and to inform an adequate assessment of risk.
31/03/2021	42 Dale Pl Orange Grove 6109 WA	Not contaminated - unrestricted use	2/06/2022	Investigations have not identified contamination at the site.
31/03/2021	5 Market St Rockingham 6168 WA	Remediated for restricted use	2/02/2022	Asbestos-impacted fill material is present across the site below a geofabric warning barrier and a layer of clean capping material comprising orange/brown sand. The sand cap above the warning barrier is on average 0.55 metres thick, with a minimum thickness of 0.26 metres along the site's western boundary.
9/04/2021	within Lots 116 and 5418, Wittenoom 6751 WA	Contaminated - remediation required	25/05/2021	Free asbestos fibres are present in the soils at the site.
15/04/2021	Lot 6043 On Deposited Plan 221011 Port Hedland 6721 WA	Possibly contaminated - investigation required	20/05/2021	Per-and poly-fluoroalkyl substances (PFAS) (such as from fire-fighting foams/PFAS-containing waste) are present in groundwater beneath the site. Further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.
15/04/2021	Anderson Street road reserve Port Hedland 6721 WA	Possibly contaminated - investigation required	20/05/2021	Per-and poly-fluoroalkyl substances (PFAS) (such as from fire-fighting foams/PFAS-containing waste) are present in groundwater beneath the site. Further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.
15/04/2021	105 Wilson St Port Hedland 6721 WA	Possibly contaminated - investigation required	20/05/2021	Per-and poly-fluoroalkyl substances (PFAS) (such as from fire-fighting foams/ PFAS-containing waste) and hydrocarbons (such as from petrol, diesel and oil) are present in groundwater beneath the site. Further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.
22/04/2021	38 Stanley Rd Wellesley 6233 WA	Possibly contaminated - investigation required	2/06/2021	Uncontrolled importation of fill material has occurred on this site. Further investigation is required to determine the nature and extent of potential impacts, and to inform assessment of potential risks.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
28/04/2021	Lot 500 Tesla Road, Rockingham 6168 WA	Possibly contaminated - investigation required	2/06/2021	Hydrocarbons (such as from petrol or diesel) are present in soil and groundwater along the south-western boundary of the site.
30/04/2021	200 Versteeg Gr Martin 6110 WA	Report not substantiated	3/06/2021	Following enquiries, no secondary evidence of contamination has been identified at the site.
30/04/2021	Lot 2898 Dampier Rd Stove Hill 6714 WA	Possibly contaminated - investigation required	12/07/2021	Investigations found that no contamination is present in soil at the site. However, the investigations were limited and at the time of classification potential sources of contamination have not been fully investigated.
3/05/2021	540 Nicholson Rd Forrestdale 6112 WA	Decontaminated	27/07/2022	Following remediation, no known contamination remains at the site.
4/05/2021	11 Glassford Rd Kewdale 6105 WA	Possibly contaminated - investigation required	9/06/2021	Hydrocarbons (such as from diesel) are present in soil beneath the site.
6/05/2021	136 Serpentine Rd Albany 6330 WA	Report not substantiated	17/06/2021	Asbestos is present in asbestos downpipes and in localised soils immediately adjacent to the downpipes. No contamination has been identified that is representative of general site conditions.
10/05/2021	12 Nineteenth Av Jurien Bay 6516 WA	Report not substantiated	10/06/2021	Following enquiries, no secondary evidence of contamination has been identified at the site.
13/05/2021	Northcote St Chidlow 6556 WA	Report not substantiated	28/07/2021	There are no grounds to indicate contamination of the site.
14/05/2021	Lot 728 on DP 192818, Ledge Point 6043 WA	Report not substantiated	10/06/2021	No contamination has been identified.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
19/05/2021	1160 Albany Hwy Bentley 6102 WA	Classification timeframe extended under s.14(1)(b)		
25/05/2021	Grand Ocean Ent Burns Beach 6028 WA	Remediated for restricted use	30/06/2021	Following remediation, hydrocarbons (such as from transformer oil) remain in soil at a depth of 1.5 metres in the vicinity of the electrical transformer.
27/05/2021	Lot 120 Roebourne-Point Samson Road, Wickham 6720 WA	Possibly contaminated - investigation required	8/07/2021	Groundwater beneath the site contains elevated levels of nutrients (such as nitrogen and phosphorus) and metals (such as arsenic, cobalt and copper) suspected to be associated with the operation of the wastewater treatment plant.
28/05/2021	56 Albany Hwy Williams 6391 WA	Possibly contaminated - investigation required	2/12/2021	Hydrocarbons (such as from diesel) are present in soil and groundwater beneath the central northern portion of the site.
31/05/2021	Lot 501 on Deposited Plan 73470 Port Hedland 6721 WA	Classification timeframe extended under s.14(1)(b)		
31/05/2021	106 Anderson St Port Hedland 6721 WA	Classification timeframe extended under s.14(1)(b)		
31/05/2021	109 Wilson St Port Hedland 6721 WA	Classification timeframe extended under s.14(1)(b)		
31/05/2021	Lot 943 on Deposited Plan 171785 Port Hedland 6721 WA	Classification timeframe extended under s.14(1)(b)		
22/06/2021	3 Barker St Bedford 6052 WA	Possibly contaminated - investigation required	4/08/2021	Hydrocarbons (such as from aged petrol fuel) have been detected in water collected from the on-site groundwater bore. The source of the hydrocarbons is not clear, but may be associated with groundwater contamination related to the historical operation of a service station at 168 Walter Road, Bedford.
23/06/2021	5 Yanana St Wedgefield 6721 WA	Possibly contaminated - investigation required	26/07/2021	Hydrocarbons (such as from petrol or diesel) were visually identified on surface soil surrounding the refuelling station along the northern boundary.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
24/06/2021	16 Munda Way Wedgefield 6721 WA	Possibly contaminated - investigation required	26/07/2021	Stained soils, suspected to be from hydrocarbons (such as from petrol, oil and/or diesel) were visually identified at the site.
28/06/2021	99 Boundary Rd Kingsford 6701 WA	Possibly contaminated - investigation required	12/07/2021	Buried waste and hydrocarbons (such as from diesel or oil) are present in soil beneath the site in localised areas. Further investigation of groundwater quality is required.
28/06/2021	71 Southern River Rd Gosnells 6110 WA	Report not substantiated	21/07/2021	No contamination has been identified.
1/07/2021	Reserve 22465 Lot 203 on DP 37681, Norseman 6443 WA	Possibly contaminated - investigation required	28/07/2021	Uncontrolled disposal of wastes has occurred on this site. However, soil and groundwater quality at the site has not been investigated.
8/07/2021	Approximate spatial representation of Part of LOT 47 ON DEPOSITED PLAN 238630 Wiluna 6646 WA	Possibly contaminated - investigation required	18/08/2021	Hydrocarbons (such as from diesel or oil) were present in soils at around 1.2 to 1.8 meters below ground level in the location of a former underground sump. Impacted soils have been removed where possible, although the presence of site infrastructure has limited remedial works and soil impacts have not been delineated.
15/07/2021	770 Brookton Hwy Roleystone 6111 WA	Possibly contaminated - investigation required	11/08/2021	Hydrocarbons (such as from petrol or diesel) are present in groundwater beneath the site.
15/07/2021	879 Warton Rd Piara Waters 6112 WA	Decontaminated	12/08/2022	Following remediation, no known contamination remains at the site.
15/07/2021	17 Brisbane St Perth 6000 WA	Contaminated - remediation required	25/08/2021	Hydrocarbons (such as from petrol) are present in soil, groundwater and soil vapour beneath the former service station site. Hydrocarbons in soil vapour extend off-site to the south-west beneath adjacent commercial and residential properties along Pier Street. Hydrocarbons are also likely to extend off-site to the south-west in groundwater.
19/07/2021	1406 George Grey Dr Yallabatharra 6535 WA	Possibly contaminated - investigation required	25/08/2021	Hydrocarbons (such as from diesel) are present in soils within the vicinity of the fuel bowser, at the source of the spill.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
28/07/2021	Lot 9010 On Deposited Plan 414089, Piara Waters 6112 WA	Classification timeframe extended under s.14(1)(b)		
29/07/2021	Lots 8 & 9 corner Brand Highway and Edwards Place, Muchea 6501 WA	Remediated for restricted use	29/09/2021	Hydrocarbons (such as from petrol or diesel) are present in groundwater beneath the adjacent service station, extending off-site to affect groundwater beneath the northwest portion of this site.
3/08/2021	91 Canning Hwy East Fremantle 6158 WA	Report not substantiated	28/10/2021	No known contamination has been identified.
3/08/2021	93 Canning Hwy East Fremantle 6158 WA	Report not substantiated	28/10/2021	No known contamination has been identified.
16/08/2021	66 Ilmenite Cr Capel 6271 WA	Classification timeframe extended under s.14(1)(b)		
19/08/2021	31 Rudloc Rd Morley 6062 WA	Possibly contaminated - investigation required	8/09/2021	Volatile organic compounds (such as from chlorinated and petroleum hydrocarbons) are present in sediment within a soak well at the site.
19/08/2021	Great Northern Hwy Cooladar Hill 6638 WA	Classification timeframe extended under s.14(1)(b)		
24/08/2021	Crown Reserve 22897, Lot 5342, Darlington 6070 WA	Classification timeframe extended under s.14(1)(b)		
25/08/2021	Albany Hwy Gosnells 6110 WA	Possibly contaminated - investigation required	22/09/2021	Hydrocarbon-contaminated groundwater (such as from petrol and diesel) is present beneath this site and is likely to have migrated beneath this site from the adjacent service station.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
27/08/2021	Road reserves adjacent to Lot 45, No. 51 Stanley Rd, Wellesley 6233 WA	Possibly contaminated - investigation required	15/09/2021	Groundwater beneath this site has been impacted by putrescible landfill leachate. Groundwater impacts are characterised by elevated total dissolved solids, ammonia, metals (including aluminium and iron), hydrocarbons (such as from oils, greases, humics and fatty acids) and per- and poly-fluoroalkyl substances (PFAS).
27/08/2021	Lot 15 Richards Rd, Waroona 6215 WA	Possibly contaminated - investigation required	20/10/2021	The site has been used as a landfill site the disposal of inert waste and other waste materials such as, asbestos, green waste, treated timber and shredder floc.
1/09/2021	335-337 Pier St Perth 6000 WA	Possibly contaminated - investigation required	5/10/2021	Hydrocarbons (such as from petrol) are present in soil, groundwater and soil vapour beneath the adjacent former service station. Hydrocarbons in soil vapour extend from the former service station to the south-west beneath the site. Hydrocarbons are present in indoor air within site buildings. Hydrocarbons in groundwater are also likely to extend from the service station to the south-west beneath the site.
1/09/2021	331-333 Pier St Perth 6000 WA	Possibly contaminated - investigation required	5/10/2021	Hydrocarbons (such as from petrol) are present in soil, groundwater and soil vapour beneath the adjacent former service station. Hydrocarbons in soil vapour extend from the former service station to the south-west beneath the site. Hydrocarbons are present in indoor air within site buildings. Hydrocarbons in groundwater are also likely to extend from the service station to the south-west beneath the site.
6/09/2021	23 Karoborup Rd Carabooda 6033 WA	Report not substantiated	12/10/2021	No known contamination has been identified.
16/09/2021	Lot 286 Alison Parade, Bayonet Head 6330 WA	Report not substantiated	6/10/2021	No known contamination has been identified.
16/09/2021	26 Opportunity St Wangara 6065 WA	Contaminated - remediation required	28/10/2021	Landfill gas (such as methane and carbon dioxide) is present beneath the adjacent former landfill which has migrated beneath this site.
16/09/2021	30 Opportunity St Wangara 6065 WA	Contaminated - remediation required	28/10/2021	Landfill gas (such as methane and carbon dioxide) is present beneath the adjacent former landfill which has migrated beneath this site.
16/09/2021	34 Opportunity St Wangara 6065 WA	Contaminated - remediation required	28/10/2021	Landfill gas (such as methane and carbon dioxide) is present beneath the adjacent former landfill which has migrated beneath this site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
28/09/2021	603 Gas Bay Rd Gnarabup 6285 WA	Possibly contaminated - investigation required	3/11/2021	Arsenic, lead, manganese, nitrate and phosphorus are present in groundwater beneath the site.
29/09/2021	2 Mary St Northampton 6535 WA	Report not substantiated	2/11/2021	No contamination has been identified.
30/09/2021	Lot 26524 Bruce Rock East Rd Bruce Rock 6418 WA	Report not substantiated	2/11/2021	No known contamination has been identified.
30/09/2021	Lot 228 Colley Rd Newman 6753 WA	Possibly contaminated - investigation required	8/11/2021	Fragments of potential asbestos-containing material were visually identified in surface soils of the middle and western portion of the site. The north-eastern portion of the site has been used for landfilling, including the likely disposal of degradable wastes, such as household waste.
4/10/2021	6 Clavering Rd Bayswater 6053 WA	Possibly contaminated - investigation required	2/11/2021	Per-and poly-fluoroalkyl substances (PFAS) (such as from fire-fighting foams) are present in soil, sediments and groundwater at the site. Further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential environmental risks.
8/10/2021	60 Milloy St Morawa 6623 WA	Classification timeframe extended under s.14(1)(b)		
11/10/2021	Gooda Binya Aboriginal Community, Lot 71 on Deposited Plan 216736, Marble Bar 6760 WA	Report not substantiated	1/11/2021	No known contamination has been identified.
14/10/2021	9 McFie St Nullagine 6758 WA	Possibly contaminated - investigation required	10/11/2021	Waste material (such as household waste, car bodies and batteries), fragments of potential asbestos-containing material and hydrocarbon (such as from diesel or oil) have been visually identified at the site.
14/10/2021	Lot 500 Jigalong Mission Rd Jigalong 6753 WA	Possibly contaminated - investigation required	10/11/2021	Fragments of potential asbestos-containing material and hydrocarbon-impacted soils (associated with fuel storage and dispensing equipment) were visually identified in surface soils of Lot 500. Waste material, comprising putrescible and commercial wastes (such as oil drums and car bodies) has been deposited across the site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
19/10/2021	Lot 1510 Rocklea 6751 WA	Possibly contaminated - investigation required	24/11/2021	Petroleum hydrocarbons (such as from oil, grease and diesel) are present in soil and surface water within an on-site drainage line due to a release of impacted wastewater in September 2021.
25/10/2021	Lot 512 (Reserve 49652) and Lot 506 (Reserve 8485), Busselton 6280 WA	Classification timeframe extended under s.14(1)(b)		
3/11/2021	Warakurna Aboriginal Community, Lot 9, Ngaanyatjarra-Giles 0872 WA	Possibly contaminated - investigation required	14/12/2021	Hydrocarbons (such as from oil and diesel) have been visually identified at the power station on the ground at and adjacent to fill point and generators. Portions of the site have been used as a landfill for the disposal of various household and construction waste. Possible asbestos-containing materials have been identified on the surface of the scrap vehicle areas.
3/11/2021	Lot 8 Warburton 6431 WA	Possibly contaminated - investigation required	16/12/2021	Hydrocarbons (such as from oil and diesel) have been visually identified on the ground near the fill point and beneath above-ground storage tanks. Portions of the site have been used as a landfill for the disposal of various household and construction waste. Possible asbestos-containing materials have been identified on the surface of the current and former landfill areas.
3/11/2021	Kanpa Aboriginal Community, Kanpa 0872 WA	Possibly contaminated - investigation required	15/12/2021	A portion of the site to the north-east of the community is being used as a landfill for the disposal of various household and construction waste. Possible asbestos-containing materials have been identified on the surface of the scrap vehicle storage area to the south-west of the community. Hydrocarbon staining (such as from oil and diesel) appears present on the ground near the power station infrastructure.
3/11/2021	Jameson Aboriginal Community, Lot 9, Ngaanyatjarra-Giles 0872 WA	Possibly contaminated - investigation required	13/12/2021	Hydrocarbons (such as from oil/diesel) have been visually identified on the ground adjacent to the power station fill point and tanker unloading area in the northern portion of the site. Portions of the site have been used as a landfill for the disposal of various household and construction waste. Possible asbestos-containing materials have been identified on the surface of the current and former landfill and scrap vehicle areas.
3/11/2021	Lot 2 Gibson Desert South 0872 WA	Possibly contaminated - investigation required	16/12/2021	Hydrocarbons (such as from oil/diesel) have been visually identified at the power station on the ground adjacent to the fill point. Portions of the site have been used as a landfill for the disposal of various household and construction waste. Possible asbestos-containing materials have been identified on the surface of the current and former landfill and scrap vehicle areas.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
3/11/2021	Lot 9 Ngaanyatjarra-Giles 0872 WA	Possibly contaminated - investigation required	14/12/2021	Hydrocarbons (such as from oil/diesel) have been visually identified on the ground adjacent to the above ground storage tank and fill point. Portions of the site have been used as a landfill for the disposal of various household and construction waste. Possible asbestos-containing materials have been identified on the surface of the current and former landfill areas as well as the scrap vehicle storage areas.
5/11/2021	100 Timewell Rd Mckail 6330 WA	Possibly contaminated - investigation required	1/12/2021	Nutrients (such as ammonia and phosphorus), metals and pathogens are present in groundwater and surface water at the site associated with current and historical wastewater treatment activities.
15/11/2021	Lot 743 Trinity Rise College Grove 6230 WA	Possibly contaminated - investigation required	22/12/2021	Disposal of municipal landfill waste has occurred on this site. However, soil and groundwater quality at the site has not been formally investigated.
15/11/2021	Lot 1 and 20 on Deposited Plan144064, Marble Bar 6760 WA	Possibly contaminated - investigation required	15/12/2021	Tailings from historical gold ore processing operations remain on-site which may contain cyanide and metals such as arsenic, lead, zinc and mercury at elevated concentrations. Asbestos containing materials are present on the ground surface. However, soil quality at the site has not been fully investigated.
16/11/2021	Lot 209 Riverside Gardens, Bayswater 6053 WA	Possibly contaminated - investigation required	16/12/2021	The site has historically been used as a landfill site. Waste materials beneath the site are generating landfill gases and asbestos containing materials may be present in sub-surface soil. Groundwater quality at the site has not been fully investigated.
16/11/2021	Crown reserve 17563, Capricorn 6642 WA	Possibly contaminated - investigation required	16/12/2021	Tailings from historical gold ore processing operations remain on-site which may contain cyanide, sulfate and metals such as arsenic, lead and mercury at elevated concentrations. However, soil quality at the site has not been fully investigated.
29/11/2021	126 Bradford St Yokine 6060 WA	Possibly contaminated - investigation required	22/12/2021	Hydrocarbons (such as from oil or diesel) were visually identified during the excavation of a two by two meter hole for the purpose of installing a floodlight on the sports field in the north east of the site. The site has historically been used as a landfill site. However, soil and groundwater quality at the site has not been investigated.
16/12/2021	10 Third Rd Armadale 6112 WA	Decontaminated	7/12/2022	Following remediation, no known contamination remains at the site.
20/12/2021	143 Station St East Cannington 6107 WA	Classification timeframe extended under s.14(1)(b)		

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
20/12/2021	141 Station St East Cannington 6107 WA	Classification timeframe extended under s.14(1)(b)		
20/12/2021	139 Station St East Cannington 6107 WA	Classification timeframe extended under s.14(1)(b)		
20/12/2021	13 Little Cl East Cannington 6107 WA	Classification timeframe extended under s.14(1)(b)		
20/12/2021	11 Little Cl East Cannington 6107 WA	Classification timeframe extended under s.14(1)(b)		
20/12/2021	9 Little Cl East Cannington 6107 WA	Classification timeframe extended under s.14(1)(b)		
20/12/2021	131 Station St East Cannington 6107 WA	Classification timeframe extended under s.14(1)(b)		
23/12/2021	Affected road reserve (Short Street) 1443 Albany Hwy, Cannington 6107 WA	Classification timeframe extended under s.14(1)(b)		
12/01/2022	22 Stephen St Bunbury 6230 WA	Remediated for restricted use	23/02/2022	Hydrocarbons (such as from diesel and asphalt) and suspected asbestos-impacted fill material remain in soils at the site.
17/01/2022	10 Wanaping Rd Kenwick 6107 WA	Possibly contaminated - investigation required	28/02/2022	Unauthorised disposal of wastes has occurred on this site. Household waste, including asbestos, is present below ground level that has been subjected to mechanical action to level the site. Surface wastes, including asbestos, appear to have been burnt. Soil and groundwater quality at the site has not been investigated.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
20/01/2022	Reserve 14537, Lot 11425 on DP 85190, Dumbleyung 6350 WA	Possibly contaminated - investigation required	24/02/2022	The site has been used as a landfill for the disposal of wastes, and as a rifle range. However, soil and groundwater quality at the site has not been investigated.
28/01/2022	part of Lot 1501 on Deposited Plan 74341, Mardie 6417 WA	Report not substantiated	3/03/2022	Following minor remedial works, no known contamination remains at the site.
1/02/2022	3 Albert St North Perth 6006 WA	Possibly contaminated - investigation required	17/03/2022	Asbestos containing material is present in soil beneath the school oval.
4/02/2022	Lot 806 Reading Place, Birchmont 6214 WA	Report not substantiated	3/03/2022	No known contamination has been identified.
4/02/2022	14 Merrifield Av Kelmscott 6111 WA	Classification timeframe extended under s.14(1)(b)		
16/02/2022	314 Kenwick Rd Maddington 6109 WA	Classification timeframe extended under s.14(1)(b)		
21/02/2022	Reserve 30710, Lot 34 Dowerin Kalannie & Old Koorda Roads, Minnivale 6462 WA	Possibly contaminated - investigation required	6/04/2022	The site has been used as a landfill site for the disposal of degradable wastes including household, green waste, and asbestos. However, soil and groundwater quality at the site has not been investigated.
22/02/2022	Lot 5 Congdon St North Fremantle 6159 WA	Contaminated - remediation required	4/04/2022	Asbestos-impacted fill is present in sub-surface soil at depths up to 1 metre below ground level across the site.
24/02/2022	25 John Xxiii Av Mount Claremont 6010 WA	Classification timeframe extended under s.14(1)(b)		

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
4/03/2022	Lot 307 Goldfields Hwy Boulder 6432 WA	Possibly contaminated - investigation required	31/03/2022	Unauthorised disposal of waste materials has occurred on this site. However, soil and groundwater quality at the site has not been investigated.
8/03/2022	16 The Avenue Picton 6229 WA	Possibly contaminated - investigation required	13/04/2022	Hydrocarbon (such as from petrol or diesel) are present in soils and groundwater beneath the location of former underground storage tanks in the south of the site.
8/03/2022	Lot 510 on Plan 413497, Wallaroo 6429 WA	Contaminated - restricted use	30/03/2022	The site is being used for the treatment and disposal of various wastes including solid and liquid waste, class IV and class V intractable wastes.
10/03/2022	25 Chapman Rd St James 6102 WA	Classification timeframe extended under s.14(1)(b)		
14/03/2022	5482 Geraldton-mount Magnet Rd Ambania 6632 WA	Possibly contaminated - investigation required	26/04/2022	A portion of the site has been used as a private farm landfill. A large quantity of drums, scrap metal and tyres located in the north-east portion of the site have been burnt in a bushfire. The drums may have contained residual sump oil or herbicides.
18/03/2022	Reserve 52910, Lot 8000 Towle Way, Parkerville 6081 WA	Classification timeframe extended under s.14(1)(b)		
22/03/2022	350 Keane Rd Forrestdale 6112 WA	Classification timeframe extended under s.14(1)(b)		
29/03/2022	2465 Mogumber Rd Mindarra 6503 WA	Possibly contaminated - investigation required	11/05/2022	Following partial remediation, asbestos fragments remain in soil across a widespread area in the vicinity of the historic settlement camp in the northern portion of the site. No additional information is known of the contamination status of soil and groundwater at the site.
8/04/2022	Lot 9000 Moramocking Road (Southern parcel), Wandering 6308 WA	Possibly contaminated - investigation required	11/05/2022	The site has been used as a landfill site for the disposal of asbestos containing material and general waste material. However, soil and groundwater quality at the site has not been investigated.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
12/04/2022	720 Welshpool Rd Wattle Grove 6107 WA	Report not substantiated	11/05/2022	No known contamination has been identified.
14/04/2022	Lots 500 & 694, Kevin Richards Memorial Oval, Millars Well 6714 WA	Possibly contaminated - investigation required	16/06/2022	Limited testing at the site has found that per-and poly-fluoroalkyl substances (PFAS) (such as from fire-fighting foams) are present in surface soil. Further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.
21/04/2022	Lot 129 on Deposited Plan 213482, Pippingarra 6722 WA	Possibly contaminated - investigation required	1/06/2022	Asbestos-containing material was identified across surface soil at the site. Hydrocarbons (such as from oil) were visually identified on surface soil surrounding damaged storage containers.
21/04/2022	Lot 147 on Deposited Plan 182405, Pippingarra 6722 WA	Possibly contaminated - investigation required	1/06/2022	Asbestos-containing material was identified in soils within the central western portion of the site.
2/05/2022	24 Hester Rd Hester 6255 WA	Classification timeframe extended under s.14(1)(b)		
5/05/2022	286 Stirling Cr Hazelmere 6055 WA	Possibly contaminated - investigation required	5/01/2023	Hydrocarbons (such as from petrol and diesel) are present in soil and groundwater. Further investigations are required to determine lateral extent of the contamination.
16/05/2022	57 Farrington Rd Leeming 6149 WA	Classification timeframe extended under s.14(1)(b)		
16/05/2022	4 Aulberry Pde Leeming 6149 WA	Classification timeframe extended under s.14(1)(b)		
17/05/2022	Almeria Pde Muchea 6501 WA	Contaminated - restricted use	22/06/2022	Hydrocarbons (such as from transformer oil) are present in surface soil and sub-soil (at 2 metres below ground level) surrounding the pole-top transformer.
19/05/2022	Lot 1864 Barter Road, Naval Base 6165 WA	Classification timeframe extended under s.14(1)(b)		

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
23/05/2022	294 High Rd Riverton 6148 WA	Report not substantiated	7/07/2022	No known contamination has been identified.
24/05/2022	Lot 5 Congdon St North Fremantle 6159 WA	Contaminated - remediation required	4/04/2022	Asbestos-impacted fill is present in sub-surface soil at depths up to 1 metre below ground level across the site.
25/05/2022	169 Hay St East Perth 6004 WA	Possibly contaminated - investigation required	15/06/2022	Hydrocarbons (such as from diesel) are present in sub-surface soils in the vicinity of a decommissioned underground fuel storage tank in the south-east portion of the site.
1/06/2022	Lot 501 on Deposited Plan 400250 Millars Well 6714 WA	Possibly contaminated - investigation required	16/06/2022	Limited testing at the site has found that per-and poly-fluoroalkyl substances (PFAS) (such as from fire-fighting foams) are present in surface soil. Further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.
1/06/2022	Lot 502 on Deposited Plan 400250 Millars Well 6714 WA	Possibly contaminated - investigation required	16/06/2022	Limited testing at the site has found that per-and poly-fluoroalkyl substances (PFAS) (such as from fire-fighting foams) are present in surface soil. Further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.
24/06/2022	1 Sanderson St Pingrup 6343 WA	Report not substantiated	3/08/2022	No known contamination has been identified.
24/06/2022	207 Bushmead Rd Hazelmere 6055 WA	Classification timeframe extended under s.14(1)(b)		
27/06/2022	348 Queen Elizabeth Av Ambergate 6280 WA	Report not substantiated	12/08/2022	No known contamination has been identified.
27/06/2022	Lot 626 on Deposited Plan 70861, Minyirr 6725 WA	Report not substantiated	11/08/2022	No known contamination has been identified.
30/06/2022	Lot 351 on Deposited Plan 74327 Newman 6753 WA	Possibly contaminated - investigation required	12/08/2022	Per-and poly-fluoroalkyl substances (PFAS) (such as from fire-fighting foams/PFAS-containing waste) are present in groundwater beneath the site. Further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
1/07/2022	2 Robb Rd North Coogee 6163 WA	Remediated for restricted use	16/06/2015	Hydrocarbons (such as from diesel or oil) are present in shallow soil beneath the power station building. Metals (such as copper, nickel and zinc) are present in groundwater beneath the site.
15/07/2022	35 Roberts St, Lot 300 & Road Reserve, South Hedland 6722 WA	Possibly contaminated - investigation required	23/10/2018	Hydrocarbons (such as from petrol) are present in groundwater beneath the east and south-eastern portions of the site. Soil vapour has not been investigated and groundwater requires further investigation off-site to the east and south east.
15/07/2022	77 Hamilton Rd South Hedland 6722 WA	Classification timeframe extended under s.14(1)(b)		
21/07/2022	Lot 3000 Maida Vale 6057 WA	Remediated for restricted use	24/08/2022	Coal tar stabilised limestone containing polycyclic aromatic hydrocarbons (PAHs) from the former road infrastructure was excavated and buried beneath the upgraded road alignment.
26/07/2022	Lot 13557 Hester 6255 WA	Possibly contaminated - investigation required	24/08/2022	A legacy asbestos-containing material (ACM) water pipe is present which has been damaged during a bushfire event. ACM fragments have been visually identified along the pipeline alignment.
12/08/2022	Barrow Island 6712 WA	Classification timeframe extended under s.14(1)(b)		
22/08/2022	Lot 351 Great Northern Highway, Newman 6753 WA	Report not substantiated	5/10/2022	No contamination has been identified.
22/08/2022	240 Hinkley Rd Jackitup 6335 WA	Possibly contaminated - investigation required	1/11/2022	Asbestos and hydrocarbons are present in soils at the site.
22/08/2022	Lot 630 Mcrae Av Paraburdoo 6754 WA	Possibly contaminated - investigation required	21/09/2022	Per-and poly-fluoroalkyl substances (PFAS) (such as from fire-fighting foams) are present in soil and groundwater beneath the site. Further investigation is required to determine the nature and extent of groundwater impacts, and to inform assessment of potential risks.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
22/08/2022	240 Hinkley Rd Jackitup 6335 WA	Possibly contaminated - investigation required	1/11/2022	Asbestos and hydrocarbons are present in soils at the site.
23/08/2022	193 Western Road, Karlakurla 6430 WA	Report not substantiated	29/09/2022	No known contamination has been identified
25/08/2022	28 Northerly St Vasse 6280 WA	Classification timeframe extended under s.14(1)(b)		
2/09/2022	2 Orton Rd Shenton Park 6008 WA	Report not substantiated	6/10/2022	Pesticides (such as from historical termite treatments) are present in soil at isolated areas near the chapel and the main building at the site.
2/09/2022	84 Tydeman Rd North Fremantle 6159 WA	Classification timeframe extended under s.14(1)(b)		
2/09/2022	Lot 330 Sams Creek Road, Point Samson 6720 WA	Report not substantiated	21/09/2022	No known contamination has been identified.
7/09/2022	Lot 301 Yardie Creek Road, North West Cape 6707 WA	Report not substantiated	29/09/2022	No known contamination has been identified.
12/09/2022	Castlereagh Way, Brabham 6055 WA	Contaminated - restricted use	25/10/2022	Hydrocarbons (such as from transformer oil) remain in the soil beneath the site.
19/09/2022	Lot 55 on DP 163599, Alma 6535 WA	Possibly contaminated - investigation required	27/10/2022	Lead tailings have been visually identified on the southern portion of the site.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
10/10/2022	60 McCabe St Mosman Park 6012 WA	Possibly contaminated - investigation required	17/11/2022	The site historically formed part of a fertiliser manufacturing facility. Remedial works for identified metal and cyanide contamination in soil carried out across the majority of the former industrial facility did not extend to this site. Soil investigations have confirmed the site is suitable for the current use. However, sub-surface soil has not been fully characterised. Further investigation is required to inform assessment of potential risks associated with proposed redevelopment of the site involving significant ground disturbance.
11/10/2022	93 Capel Dr Capel 6271 WA	Possibly contaminated - investigation required	22/11/2022	Visual and olfactory evidence of hydrocarbons (such as from petrol or diesel) have been identified down-gradient of a service station in the Capel River and along the riverbank.
11/10/2022	Lot 256 on Deposited Plan 194926, Capel 6271 WA	Classification timeframe extended under s.14(1)(b)		
11/10/2022	Section of Capel River, Capel 6271 WA	Classification timeframe extended under s.14(1)(b)		
11/10/2022	Capel Drive, Capel 6271 WA	Classification timeframe extended under s.14(1)(b)		
13/10/2022	Lot 110 Marble Bar 6760 WA	Classification timeframe extended under s.14(1)(b)		
21/10/2022	398 Hector St Yokine 6060 WA	Possibly contaminated - investigation required	31/01/2023	Hydrocarbons (such as from petrol, diesel or oil) and metals are present in groundwater beneath the site. Further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.
21/10/2022	398 Hector St Yokine 6060 WA	Possibly contaminated - investigation required	31/01/2023	Hydrocarbons (such as from petrol, diesel or oil) and metals are present in groundwater beneath the site. Further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.
26/10/2022	Bennett Ave North Coogee 6163 WA	Possibly contaminated - investigation required	24/11/2022	Asbestos-containing materials (ACM) in fill material found to be present at an adjacent site to the west likely extends to beneath the site.
31/10/2022	Mining Lease L80/55, Durack 6743 WA	Possibly contaminated - investigation required	8/12/2022	Potentially hydrocarbon-impacted soil remains beneath the foundations of the power station and in the area used to temporarily store equipment to be disposed off-site. No groundwater investigations have been undertaken in the immediate area of the former on-site power station facility.

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
1/11/2022	78 Dora St Broome 6725 WA	Classification timeframe extended under s.14(1)(b)		
4/11/2022	92 Windsor Rd Wangara 6065 WA	Classification timeframe extended under s.14(1)(b)		
7/11/2022	93 Capel Dr Capel 6271 WA	Possibly contaminated - investigation required	22/11/2022	Visual and olfactory evidence of hydrocarbons (such as from petrol or diesel) have been identified down-gradient of a service station in the Capel River and along the riverbank.
15/11/2022	Lot 547 on Plan 13244, Jandakot 6164 WA	Classification timeframe extended under s.14(1)(b)		
17/11/2022	Lot 130 on DP 213482, Pippingarra 6722 WA	Classification timeframe extended under s.14(1)(b)		
23/11/2022	Lot 499 Railway Terrace, Goomalling 6460 WA	Classification timeframe extended under s.14(1)(b)		
23/11/2022	Mining Tenement M45/16, Marble Bar 6760 WA	Possibly contaminated - investigation required	8/12/2022	The site has been used for historical processing of gold, copper, tin, tantalite and asbestos. However, soil and groundwater at the site has not been investigated.
24/11/2022	Lot 47 Steedman Street, Wellstead 6328 WA	Possibly contaminated - investigation required	4/01/2023	Historical municipal landfilling has occurred on this site. However, soil and groundwater quality at the site has not been investigated.
28/11/2022	75 Whitemoss Dr Vasse 6280 WA	Classification timeframe extended under s.14(1)(b)		

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
30/11/2022	286 Stirling Cr Hazelmere 6055 WA	Possibly contaminated - investigation required	5/01/2023	Hydrocarbons (such as from petrol and diesel) are present in soil and groundwater. Further investigations are required to determine lateral extent of the contamination.
1/12/2022	74 Hardey Rd Belmont 6104 WA	Possibly contaminated - investigation required	4/01/2023	Per-and poly-fluoroalkyl substances (PFAS) (such as from fire-fighting foams/PFAS-containing waste) are present in groundwater beneath the site. Further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.
2/12/2022	7 Stanley Rd Leschenault 6233 WA	Possibly contaminated - investigation required	11/01/2023	Groundwater beneath this site has been impacted by putrescible landfill leachate. Groundwater impacts are characterised by elevated concentrations of per- and poly-fluoroalkyl substances (PFAS).
5/12/2022	Mining Lease 270SA, Juna Downs 6751 WA	Classification timeframe extended under s.14(1)(b)		
8/12/2022	55 Barrett St Herne Hill 6056 WA	Report not substantiated	24/01/2023	No evidence of contamination has been identified.
13/12/2022	26 Jade St Maddington 6109 WA	Possibly contaminated - investigation required	10/01/2023	Hydrocarbons (such as greases) were visually identified on hard stand surfaces and open ground where heavy equipment was serviced.
13/12/2022	19 Eva St Maddington 6109 WA	Possibly contaminated - investigation required	10/01/2023	Hydrocarbons (such as greases) were visually identified on hard stand surfaces and open ground where heavy equipment was serviced.
13/12/2022	398 Hector St Yokine 6060 WA	Possibly contaminated - investigation required	31/01/2023	Hydrocarbons (such as from petrol, diesel or oil) and metals are present in groundwater beneath the site. Further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.
13/12/2022	38 C Ellen Stirling Bvd Innaloo 6018 WA	Classification timeframe extended under s.14(1)(b)		

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
13/12/2022	18 Ellen Stirling Bvd Innaloo 6018 WA	Classification timeframe extended under s.14(1)(b)		
14/12/2022	308 Landsdale Rd Landsdale 6065 WA	Classification timeframe extended under s.14(1)(b)		
14/12/2022	58 Hardey Rd Belmont 6104 WA	Possibly contaminated - investigation required	17/01/2023	Per-and poly-fluoroalkyl substances (PFAS) (such as from fire-fighting foams) are present in groundwater beneath the site. Further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.
14/12/2022	97 Guthrie St Osborne Park 6017 WA	Possibly contaminated - investigation required	24/01/2023	Per-and poly-fluoroalkyl substances (PFAS) (such as from fire-fighting foams/PFAS-containing waste) are present in groundwater beneath the site. Further investigation is required to determine the nature and extent of impacts, and to inform assessment of potential risks.
14/12/2022	Lot 115 On Plan 69110 Leda 6170 WA	Possibly contaminated - investigation required	26/04/2018	Sulfate, ammonia/ammonium, chloride, nitrate, arsenic, copper and manganese are present in groundwater beneath this site.
14/12/2022	287 Kerosene Lane Baldivis 6171 WA	Remediated for restricted use	26/11/2020	A decommissioned tailings storage facility is present on this site. It contains sulphide, iron, nickel, cobalt, copper and trace metals, beneath a low-permeability cover and a sand capping layer. Nickel and copper are present in surface soils to the north and south of the tailings storage facility. Groundwater beneath this site is contaminated by a dense plume of ammonium sulfate, which extends off-site to the north, south and west. Ammonia, sulfate, nitrate and metals (arsenic, boron, cobalt, copper, iron and zinc) are present in groundwater.
15/12/2022	413 Karnup Rd Hopeland 6125 WA	Possibly contaminated - investigation required	23/01/2023	Elevated concentrations of metals and hydrocarbons (such as from petrol, diesel or oil) have been detected in surface soils, groundwater and surface water in isolated locations on the site.
22/12/2022	Lot 10237 On Plan 206721 Eneabba 6518	Contaminated - restricted use	17/01/2023	Hydrocarbons (such as from petrol or diesel or oil) are present in soils beneath the site.
23/12/2022	State Forrest 22, Keysbrook 6126 WA	Classification timeframe extended under s.14(1)(b)		
23/12/2022	57 Elgee Rd Bellevue 6056 WA	Classification timeframe extended under s.14(1)(b)		

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
23/12/2022	91 Elgee Rd Bellevue 6056 WA	Classification timeframe extended under s.14(1)(b)		
23/12/2022	Railway Reserve Bellevue 6056 WA	Classification timeframe extended under s.14(1)(b)		
6/01/2023	The Esplanade Esperance 6450 WA	Classification timeframe extended under s.14(1)(b)		
11/01/2023	63 Cathedral Av Geraldton 6530 WA	Possibly contaminated - investigation required	7/02/2023	Hydrocarbons (such as from petrol, diesel or oil), metals and cyanide are present in groundwater beneath the eastern portion of the site. Tar or bituminous material has been encountered during ground disturbance works in the south-eastern portion of the site.
13/01/2023	Mining Lease AM70/265, M365SA, Rocklea 6751 WA	Classification timeframe extended under s.14(1)(b)		
13/01/2023	Mining Lease AML70/00004 Section ML4SA 236 and 237, Rocklea 6751 WA	Classification timeframe extended under s.14(1)(b)		
16/01/2023	92 Blair St Bunbury 6230 WA	Report not substantiated	7/02/2023	No known contamination has been identified.
18/01/2023	Reserve 48553, Lot 8004, East Rockingham 6168 WA	Possibly contaminated - investigation required	3/03/2023	Ammonia is present in groundwater beneath the adjacent Kwinana Nickel Refinery at 270 Patterson Road, Kwinana Beach and extends west beneath this site. Asbestos is present in soil across the site.
23/01/2023	section of Lot 15445, Crown Reserve 47831, Hillarys 6025 WA	Classification timeframe extended under s.14(1)(b)		

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
25/01/2023	21 Sheppard Way Marmion 6020 WA	Possibly contaminated - investigation required	9/03/2023	Chlorinated hydrocarbons (such as from dry cleaning solvents) are present in groundwater beneath the site and extend off-site to the west/south-west.
1/02/2023	1206 Chester Pass Rd Kalgan 6330 WA	Possibly contaminated - investigation required	3/03/2023	The site has been used as a landfill for disposal of degradable wastes. Metals and nutrients are present in groundwater beneath the site, however, groundwater has not been fully investigated.
14/02/2023	Lot 175 Dampier Rd Gap Ridge 6714 WA	Contaminated - remediation required	12/04/2021	Petroleum hydrocarbons (such as from diesel or oil) are present in the soil at multiple locations across a large portion of the site. Groundwater at the site is impacted by both dissolved phase hydrocarbons and light non-aqueous phase liquid (LNAPL), such as pure hydrocarbon floating on the surface of groundwater. These impacts are present in groundwater in multiple areas across the site. Chlorinated hydrocarbons (such as from chlorinated solvents) and Perfluoroalkyl and Polyfluoroalkyl Substances (PFAS) are also present in groundwater beneath the site in multiple areas.
22/02/2023	35 Craiggie St Laverton 6440 WA	Classification timeframe extended under s.14(1)(b)		
23/02/2023	2 Mcmanus St Wilson 6107 WA	Decontaminated	6/04/2021	Following remediation, no contamination remains at the site.
24/02/2023	219 Kelvin Rd Orange Grove 6109 WA	Awaiting Classification		
27/02/2023	19 Sheppard Way Marmion 6020 WA	Possibly contaminated - investigation required	9/03/2023	Chlorinated hydrocarbons (such as from dry cleaning solvents) are present in groundwater beneath the adjacent dry cleaners and extend beneath the eastern portion of this site.
3/03/2023	Unallocated Crown Land (PIN 951197), Salmon Gums 6445 WA	Awaiting Classification		

DATE REPORT RECEIVED	STREET ADDRESS	CURRENT CLASSIFICATION	DATE OF CLASSIFICATION	NATURE AND EXTENT OF CONTAMINATION
7/03/2023	16 The Avenue Picton 6229 WA	Possibly contaminated - investigation required	13/04/2022	Hydrocarbon (such as from petrol or diesel) are present in soils and groundwater beneath the location of former underground storage tanks in the south of the site.
10/03/2023	2 Padbury St Moora 6510 WA	Classification timeframe extended under s.14(1)(b)		
10/03/2023	45 Drummond St Moora 6510 WA	Possibly contaminated - investigation required	15/12/2009	The groundwater beneath the Site is impacted by hydrocarbons; further investigation to determine the nature and extent of the contamination is required. The dissolved phase plume is migrating offsite in a generally westwards direction.
15/03/2023	Mining Tenement M47/254 Mount Anketall 6714 WA	Awaiting Classification		
15/03/2023	189 Seven Hills Rd Roelands 6226 WA	Awaiting Classification		