

Table 1 - Number of interruptions by cause for Mundaring

	Animal	Bird	Customer Installation or Appliance	Emergency Outage For Hazard	Equipment Failure (Includes Pole Top Fire)	Fire (Not Pole Top Fire)	Generation Failure	Human Error	Lightning	Machine or Tool	Plan Outage or Disconnection	PQI - Default Code	Unknown	Vandalism or Willful Damage	Vegetation	Vehicle	Wind or Wind Bourne Debris
2011	2	1	6	5	22	0	3	1	1	0	18	0	14	1	4	1	8
2010	1	6	3	11	20	1	0	1	0	4	52	1	19	2	4	3	4
2009	2	3	2	0	13	0	0	1	4	0	27	0	7	0	5	0	5

Note to Table 1: Typically an interruption to supply affects only a small proportion of the Mundaring customers.

Table 2 - Number of interruptions by cause for Parkerville

	Animal	Bird	Customer Installation or Appliance	Emergency Outage For Hazard	Equipment Failure (Includes Pole Top Fire)	Fire (Not Pole Top Fire)	Generation Failure	Human Error	Lightning	Machine or Tool	Plan Outage or Disconnection	PQI - Default Code	Unknown	Vandalism or Willful Damage	Vegetation	Vehicle	Wind or Wind Bourne Debris
2011	1	0	5	6	17	1	2	1	1	0	42	0	13	0	4	2	3
2010	0	3	6	5	19	1	0	4	1	2	65	0	21	1	4	1	2
2009	2	2	2	4	20	0	0	1	4	0	29	2	12	1	9	0	5

Notes to Table 2: Typically an interruption of supply affects a small proportion of the Parkerville customers.