Department of Training and Workforce Development

Hon Donna Faragher MLC asked:

1) When was the last Building Condition Assessment (BCA) process undertaken across all TAFE Colleges?

Answer: The BCA process for TAFE colleges is completed every two years and was last undertaken in 2017.

10 OCT 0017

Department of Training and Workforce Development

Hon Donna Faragher MLC asked:

2) Please provide a list of all identified maintenance (by TAFE College) from the latest Building Condition Assessment undertaken?

Answer: Attached is the maintenance identified through TAFE colleges BCAs (Appendix A).

1 0 OCT 2017

NORTH REGIONAL TAFE BCA REQUIRED MAINTENANCE 2017 - 2026 MAINTENANCE AND UPGRADES (valued at more \$20,000)

Categories	Campus	Project Description
	Fitzroy	Replacement of +10yr old Air-Con Splits and redundant Air Handling Unit's
	Broome Broome	Replacement of +10yr old Air-Con Splits and redundant Air Handling Unit's
	Aquaculture	Replacement of +10yr old Air-Con Splits and redundant Air Handling Unit's
1	Halis Creek	Replacement of +10yr old Air-Con Splits and redundant Air Handling Unit's
Replace Obsolete Air-con	Kununurra Wyndham	Replacement of +10yr old Air-Con Splits and redundant Air Handling Unit's Replacement of +10yr old Air-Con Splits and redundant Air Handling Unit's
Equipment	Derby	Replacement of +10yr old Air-Con Splits and redundant Air Handling Unit's
	Balu Baru	Replacement of +10yr old Air-Con Splits and redundant Air Handling Unit's
	Karratha	Replacement of +10yr old Air-Con Splits and redundant Air Handling Unit's
ļ	Minurmarghali Mia Pundulmurra	Replacement of +10yr old Air-Con Splits and redundant Air Handling Unit's Replacement of +10yr old Air-Con Splits and redundant Air Handling Unit's
	Newman	Replacement of +10yr old Air-Con Splits and redundant Air Handling Unit's
	Tom Price	Replacement of +10yr old Air-Con Splits and redundant Air Handling Unit's
	Fitzroy	
	Broome Broome	Replacement of older part of fire ring main
	Aquaculture	Replace water chillers (4) to hatchery sheds and replacement of emergency power generators
	Halls Creek	Plant and Services
Landing the state of the state	Kununurra	Plant and Services
Replace Major Mechanical Plant & Campus Services	Wyndham	
Planti& Campus Services	Derby Balu Baru	
	Karratha	Plant upgrades + replacement fixed plant
	Minurmarghali Mia	Plant upgrades entrance car park resurface water isolation valves fire services upgrade
	Pundulmurra Neuman	Plant and Services Plant and services fire an water main valve upgrade asphalt resurface
La Companya da La Com	Newman Tom Price	valve replacement, fire services and asphalt resurface
processing the process of the second	Fitzroy	Upgrade security system
i	Broome	Upgrade security system, led lamp replacement
	Broome	
	Aquaculture Halls Creek	lupgrade security system, replace suspended lighting system to hatchery lupgrade security system
	Kununurra	upgrade security system, lighting upgrade
Electrical Equipment - Security	Wyndham	upgrade security system
and Safety Works	Derby Boly Bory	upgrade security system, lighting upgrade
1	Balu Baru	upgrade security system
	Karratha	Upgrade electrical switch boards and services security expansion security and road lighting upgrade
•	Minurmarghali Mia	Upgrade it cabling, upg electrical switch boards and services security upgrade
	Pundulmurra Newman	Upgrade electrical switch boards and services/lighting Upgrade electrical switch boards upgrade security system street lighting
*	Tom Price	Upgrade it cabling, upg electrical switch boards and services security upgrade security lighting
	Fitzroy	
	Broome	
	Broome Aquaculture ·	Re-roof hatchery sheds, replace link mesh infill panels and blockwork walls
	Halls Creek	1/2-1001 Hatchery streets, replace link friesh hillin pariets and blockwork waits
Structural Remediation (Roof	Kununurra	Re-roof trades area Carpentry, Joinery and metals
restoration, demolition, gutters	Wyndham	reclad roof and walls to trades area
(etc)	Derby Balu Baru	Clarendon St re-roof and design
工业总统建设的 是有关系。	Karratha	re-roof original buildings/ and underpin where required
Farrier State 1775	Minurmarghali Mia	re-roof transportables
	Pundulmurra	Re-roof to original buildings Repair structural supports to verandahs
APPENDING STATE OF ST	Newman Tom Price	Reroof Reroof
17.7000000 PROPERTY AND THE STREET, THE STREET, STREET,	Fitzroy	[TANDON
	Broome	Electronic doors in lecturer office (major foot traffic access)
	Broome	
	Aquaculture	
	Halis Creek	Phase out of Asbestos in buildings (where possible), Improvement of Universal Access requirements
	Kununurra	Control of the contro
	Wyndham	
	•	Phase out of Asbestos in buildings (where possible), Improvement of Universal Access requirements
Compliance - Asbestos, OSH,	Derby	Phase out of Asbestos in buildings (where possible), Improvement of Universal Access requirements
Universal Access	Balu Baru	
10000000000000000000000000000000000000	Karratha	Dhana aut of Ashantas is huildings (where wessible). Improvement of the constant Assault Assault
		Phase out of Asbestos in buildings (where possible), Improvement of Universal Access requirements
	Minurmarghali Mia	Phase out of Asbestos in buildings (where possible), Improvement of Universal Access requirements
	Pundulmurra	
		Phase out of Asbestos in buildings (where possible), Improvement of Universal Access requirements
	Newman	Phase out of Asbestos in buildings (where possible), Improvement of Universal Access requirements
	Tom Price	Phase out of Asbestos in buildings (where possible), improvement of Universal Access requirements

CENTRAL REGIONAL TAFE BCA REQUIRED MAINTENANCE 2017 - 2026 MAINTENANCE AND UPGRADES (valued at more \$20,000)

Categories	Campus	Project Description
Replace Obsolete Air-con	Geraldton	Replace various air-con systems
Equipment	BCMI	Repairs to existing sea water heat exchange unit - pumps and titanium plates
Equipment	Саглагуоп	Replace split system units
	Tech Park	Replace Variable Refrigerate Volume units
	Kalgoorlie	Replace various air-con systems
	Northam	Replace various air-con systems
	Moora	Replace various air-con systems
	Merredin	Replace various air-con systems
	Geraldton	Repair/replace extraction systems - kitchens, art, engineering, construction
	Geraldton	Repair/replace Pumps - Bores, Ponds, Sewer
日光表於學門的記述上於 30.15%	BCMI	Repair/replace pumps - Air-Con, Circulation, Beach Well, Discharge, Pigging, Sewer
Replace Major Mechanical	Carnarvon	Repair/Replace Lift
Plant & Campus Services	Carnarvon	Repair/Replace extraction units
TOTAL OF THE STATE	Tech Park	Repair/Replace extraction units
化学等等的现在 自己不适	Kalgoorlie	Repair/Replace extraction units
	Kalgoorlie	Repair/Replace extraction units
t i kawa i waka ili ama ili ili ka	Northam	Repair/Replace extraction units
•	Geraldton	Switchboard and RCD Upgrades
	Geraldton	Fire Detection - extend into older areas of the campus
Electrical Equipment - Security		Upgrade security system - key pads, Motton Sensor, Software, Challenger Units
and Safety Works	Geraldton	Replace Hot Water Units and Urns
	Geraldton	Replace External Security Ground Lighting
	Carnarvon	Maintain fire and security systems
	Tech Park	Maintain fire and security systems
	Kalgoorlie	Upgrade security system - key pads, Motion Sensor, Software, Cameras
	Northam	Fire Detection - no cover currently
	Moora	Fire Detection - no cover currently
	Merredin	Fire Detection - no cover currently
	Geraldton	Gutter/Downpipe Replacement
Structural Remediation (Roof	Geraldton	Rust Mitigation and Treatment
restoration demolition, gutters	Geraldton	Replace Roofs from Tile to Colorbond
	Geraldton	Repair Colorbond Roofs
THE PARTY OF THE P	BCMI	Repaint external paintwork on bargeboards, eaves etc.
(etc)	Carnarvon	Replace roof sheets and gutters
. 出来的"温格克勒西斯克姆克里特"是"巴克"的	Kalgoorlie	Repair Colorbond Roofs
	Northam	Repair Colorbond Roofs
1. 大学的特别的特别的特别的特别的 1. 强力性的人	Moora	Gutter/Downpipe Replacement
17 (20)	Merredin	Gutter/Downpipe Replacement
THE CONTRACTOR OF THE STATE OF	Geraldton	Repair/Replace automatic sliding doors
	Geraldton	Replace aging vinyl in B Block (possible asbestos)
Compliance: Asbestos OH&S:	Geraldton	Repair/Replace Emergency Lighting
Universal Access	Geraldton	Replace aging hose reels and hydrants
Universal Access	Geraldton	Electrical Pit Replacement (asbestos)
。	Carnarvon	Repair/Replace automatic sliding doors
	Tech Park	Repair/Replace automatic sliding doors
[1] [1] [1] [1] [1] [1] [1] [1] [1] [1]	Kalgoorlie	Repair/Replace automatic sliding doors
15年2月1日 11年2月1日 11年2月1日 11日 11日 11日 11日 11日 11日 11日 11日 11日	Kalgoorlie	Replace aging hose reels and hydrants
BANG SANTAN AND SHEMBERS AND THE STATE OF THE SANTAN AND AND AND AND AND AND AND AND AND A	Kalgoorlie	Repair/Replace Emergency Lighting
	Northam	Asbestos Site Wide
한 바다를 잃었다. 그는 말이 뭐	Moora	Repair/Replace automatic sliding doors

SOUTH REGIONAL TAFE BCA REQUIRED MAINTENANCE 2017- 2026 MAINTENANCE AND UPGRADES (valued at more \$20,000)

Categories	Campus	Project Description
	Albany	Up-grade and replace a/c systems campus wide
	Bunbury	A Block - Cassette/Split Systems - there is a mixture of new and old systems Replace B Block - B1 Package Unit, B24 Package Unit Current systems are 30 + years old and no
	Bunbury	Incore function efficiently. Yearly maintenance cost are escalating.
		C Block Ground and Upper Floor Package Units. Current systems are 30 + years old and no longer
	Випригу	function efficiently. Yearly maintenance cost are escalating.
	Bunbury	D Block Canteen Evaporative System Current systems are 30 + years old and no longer function
		efficiently. Yearly maintenance cost are escalating. E Block Evaporative System Current systems are 30 + years old and no longer function
	Bunbury	lefficiently. Yearly maintenance cost are escalating.
	Bunbury	F Block Cassette System will have reached their life expectancy
	Bunbury	H Block Cassette System will have reached their life expectancy
	Bunbury	J Block Split Systems
Replace Obsolete Air Conditioning	Bunbury Bunbury	M Block Split Systems N Block Package/Casette Systems
Equipment	Bunbury	Q Block Split Systems
-	Bunbury	S Block Cassette/Split System
	Bunbury	Library Evaporative System System Current systems are 30 + years old and no longer function
		efficiently. Yearly maintenance cost are escalating.
	Bunbury Busselton	Nagala Maya Cassette System Replacement A Block Split Systems
		B Block Evaporative System and heating gas units is 20 + years old and no longer function
	Collie	efficiently.Yearly maintenance cost are escalating.
	Collie	install reverse cycle units to G1.1 and G1.4
	Harvey	System upgrade no longer function efficiently. Yearly maintenance cost are escalating.
	Margaret River Margaret River	C Block Cassette/Split System S Block Cassette/Split System
	Margaret River	W Block Cassette/Split System
		B BlockCassette/Split System is 15 + years old and no longer function efficiently. Yearly
	Manjimup	maintenance cost are escalating replacement parts no longer available.
	Albany	Up-grade sewerage pumps and water supply tank
	Albany	Upgrade Workshop Distribution Board
	Albany	Upgrade existing irrigation system Upgrade fire services water supply to South side of the campus
	Albany Albany	New extraction and filtration system required in trades workshop
	Albany	Replace hot water units
	Bunbury	Replace Extraction/exhaust system to the Light Automotive Rolling Road
Replace Major Mechanical Plant &	Bunbury	C Block Extraction System Labs
Campus Services	Bunbury	L Block Extraction System Beauty Therapy. installed N Block Cyclone/Dust Extraction System. The system no longer provides sufficient extraction of sav
•	Bunbury	dust and can not be expanded to supply extraction for other machine requirements
	Bunbury	L Block Compressor/Airline replaced
	Bunbury	K Block Freezer/Cool Room replaced
	Bunbury	C Block Labs liquid gas lines replaced. The Qxygen line are leaking, There is a risk of explosion
	Випригу	Installation of a Bore Water Filtration System. Bore water contains iron causing unsightly water staining to build walls and windows and deteriation of irrigation system
	Bunbury	Institute PABX Phone system has reached end of life no longer supported by NEC
	Albany	Up-grade existing security camera system
	Albany	Replace lighting to walkway, D Block and café with LED's
	Albany	Upgrade lighting in C Block with solar tubes
	Albany	Upgrade electrical mains Distribution Board & sub main 1&2
	Albany	Upgrade lighting in B Block with solar tubes Upgrade electrical services to A,B,C,D,E,F,K,L Blocks
	Bunbury All South West	
	Campuses	Upgrade existing security camera system
	All South West	Upgrade existing security (Titan) System
	Campuses	
	Collie	Upgrade A, B, C Block & Workshops Distribution Boards
Electrical Equipment - Security and Safety Works	Collie Collie	Upgrade existing security camera system P.A. system to be installed
Salety Works	Katanning	Expand and upgrade security camera system through out campus
	Margaret River	Replace Lighting mounted in concete paths and lawn areas
	Margaret River	Electrical motor storage room not working properly, loses memory after power outage. End of life
		cycle, need to be replaced
	Margaret River	Several security night light fittings need to be replaced as they can't be repaired Replace lamp posts in car parks with LED (keep failing and replacement is expensive)
	Margaret River	Replace lamp posts in car parks with LED (keep railing and replacement is expensive) Lights next to stairs from carpark to winery building were removed because they were shorting out,
	Margaret River	new ones need to be installed
	Margaret River	Emergency exit lights need to be replaced with LED as they keep failing
		Upgrade security system as being terminated from Kalgoorlie
	Esperance	
	Margaret River	Replace S Block Electricial Cabinet
	Margaret River Albany	Toilet refurbishment to D & EF Blocks
	Margaret River Albany Albany	Toilet refurbishment to D & EF Blocks A Block refurbishment to Gym, classroom and changerooms
	Margaret River Albany Albany Albany	Toilet refurbishment to D & EF Blocks A Block refurbishment to Gym, classroom and changerooms Raise main walkway roof and extend L Block entrance roof
	Margaret River Albany Albany Albany Albany	Toilet refurbishment to D & EF Blocks A Block refurbishment to Gym, classroom and changerooms
	Margaret River Albany Albany Albany	Toilet refurbishment to D & EF Blocks A Block refurbishment to Gym, classroom and changerooms Raise main walkway roof and extend L Block entrance roof Replace floor coverings

NORTH METROPOLITAN TAFE BCA REQUIRED MAINTENANCE

2017 - 2016 MAINTENANCE AND UPGRADES (valued at more \$20,000)

Maintence Categories	Campus	Project Description		
	12 Aberdeen street	Replace 7 split air con units due to R22 regrigerent		
	12 Aberdeen street	Replace 2 Variate Refridgerate Volume systems		
1	12 Aberdeen street	Replace 5 split air con units		
	19 Aberdeen Street	Replace Air Handling Unit x 2		
	133 Newcastle Street	Chiller replacement		
	25 Aberdeen Street	Air Handling Uunit replacement x 10		
	25 Aberdeen Street	Replace existing air con within server room to current code		
	25 Aberdeen Street	Replace child care centre air con units		
	East Perth	Air Handling Unit replacement x 10		
		Replace chiller and cooling towers due to obsolete R22 refrigerent and parts,		
	East Perth	Variable Air Volume boxes and Building Management System		
	Leederville Campus	Replace frigipole packaged units B Block		
	Leederville Campus	Air Handling Unit replacement x 5		
place Obsolete Air-con		Replace split airconditioner units A block north courtyard		
•	Leederville Campus	Air conditioning replacement chiller A Block		
juipment	Midland			
	Midland	Air conditioning replacement air con split systems/evap		
	Midland	Air conditioning R22 replacement		
•	Midland	Replace Air Handling Unit x 5		
	Balga	Air-Con Package unit replacment		
	Balga	R22 replacement		
	Balga	Split system replacement .		
	Kendrew	C Block Chiller		
	Kendrew	D block chiller supplementary water tank required		
	Kendrew	Evap Systems in E Block		
	Kendrew	Building Manament System and timers replaced		
	Kendrew	Replace Evap Systems in D Block		
	McLarty	Replace Simulator Hospital Heating, Ventilation and Cooling system		
	McLarty	Replace all other Air-Con systems all buildings		
	12 Aberdeen street	Overhaul lift (built 1999)		
	12 Aberdeen street	Replace roof top Air-Con systems and Building Management System		
	133 Newcastle st	Overhaul Lift		
	133 Newcastle st	Replace Air conditioner units plant room		
	133 Newcastle Street	Replace evap cooler		
	19 Aberdeen street	Replace chiller unit, cooling tower		
	19 Aberdeen street	Water and air balancing to air conditioning systems		
	19 Aberdeen Street	Replace 7 split air con units		
	25 Aberdeen st	Overhaul lifts 3 and 4 (installed 1984)		
	25 Aberdeen st	Air Balancing all levels		
		Replace cooling towers level 5 plant area		
	25 Aberdeen st			
•	30 Aberdeen St	Lift replacement		
	East Perth	Overhaul lift A block (1992)		
	East Perth	Overhaul lift B block (1994)		
place Major Mechanical	East Perth	Replace fume cupboards to Laboratory area (11 off)		
ant & Campus Services	Leederville Campus	Refurbish Lift and controls		
	Leederville Campus	Replace boiler for air conditioner		
	Midland	Fire Services, upgrade emergency lighting		
	Midland	Fire Services, replace fire panel extend Electrical Wiring Interconnect System		
	Balga	Fire Services upgrade emergency lighting		
	Balga	Dust extraction		
	Kendrew	Replace 4 Fire Panels & Electrical Wiring Interconnect System		
	McLarty	Fire Panels & Electrical Wiring Interconnect System		
	McLarty	Replace fire doors		
	Kendrew	Fire Protection tanks & pumps		
	Kendrew	Replace Lift C Block		
	Kendrew	Replace Lift D Block		
	kendrew	Freezers/chillers E Block		
	Clarkson	Water recycling		
	Clarkson	Dust Extraction		
	Clarkson	Air Compressors		
	12 Aberdeen street	Replace fire control panel		
÷		Replace security system		
	12 Aberdeen street			
	12 Aberdeen Street	Lighting upgrade		
	25 Aberdeen street	Replace building management system also service 19 Aberdeen St		
•	0.5.11			
	25 Aberdeen street	Replace Electrical Wiring Interconnect System for fire evacuation		
	25 Aberdeen street	Replace Uninterupted Power Supply inverter to IT area		
	25 Aberdeen street 25 Aberdeen street	Replace Uninterupted Power Supply inverter to IT area Restoration of existing door access system		
	25 Aberdeen street	Replace Uninterupted Power Supply inverter to IT area		

The second secon		
Maintence Categories	Campus	Project Description
manacios subgenes	Jampao	
GLO)	Leederville Campus	Replacement roof tiles to A block
	Leederville Campus	Repairs to F Block roof
	Leederville Campus	Replace roof to G block
	Leederville Campus	Continued replacement of eaves and guttering A block
	Leederville Campus	Replace clay pipe sewer system south elevation east C block)
	Leederville Campus	Replace guttering to B and C block/repaint facias & eaves
	Leederville Campus	Repair and repaint windows to blocks B and C
	Leederville Campus	Replace carpet and vynil flooring all areas
	Leederville Campus	Repairs to landscaping retaining walls
	Leederville Campus	Internal repairs and painting various areas
	Leederville Campus	Repair and repaint external walls courtyard area
	Leederville Campus	Replace earthenware soil pipes (South/East elevation)
	Mt Lawley	Remove asbestos demountables
	Mt Lawley	Refurbish Optics building internal and external
	Mt Lawley	Refurbishment of student seating cafeteria area
	Mt Lawley	Internal painting and repair Levels 1,2,
	Mt Lawley	External repairs and paint to windows and doors to various areas
【阿萨维 医自动性 医皮肤性	Mt Lawley	Replace carpet to Library and various classrooms
	Mt Lawley	Replace steel windows to south block
	Balga	Roofs
	Midland	Roofs
	Midland	Toilet refurbishment
	Midland	Paint
	Midland	Recarpet
	Balga	Building Fabric - replace and paint cladding and sunscreens
	Balga	Toilet refurbishment
	Balga	Paint
	Balga	Recarpet
	Midland	Building Fabric, gutters, sindows and external painting
	Kendrew	Gutters replaced
	Kendrew	Walkway Covers
	Kendrew	Roof access system
	Kendrew	Paint
	Kendrew	Recarpet
	McLarty McLarty	Roof access system Paint
	McLarty	Recarpet
	Kendrew	Window seals all Campus
	McLarty	Replace toilet cisterns and other plumbing
	Kendrew	Replace toilet cisterns all Campus
	Clarkson	Roof repairs
	Clarkson	Roller shutter door replacement
and the second section of the	19 Aberdeen street	Refurbish toilets for universal access
	19 Aberdeen street	Additional handrail to exit stairways all levels
	19 Aberdeen street	Install CCTV cameras for security
. ,	25 Aberdeen st	Additional handrail to exit stairways all levels
	25 Aberdeen st	Install additional CCTV cameras for security
·	25 Aberdeen st	Replace delapidated asbestos fire doors
	25 Aberdeen Street	Remove asbestos East Block plant room
,	25 Aberdeen Street	Museum Street entrance paving
	Leederville Campus	Replace stairs to B block west. Non compliant
Compliance - Asbestos OSH,	Leederville Campus	Auto Doors for disable access various areas
universal access	Leederville Campus	Install additional lift for disable access north elevation
miliaeladi drocaa	Leederville Campus	Additional handrail to exit stairways all levels
	Balga	Asbestos removal and replacement service pits, fascias, eaves and cladding
	Balga	Universal access to include ramps and handrails
•	Balga	Replacement Emergency Stop switches
	Midland	re-lay paved walkways to resolve trip hazards
	Kendrew	Replace factile tiles
	Kendrew	Auto Doors replacement
	McLarty	Auto Doors replacement
	McLarty	Upgrades to Canteen kitchen
	Kendrew	Relaying of brick paving walkways

SOUTH METROPOLITAN TAFE BCA REQUIRED MAINTENANCE

2017- 2026 MAINTENANCE AND UPGRADES (valued at more than \$20,00

Categories	Campus	Project Description		
	Beaconsfield	Air conditioning		
	Maritime	Air conditioning		
	E-Tech	Air conditioning		
	Peel	Air conditioning		
	Rockingham	Air conditioning		
	Murdoch	Air conditioning		
Replace Obsolete Air-	Munster - ACEPT	Air conditioning		
con Equipment	Henderson	Air conditioning		
	Kwinana Auto	Air conditioning		
	Bentley	Air conditioning		
	Carlisle	Air conditioning		
	Thornlie	Air conditioning		
	Armadale	Air conditioning		
	Jandakot	Air conditioning		
	Beaconsfield	Hydraulics & Fire Services & Other		
	Maritime	Hydraulics & Fire Services & Other		
	E-Tech	Hydraulics & Fire Services & Other		
	Peel	Hydraulics & Fire Services & Other		
	Rockingham	Hydraulics & Fire Services & Other		
Replace Major	Murdoch	Hydraulics & Fire Services & Other		
Mechanical Plant &	Munster - ACEPT	Hydraulics & Fire Services & Other		
Campus Services	Kwinana Auto	Hydraulics & Fire Services & Other		
campas services	Henderson	Hydraulics & Fire Services & Other		
	Bentley	Hydraulics & Fire Services & Other		
	Carlisie	Hydraulics & Fire Services & Other		
	Thornlie	Hydraulics & Fire Services & Other		
	Jandakot	Hydraulics & Fire Services & Other		
	Armadale	Hydraulics & Fire Services & Other		
	Beaconsfield	Power, Security & Electrical Safety Upgrades		
	E-Tech	Power, Security & Electrical Safety Upgrades		
	Maritime Peel	Power, Security & Electrical Safety Upgrades		
		Power, Security & Electrical Safety Upgrades		
Electrical Equipment -	Rockingham Murdoch	Power, Security & Electrical Safety Upgrades		
Security and Safety	Kwinana	Power, Security & Electrical Safety Upgrades		
Works		Power, Security & Electrical Safety Upgrades Power, Security & Electrical Safety Upgrades		
AAOLK2	Henderson Bentley	Power, Security & Electrical Safety Opgrades Power, Security & Electrical Safety Upgrades		
	Carlisle			
	Thornlie	Power, Security & Electrical Safety Upgrades		
	Armadale	Power, Security & Electrical Safety Upgrades Power, Security & Electrical Safety Upgrades		
	Jandakot	Power, Security & Electrical Safety Opgrades Power, Security & Electrical Safety Upgrades		
	Beaconsfield	Roofs		
	Maritime	Roofs		
	E-Tech	Roofs		
医抗偏性 医水乳 南菜	Peel	Roofs		
	Rockingham	Roofs		
	Murdoch	Roofs		
	Munster - ACEPT	Roofs		
	Henderson	Roofs		
	Kwinana Auto	Roofs		
	Bentley	Roofs		
	Carlisle	Roofs		
	Thornlie	Roofs		
	Armadale	Roofs		
structural Remediation	Jandakot	Roofs		
Roof restoration,		Building Fabrication		
larana (1881) and a second in each	Manufacture -			
iemonuon, gutters etc)	ewariime			
demolition, gutters etc)		Building Fabrication		
iemoniton, guiters etc)	E-Tech Peel	Building Fabrication Building Fabrication		

Categories	Campus	Project Description
	Murdoch	Building Fabrication
	Munster - ACEPT	Building Fabrication
	Henderson	Building Fabrication
	Kwinana Auto	Building Fabrication
	Bentley	Building Fabrication
	Carlisle	Building Fabrication
	Thornlie	Building Fabrication
	Armadale	Building Fabrication
a. <u>Laste de la calendar en la calendar de la calendar</u>	Jandakot	Building Fabrication
	Beaconsfield	OHS & Code Compliance
	Maritime	OHS & Code Compliance
	E-Tech	OHS & Code Compliance
	Peel	OHS & Code Compliance
	Rockingham	OHS & Code Compliance
	Murdoch	OHS & Code Compliance
	Munster - ACEPT	OHS & Code Compliance
	Kwinana Auto	OHS & Code Compliance
	Henderson	OHS & Code Compliance
	Bentley	OHS & Code Compliance
	Carlisle	OHS & Code Compliance
「Company of the Company of the C	Thornlie	OHS & Code Compliance
Compliance -	Armadale	OHS & Code Compliance
Asbestos, OSH,	Jandakot	OHS & Code Compliance
Universal Access	Beaconsfield	Preventive maintenance
Offiversal Access	Maritime	Preventive maintenance
	E-Tech	Preventive maintenance
	Peel	Preventive maintenance
	Rockingham	Preventive maintenance
	Murdoch	Preventive maintenance
	Munster - ACEPT	Preventive maintenance
	Kwinana Auto	Preventive maintenance
	Henderson	Preventive maintenance
	Bentley	Preventive maintenance
	Carlisle	Preventive maintenance
	Thornlie	Preventive maintenance
	Armadale	Preventive maintenance
landa a <u>johanna a sana a naga</u> an an arang	Jandakot	Preventive maintenance

Department of Training and Workforce Development

Hon Donna Faragher MLC asked:

3) Please provide a list of the total maintenance expenditure (by TAFE College) since the latest Building Condition Assessment was undertaken?

Answer: The table below summarises the maintenance expenditure in 2016-17 as identified in the most recent BCA process for TAFE Colleges.

COLLEGE	TOTAL COST \$'000 (excluding GST)
Central Regional TAFE	\$1,100,556.15
North Metropolitan TAFE	\$6,155,360.29
North Regional TAFE	\$3,337,823.73
South Metropolitan TAFE	\$5,473,922.52
South Regional TAFE	\$1,244,976.32
Total	\$17,312,639.01

10 OCT 2017

Department of Training and Workforce Development

Hon Donna Faragher MLC asked:

- 4) Please list all current national partnership agreements and/or Commonwealth grants that the Department of Training and Workforce Development receives funding and include:
 - i) The National Agreement for Skills and Workforce Development
 - ii) The Indian Ocean Territories Service Delivery Arrangement
 - iii) The Accredited Courses Grant Agreement
 - a) the date the agreement commenced and its expected expiry date?

Answer:

 The National Agreement for Skills and Workforce Development Commencement: 2008-09 Expiry: Ongoing

 ii) The Indian Ocean Territories Service Delivery Arrangement Commencement: July 2017
 Expiry: Multi-Year Arrangement – June 2021

iii) The Accredited Courses Grant Agreement Commencement: June 2017 Expiry: June 2018

b) the total amount received in 2016-17 and the expected funding in 2017-18, 2018-19, 2019-20 and 2020-21?

Answer:

i) The National Agreement for Skills and Workforce Development

2016-17 (\$)	2017-18 (\$)	2018-19 (\$)	2019-20 (\$)	2020-21 (\$)
159,578,060	161,800,000	163,900,000	166,300,000	168,500,000

ii) The Indian Ocean Territories Service Delivery Arrangement

2016-	17 (\$)	2017-18 (\$)	2018-19 (\$)	2019-20 (\$)	2020-21 (\$)
14	0,300	167,700	90,000	92,000	94,000

iii) The Accredited Courses Grant Agreement

2016-17 (\$)	2017-18 (\$)	2018-19 (\$)	2019-20 (\$)	2020-21 (\$)
275,000 (including GST)	Nil	Nil	Nil	Nil

Expected funding: Not applicable - Finite Grant Agreement

Department of Training and Workforce Development

Hon Donna Faragher MLC asked:

5) What is the expected total expenditure by the Department of Training and Workforce Development on government advertising in 2017-18?

Answer: \$288 250

5 OCT 2017