

RAIL LINES — DISRUPTIONS — JOONDALUP

3358. Hon Ken Travers to the Parliamentary Secretary representing the Minister for Transport:

I refer to the train disruptions to the Joondalup rail (Clarkson to Butler) line on 5 September 2015, and I ask:

- (a) what time did the delays first occur;
- (b) what were the technical issues responsible;
- (c) when did services resume; and
- (d) how many services were affected?

Hon Jim Chown replied:

- (a) 7:30am
- (b) A defective fastener.
- (c) Services ran between Perth and Clarkson without interruption but were stopped between Clarkson and Butler until approximately 9:37am.
- (d) Eight services were terminated at Clarkson station.